RECEIVED

UNITED STATES DEPARTM BUREAU O

ia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMNM101108

ENT OF THE INTERIOR	UCD.Arres	:1:
F LAND MANAGEMENT	OCT 1 2 2018 rtes	••

SUNDRY NOTICES AND REPORTS ON WELLS not use this form for proposals to drill or to re-enter an

abandoned well. Use form 3160-3 (APD) for solls projection in the same of the			6. If Indian, Allottee	6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2			7. If Unit or CA/Agre	7. If Unit or CA/Agreement, Name and/or No.		
Type of Well Gas Well				8. Well Name and No. WEST BRUSHY 5 FEDERAL SWD 5		
2. Name of Operator Contact: BOBBIE GOODLOE COG OPERATING LLC E-Mail: bgoodloe@concho.com			9. API Well No. 30-015-31869-	9. API Well No. 30-015-31869-00-S1		
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701 Be-iviali. Byoodide@colino.com 3b. Phone No. (include area code) Ph: 575-748-6952			10. Field and Pool or BRUSHY DRA	10. Field and Pool or Exploratory Area BRUSHY DRAW-WOLFCAMP		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, State		
Sec 5 T26S R29E SESE 800FSL 850FEL			EDDY COUNT	EDDY COUNTY, NM		
12. CHECK THE A	PROPRIATE BOX(ES) TO	INDICATE NATURE OF	F NOTICE, REPORT, OR OT	HER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION					
□ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	■ Water Shut-Off		
☐ Notice of Intent	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	■ Well Integrity		
Subsequent Report Subsequent Re	□ Casing Repair	■ New Construction	□ Recomplete	Other		
☐ Final Abandonment Notice	□ Change Plans	Plug and Abandon	□ Temporarily Abandon			
	□ Convert to Injection	□ Plug Back	■ Water Disposal			
08/31/18 Moved rig to location. 09/04/18 Rigged up plugging equipment. Dug out cellar. 5 1/2" had water flow. NU BOP. Set 5 1/2" CIBP @ 4250'. Circulated hole w/ MLF. Pressure tested csg. held 500. psi, water flow stopped. Spotted 25 sx class C cmt @ 4250-4000'. WOC 09/05/18 Tagged plug @ 3975'. Spotted 25 sx class C cmt @ 2900-2650'. WOC. Tagged plug @ 2654'. Perfd csg. @ 620'. Sqz'd 80 sx. class C cmt @ 620-300'. WOC. Tagged plug @ 300'. ND BOP. Spotted 15 sx class C cmt @ 125' & circulated to surface. 09/06/18 Verified cmt to surface. Rigged down & moved off. 09/22/18 Moved in backhoe and welder. Dug out cellar. Cut off well head. Verified cement to surface. Welded on "Above Ground Dry Hole Marker". Backfilled cellar. Cut off deadmen. Cleaned location, moved off. Accepted for record - NMOCD RECLAMATION PROCEDURE ATTACHED ATTACHED ATTACHED ATTACHED ATTACHED ATTACHED ACCEPTED TO THE COLUMN ATTACHED ACCEPTED TO THE COLUMN ATTACHED ATTACHED RECLAMATION PROCEDURE ATTACHED						
	Electronic Submission #4369	RATING LLC, sent to the Ca by DEBORAH MCKINNEY	arisbad			
Nume(17 mea/19peu) DOBIE C	JOODLOL	THE REGUL	ATOM ANALIST			
Signature (Electronic S	•	Date 09/25/2	PENTEN END DECA			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved By		Title	SEP 2 6 2018	Date		
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to condu	uitable title to those rights in the sub act operations thereon.	ject lease Office	DMCKINNEY LIET BUREAU OF LAND MANAGEMEN			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crim statements or representations as to a	e for any person knowingly and ny matter within its jurisdiction.	will CARLSBAD to 15 LD 10 FF 16 Et o	or agency of the United		



BUREAU OF LAND MANAGEMENT

Carlsbad Field Office
620 E. Greene St.

620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Henryetta Price Environmental Protection Specialist 575-234-5951

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612