Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

RECEIVED **CCD** Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMLC061705B

SUNDRY NOTICES AND REPORTS ON WELL 80 V 2 8 2018 Do not use this form for proposals to drill or to re-enter an

DO NOT USE IN							
abandoned well. Use form 3160-3 (APD) for such expnessels. USE IN THE PROPERTY OF THE PROPERT				6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No. 891000303E			
1. Type of Well S Oil Well □ Gas Well □ Other				8. Well Name and No. POKER LAKE UNIT 78			
2. Name of Operator Contact: TRACIE J CHERRY				9. API Well No.			
BOPCO LP E-Mail: tracie_cherry@xtoenergy.com				30-015-27536-00-S1			
3a. Address 6401 HOLIDAY HILL RD BLDG 5 SUITE 200 MIDLAND, TX 79707 3b. Phone No. (include area Ph: 432-221-7379				10. Field and Pool or Exploratory Area POKER LAKE-DELAWARE			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, State			
Sec 25 T24S R30E NENE 660FNL 660FEL				EDDY COUNTY, NM			
12. CHECK THE AI	PPROPRIATE BOX(ES) TO IN	DICATE NATURE OF	F NOTICE, I	REPORT, OR OTH	ER DATA	A.	
TYPE OF SUBMISSION	ACTION						
☐ Notice of Intent	☐ Acidize	☐ Deepen	eepen Production (Start/Re		■ Water Shut-Off		
_	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamat	ion	☐ Well I	■ Well Integrity	
Subsequent Report	□ Casing Repair	■ New Construction	☐ Recomple	te Other			
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	☐ Tempora	arily Abandon			
	Convert to Injection	Plug Back	■ Water Di	sposal			
testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. BOPCO, LP respectfully submits this sundry notice to report plugging and abandonment of the referenced well. 09/19/18 - 09/20 MIRU. POOH w/pump and rods. ND wellhead and install BOP. FT/PT 1000/300 psi (good). POOH w/tbg. 09/23/18 - 09/24/18 Tag PBTD @ 7989'. Spot salt gelled mud 7989' - 6500'. RIH w/5-1/2" CIBP to 6540', set, Tag CIBP @ 6540'. Circulate 150 bbls salt gelled mud, test csg to 500 psi (good). Spot 25 sx C cmt 6540'-6287'. WOC 4 hrs. Tag @ 6272'. RIH w/pkr to 3593'. Perf sqz holes @ 4260'. Establish injection GC / 12 - 3 - 18 Accepted for record - NMOCD							
14. I hereby certify that the foregoing is Comm Name (Printed/Typed) TRACIE J	Electronic Submission #444893 For BOPCO nitted to AFMSS for processing by	LP, sent to the Carlsbac DEBORAH MCKINNEY	j	(18PP1162SE)			
					2 2 5 6 6		
Signature (Electronic S	Date 11/21/20	018 AL	CEPTED FO	K KEC()RD		
	THIS SPACE FOR FEI	DERAL OR STATE (OFFICE US				
Approved By		Title		NOV 26	2018 Date		
Conditions of approval, if any, are attached			Millenney	LIE			
ertify that the applicant holds legal or equivalent would entitle the applicant to condu	lease Office		BUREAU OF LAND W CARLSBAD FIEL	D OFFICE		•	
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a crime for tatements or representations as to any m	r any person knowingly and vatter within its jurisdiction.	willfully to mak	e to any department or	agency of the	United	

Additional data for EC transaction #444893 that would not fit on the form

32. Additional remarks, continued

09/25/18
Tag TOC @ 3782'. Set pkr @ 441', perf @ 1000'. EIR, sqz 100 sxs C 1000' - 655'. WOC 4 hrs. Tag TOC @ 630'. Perf sqz holes 60', sqz 25 sx C cmt to surface

09/26/18 Verify cmt to surf

11/01/18

Cut off wellhead. Install marker. Well P&A'd



BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonnent, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Henryetta Price Environmental Protection Specialist 575-234-5951

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612