Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR

RECEIVED OCD Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

BUREAU OF LAND MANAGEMENT JAN 1 7 2019 SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such DESTRIBUTION ARTESIA O.C.D.				5. Lease Serial No. NMNM88139 6. If Indian, Allottee or Tribe Name	
1. Type of Well				8. Well Name and No. WOOD DRAW 35 FEDERAL 3	
2. Name of Operator Contact: DAVID STEWART				9. API Well No.	
OXY USÁ INC	E-Mail: david_stewart@oxy.com			30-015-35568	
3a. Address P.O. BOX 50250 MIDLAND, TX 79710	3b. Phone No. (include area code) Ph: 432-685-5717			10. Field and Pool or Exploratory Area CORRAL CANYON DELAWARE, NW	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			} !	11. County or Parish, State	
Sec 2 T24S R29E NENW 150FNL 2310FWL 32.165905 N Lat, 103.956261 W Lon				EDDY COUNTY, NM	
12. CHECK THE AF	PPROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, R	EPORT, OR OTH	ER DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
C Notice of Intent	☐ Acidize	☐ Deepen	☐ Productio	n (Start/Resume)	☐ Water Shut-Off
□ Notice of Intent	☐ Alter Casing	Hydraulic Fracturing	☐ Reclamation		☐ Well Integrity
Subsequent Report	☐ Casing Repair	□ New Construction	Recomple		Other
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	☑ Plug and Abandon ☐ Plug Back	☐ Temporar		
If the proposal is to deepen direction: Attach the Bond under which the wor following completion of the involved testing has been completed. Final Al determined that the site is ready for f 11/27/18 - MIRU PU 11/28/18 - POOH & LD rods & 11/29/18 - NDWH, NU BOP, r 11/30/18 - RIH w/ GR/junk ba 12/3/18 - RIH w/ 54jts tbg, rig 12/4/18 - Repl rigs	rk will be performed or provide the loperations. If the operation results bandonment Notices must be filed of inal inspection. A pump. rel TAC, POOH & LD tbg. sket to 5400', POOH. RIH &	Bond No. on the with BLM/BIA in a multiple completion or reconstruction of the completion of the control of the	Required subsimpletion in a neing reclamation,	RECLAMATI	60-4 must be filed once and the operator has
	Electronic Submission #449 For OXY I Committed to AFMSS for TEWART Submission)	USA INC, sent to the Carlsb processing by JAMES AMC Title SR. RE Date 01/07/2	ad os on 01/09/20 GULATORY 019	19 () ADVISOR	
Accepted for Reco	C THIS SPACE FOR	FEDERAL OR STATE	OFFICE US)	1010
_Approved By	nor a: am	Title S	4T		Date
Conditions of approval, if any, are attached certify that the applicant holds legal or eqwhich would entitle the applicant to conditions.	juitable title to those rights in the su	t warrant or bject lease Office	shad		

Additional data for EC transaction #449527 that would not fit on the form

32. Additional remarks, continued

12/5/18 - RIH w/ tbg & tag CIBP @ 5397', circ hole w/ 10# MLF, pressure test csg to 600#, held OK. M&P 25sx CL Cmt @ 5397' to calc TOC 5144'. PUH to 3894', M&P 25sx Cl C cmt w/ 3% CaCl2, PUH, WOC. RIH & tag cmt @ 3617', PUH to 3294', M&P 40sx Cl C cmt, PUH, WOC.

12/6/18 - RIH & tag cmt @ 2894', PUH to 2505', M&P 25sx CL C cmt w/ 3% CaCl2, BLM witnessed tag & plug, PUH, WOC. RIH & tag cmt @ 2188', PUH & perf @ 60', attempt to EIR, pressure up to 350#, no rate or loss. RIH to 925', M&P a total of 104sx Cl C cmt, circ cmt to surf, remove all surface valves and risers, fill w/ cmt, top off csg.

12/7/18 - Verifiy cmt to surface on all strings, ND BOP, RD PU.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crystal Weaver Environmental Protection Specialist 575-234-5943

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612