SUND	BUREAU OF LAND MANA		T TESS NEW NO		
Do not use	well. Use form 3160-3 (AP	drill or to re-enter an 👘 👘	AITIES NMNM45236 6. If Indian, Allotte		
SUBMIT	IN TRIPLICATE - Other ins	tructions on page 2	7. If Unit or CA/A	greement, Name and/or	
<ul> <li>I. Type of Well</li> <li>Coll Well</li> <li>Gas Well</li> <li>Other</li> </ul>				8. Well Name and No. STERLING SILVER MDP1 33-4 FD	
2. Name of Operator Contact: SARAH CHAPMAN OXY USA INCORPORATED E-Mail: SARAH_CHAPMAN@OXY.COM				30-015-45386-00-X1	
3a. Address3b. Photen5 GREENWAY PLAZA SUITE 110Ph: 713-3HOUSTON, TX 77046-0521Ph: 713-3		3b. Phode No. (include area code) Ph: 713-350 4997 SIA DIS	RVATION 10. Field and Pool INGLE WELL	or Exploratory Area .S	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		<sup>i)</sup> MAR 112	11. County or Paris	11. County or Parish, State	
Sec 33 T23S R31E NENW 69FNL 2439FWL		1000112		EDDY COUNTY, NM	
32.267994 N Lat, 103.783	401 W Lon	RECEIVE	D		
<u> </u>	E APPROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, REPORT, OR O	THER DATA	
TYPE OF SUBMISSION	· · · · · · · · · · · · · · · · · · ·	TYPE OF	TYPE OF ACTION		
Notice of Intent		Deepen	□ Production (Start/Resume)	—	
🛛 Subsequent Report	Alter Casing	Hydraulic Fracturing	Reclamation	U Well Integri	
	Casing Repair	□ New Construction	□ Recomplete	Other Drilling Operat	
☐ Final Abandonment Notic	e Change Plans Convert to Injection	Plug and Abandon Plug Back	<ul> <li>Temporarily Abandon</li> <li>Water Disposal</li> </ul>		
Attach the Bond under which th following completion of the invo	e work will be performed or provide blved operations. If the operation re al Abandonment Notices must be fil	, give subsurface locations and measure the Bond No. on file with BLM/BIA sults in a multiple completion or reco led only after all requirements, includi	Required subsequent reports must mpletion in a new interval, a Form (	t be filed within 30 days 3160-4 must be filed on	
Test 7-5/8" csg to 1500# f test to EMW=14.5ppg 135 P-110 DQX and SF TOR	or 30 minutes, good test. RIH 2#, good test. Drill 6-3/4" hol Q csg @ 20481', pump 120bl yield. Full returns throughout	P test, test 5000# high 250# low I & drill new formation to 4409' e to 20525'M/10271'V. RIH & s bl tuned spacer then cmt w/ 84 t job, est TOC @ 9160'. 2/23/1	, perform FIT set 5-1/2" 20# 5sxs (217bbl) class C		
	• •				
14. I hereby certify that the foregoing	Electronic Submission # For OXY USA	456985 verified by the BLM Well A INCORPORATED, sent to the essing by PRISCILLA PEREZ or	Carlsbad		
	) STEWART		ATORY ADVISOR	· · · · · · · · · · · · · · · · · · ·	
Signature (Electro	nic Submission)	Date 03/06/20	)19		
	THIS SPACE FO	OR FEDERAL OR STATE (	in dia anna anna anna anna anna anna ann	<u> </u>	
Approved By			oted for Record	MAR Date 6 2	
Conditions of approval, if any, are att certify that the applicant holds legal o which would entitle the applicant to c	r equitable title to those rights in the		nathon Shepard risbad Field Office		
Title 18 U.S.C. Section 1001 and Titl	e 43 U.S.C. Section 1212, make it a	crime for any person knowingly and s to any matter within its jurisdiction.	willfully to make to any department	t or agency of the Unite	