Submit One Copy To Appropriate District	State of New		Form C-103
District I REGENSE	Energy, Minerals and M	Natural Resources	Revised November 3, 2011
625 N. French Dr., Hobbs, NM 88240 District II	40		WELL API NO. 30-015-20715
D <u>istrict II</u> 11 S. First St., Artesia, NM 88210 AUG 9 2 District III	OUL CONSERVATI	ON DIVISION	5. Indicate Type of Lease
000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. 1	Francis Dr.	STATE STATE
District IV	SAU-Santa Fe, NN	4 87505	6. State Oil & Gas Lease No.
District III POC 000 Rio Brazos Rd., Aztec, NM 87410 District IV 220 S. St. Francis Dr., Sant SKARCTIL ASTE 7505			E-4200
SUNDRY NOTICES A	ND REPORTS ON WE	LLS	7. Lease Name or Unit Agreement Name
DO NOT USE THIS FORM FOR PROPOSALS TO DIFFERENT RESERVOIR. USE "APPLICATION			Conoco State
PROPOSALS.)		i)i ok seen	8. Well Number
	Vell Other		
2. Name of Operator COG Operating LLC			9. OGRID Number 229137
Address of Operator			10. Pool name or Wildcat
208 W Main Artesia NM 88210			Grayburg Upper-Penn
. Well Location			······································
Unit Letter K 1980 feet from the	South line and 1650 feet	from the West line	
Section <u>15</u> Township <u>17S</u> F	Range 29E NMPM Edd	ly County	
11. 1	Elevation (Show whether	DR, RKB, RT, GR, etc	.)
	3562' GR		
2. Check Appropriate Box to India	cate Nature of Notice	e, Report or Other I	Data
NOTICE OF INTEN	TION TO:	SUF	BSEQUENT REPORT OF:
	G AND ABANDON	REMEDIAL WOR	
	NGE PLANS		
		COMMENCE DI	
PULL OR ALTER CASING 🛛 MUL		CASING/CEMEN	
•		CASING/CEMEN	
THER:		CASING/CEMEN	NT JOB
OTHER: All pits have been remediated in comp	liance with OCD rules a	CASING/CEMEN	T JOB
DTHER: All pits have been remediated in comp	liance with OCD rules a	CASING/CEMEN	Image: NT JOB Image: Description after P&A ready for OCD inspection after P&A Image: Description after P&A erator's pit permit and closure plan. Image: Description after P&A in properly abandoned. Image: Description after P&A
OTHER: All pits have been remediated in comp Rat hole and cellar have been filled ar A steel marker at least 4" in diameter	liance with OCD rules a ad leveled. Cathodic pro and at least 4' above grou	CASING/CEMEN Location is nd the terms of the Op- tection holes have been and level has been set in	Image: NT JOB Image: Construction after P&A ready for OCD inspection after P&A erator's pit permit and closure plan. properly abandoned. in concrete. It shows the
OTHER: All pits have been remediated in comp Rat hole and cellar have been filled ar A steel marker at least 4" in diameter at OPERATOR NAME, LEASE N	liance with OCD rules a d leveled. Cathodic pro and at least 4' above grou AME, WELL NUMBE	CASING/CEMEN Location is nd the terms of the Op- tection holes have beer and level has been set is R , API NUMBER, O	IT JOB Image: Constraint of the system ready for OCD inspection after P&A erator's pit permit and closure plan. i properly abandoned. in concrete. It shows the UARTER/QUARTER LOCATION OR
OTHER: All pits have been remediated in comp Rat hole and cellar have been filled ar A steel marker at least 4" in diameter	liance with OCD rules a d leveled. Cathodic pro and at least 4' above grou AME, WELL NUMBE WNSHIP, AND RANC	CASING/CEMEN Location is nd the terms of the Op- tection holes have beer and level has been set in R, API NUMBER, Q E. All INFORMATI	IT JOB Image: Constraint of the system ready for OCD inspection after P&A erator's pit permit and closure plan. i properly abandoned. in concrete. It shows the UARTER/QUARTER LOCATION OR
OTHER: All pits have been remediated in comp Rat hole and cellar have been filled ar A steel marker at least 4" in diameter a OPERATOR NAME, LEASE N UNIT LETTER, SECTION, TO PERMANENTLY STAMPED (liance with OCD rules a d leveled. Cathodic pro and at least 4' above grou AME, WELL NUMBE WNSHIP, AND RANC DN THE MARKER'S S	CASING/CEMEN	Image: NT JOB Image: NT JOB Image: Image: Image: NT JOB Image: Image
DTHER: All pits have been remediated in comp Rat hole and cellar have been filled ar A steel marker at least 4" in diameter at OPERATOR NAME, LEASE N UNIT LETTER, SECTION, TO PERMANENTLY STAMPED (The location has been leveled as nearl	liance with OCD rules a d leveled. Cathodic pro and at least 4' above grou AME, WELL NUMBE WNSHIP, AND RANC DN THE MARKER'S S	CASING/CEMEN	IT JOB Image: Constraint of the system ready for OCD inspection after P&A erator's pit permit and closure plan. i properly abandoned. in concrete. It shows the UARTER/QUARTER LOCATION OR
OTHER: All pits have been remediated in comp Rat hole and cellar have been filled ar A steel marker at least 4" in diameter at OPERATOR NAME, LEASE N UNIT LETTER, SECTION, TO PERMANENTLY STAMPED (The location has been leveled as nearl her production equipment.	liance with OCD rules a ad leveled. Cathodic pro and at least 4' above grou AME, WELL NUMBE WNSHIP, AND RANC ON THE MARKER'S S	CASING/CEMEN	Image: NT JOB Image: Construction after P&A ready for OCD inspection after P&A erator's pit permit and closure plan. a properly abandoned. in concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR s been cleared of all junk, trash, flow lines and
OTHER: All pits have been remediated in comp Rat hole and cellar have been filled ar A steel marker at least 4" in diameter OPERATOR NAME, LEASE N UNIT LETTER, SECTION, TO PERMANENTLY STAMPED (The location has been leveled as nearl her production equipment. Anchors, dead men, tie downs and rise	Diance with OCD rules a ad leveled. Cathodic pro and at least 4' above grou AME, WELL NUMBE WNSHIP, AND RANC ON THE MARKER'S S by as possible to original ers have been cut off at le	CASING/CEMEN	Image: NT JOB Image: Construction after P&A erator's pit permit and closure plan. Properly abandoned. in concrete. It shows the Image: Construction or concrete. UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR Image: Construction of construction of construction of construction of construction of construction. s been cleared of all junk, trash, flow lines and pund level. Image: Construction of construction of construction.
OTHER: All pits have been remediated in comp Rat hole and cellar have been filled ar A steel marker at least 4" in diameter OPERATOR NAME, LEASE N UNIT LETTER, SECTION, TO PERMANENTLY STAMPED (The location has been leveled as nearl her production equipment. Anchors, dead men, tie downs and rise If this is a one-well lease or last remai CD rules and the terms of the Operator's	Diance with OCD rules a ad leveled. Cathodic pro and at least 4' above grou AME, WELL NUMBE WNSHIP, AND RANC ON THE MARKER'S S by as possible to original ers have been cut off at lease in the bar	CASING/CEMEN Location is in and the terms of the Op- tection holes have been and level has been set in R , API NUMBER, O E . All INFORMATION URFACE. ground contour and has east two feet below gro intery and pit location(st	Image: NT JOB Image: Construction after P&A ready for OCD inspection after P&A erator's pit permit and closure plan. a properly abandoned. in concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR s been cleared of all junk, trash, flow lines and
OTHER: All pits have been remediated in comp Rat hole and cellar have been filled ar A steel marker at least 4" in diameter at OPERATOR NAME, LEASE N UNIT LETTER, SECTION, TO PERMANENTLY STAMPED (The location has been leveled as nearl her production equipment. Anchors, dead men, tie downs and rise If this is a one-well lease or last remai CD rules and the terms of the Operator's om lease and well location.	liance with OCD rules a deleveled. Cathodic pro and at least 4' above grou AME, WELL NUMBE WNSHIP, AND RANC DN THE MARKER'S S y as possible to original ers have been cut off at leasing well on lease, the ba pit permit and closure pl	CASING/CEMEN Location is in and the terms of the Op- tection holes have been and level has been set in R , API NUMBER, Q E . All INFORMATIN URFACE. ground contour and has east two feet below gro attery and pit location(stan. All flow lines, pro-	Image: NT JOB Image: Construction after P&A erator's pit permit and closure plan. properly abandoned. in concrete. It shows the Image: Construction of the constru
DTHER: All pits have been remediated in comp Rat hole and cellar have been filled ar A steel marker at least 4" in diameter at OPERATOR NAME, LEASE N UNIT LETTER, SECTION, TO PERMANENTLY STAMPED (The location has been leveled as nearl her production equipment. Anchors, dead men, tie downs and rise If this is a one-well lease or last remai CD rules and the terms of the Operator's om lease and well location. All metal bolts and other materials hav	liance with OCD rules a deleveled. Cathodic pro and at least 4' above grou AME, WELL NUMBE WNSHIP, AND RANC DN THE MARKER'S S y as possible to original ers have been cut off at leasing well on lease, the ba pit permit and closure pl	CASING/CEMEN Location is in and the terms of the Op- tection holes have been and level has been set in R , API NUMBER, Q E . All INFORMATIN URFACE. ground contour and has east two feet below gro attery and pit location(stan. All flow lines, pro-	Image: NT JOB Image: Construction after P&A erator's pit permit and closure plan. Properly abandoned. in concrete. It shows the Image: Construction or concrete. UARTER/QUARTER LOCATION OR Image: Construction of construction of construction of construction of construction of construction. Is been cleared of all junk, trash, flow lines and sund level. Image: Construction of construction of construction of construction. Is been cleared of all junk, trash, flow lines and sund level. Image: Construction of construction.
OTHER: All pits have been remediated in comp Rat hole and cellar have been filled ar A steel marker at least 4" in diameter at OPERATOR NAME, LEASE N UNIT LETTER, SECTION, TO PERMANENTLY STAMPED (The location has been leveled as nearl her production equipment. Anchors, dead men, tie downs and rise If this is a one-well lease or last remai CD rules and the terms of the Operator's om lease and well location.	liance with OCD rules a ad leveled. Cathodic pro and at least 4' above grou AME, WELL NUMBE WNSHIP, AND RANC ON THE MARKER'S S y as possible to original ers have been cut off at le ning well on lease, the ba pit permit and closure pl e been removed. Portabl	CASING/CEMEN	Image: NT JOB Image: Construction after P&A erator's pit permit and closure plan. properly abandoned. in concrete. It shows the Image: Construction of the constru
OTHER: All pits have been remediated in comp Rat hole and cellar have been filled ar A steel marker at least 4" in diameter at OPERATOR NAME, LEASE N UNIT LETTER, SECTION, TO PERMANENTLY STAMPED (The location has been leveled as nearl her production equipment. Anchors, dead men, tie downs and rise If this is a one-well lease or last remai CD rules and the terms of the Operator's om lease and well location. All metal bolts and other materials hav be removed.) All other environmental concerns have Pipelines and flow lines have been aba	liance with OCD rules a ad leveled. Cathodic pro and at least 4' above grou AME, WELL NUMBE WNSHIP, AND RANCO ON THE MARKER'S S y as possible to original ers have been cut off at le ning well on lease, the ba pit permit and closure pl e been removed. Portabl e been addressed as per (CASING/CEMEN	Image: NT JOB Image: Construction after P&A erator's pit permit and closure plan. properly abandoned. in concrete. It shows the Image: Construction of the constru
OTHER: All pits have been remediated in comp Rat hole and cellar have been filled ar A steel marker at least 4" in diameter at OPERATOR NAME, LEASE N UNIT LETTER, SECTION, TO PERMANENTLY STAMPED (The location has been leveled as nearl her production equipment. Anchors, dead men, tie downs and rise If this is a one-well lease or last remai CD rules and the terms of the Operator's om lease and well location. All metal bolts and other materials hav be removed.) All other environmental concerns have Pipelines and flow lines have been aba trieved flow lines and pipelines.	liance with OCD rules a ad leveled. Cathodic pro- and at least 4' above grou AME, WELL NUMBE WNSHIP, AND RANCE ON THE MARKER'S S y as possible to original a ers have been cut off at lease ning well on lease, the ba pit permit and closure pl e been removed. Portable e been addressed as per Condoned in accordance w	CASING/CEMEN	NT JOB Image: Construction after P&A erator's pit permit and closure plan. properly abandoned. in concrete. It shows the Image: Construction of the construction o
OTHER: All pits have been remediated in comp Rat hole and cellar have been filled ar A steel marker at least 4" in diameter at OPERATOR NAME, LEASE N UNIT LETTER, SECTION, TO PERMANENTLY STAMPED (The location has been leveled as nearl her production equipment. Anchors, dead men, tie downs and rise If this is a one-well lease or last remai CD rules and the terms of the Operator's om lease and well location. All metal bolts and other materials hav be removed.) All other environmental concerns have Pipelines and flow lines have been aba trieved flow lines and pipelines. If this is a one-well lease or last remai	Diance with OCD rules a ad leveled. Cathodic pro- and at least 4' above grou AME, WELL NUMBE WNSHIP, AND RANC ON THE MARKER'S S y as possible to original ers have been cut off at lease ning well on lease, the ba pit permit and closure pl e been removed. Portable e been addressed as per Condoned in accordance we ning well on lease: all elease	CASING/CEMEN	Image: Section after P&A erady for OCD inspection after P&A erator's pit permit and closure plan. a properly abandoned. in concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR s been cleared of all junk, trash, flow lines and und level. s) have been remediated in compliance with duction equipment and junk have been remover oved. (Poured onsite concrete bases do not hav
OTHER: All pits have been remediated in comp Rat hole and cellar have been filled ar A steel marker at least 4" in diameter at OPERATOR NAME, LEASE N UNIT LETTER, SECTION, TO PERMANENTLY STAMPED (The location has been leveled as nearl her production equipment. Anchors, dead men, tie downs and rise If this is a one-well lease or last remai CD rules and the terms of the Operator's om lease and well location. All metal bolts and other materials hav be removed.) All other environmental concerns have Pipelines and flow lines have been aba trieved flow lines and pipelines.	Diance with OCD rules a ad leveled. Cathodic pro- and at least 4' above grou AME, WELL NUMBE WNSHIP, AND RANC ON THE MARKER'S S y as possible to original ers have been cut off at lease ning well on lease, the ba pit permit and closure pl e been removed. Portable e been addressed as per Condoned in accordance we ning well on lease: all elease	CASING/CEMEN	NT JOB Image: Construction after P&A erator's pit permit and closure plan. properly abandoned. in concrete. It shows the Image: Construction of the construction o
OTHER: All pits have been remediated in comp Rat hole and cellar have been filled ar A steel marker at least 4" in diameter at OPERATOR NAME, LEASE N UNIT LETTER, SECTION, TO PERMANENTLY STAMPED (The location has been leveled as nearl her production equipment. Anchors, dead men, tie downs and rise If this is a one-well lease or last remai CD rules and the terms of the Operator's om lease and well location. All metal bolts and other materials hav be removed.) All other environmental concerns have Pipelines and flow lines have been aba trieved flow lines and pipelines. If this is a one-well lease or last remai	Diance with OCD rules a ad leveled. Cathodic pro- and at least 4' above grou AME, WELL NUMBE WNSHIP, AND RANC ON THE MARKER'S S y as possible to original a ers have been cut off at lease ning well on lease, the bas pit permit and closure pl e been removed. Portable e been addressed as per (andoned in accordance we ning well on lease: all elease rastructure.	CASING/CEMEN	Image: Second state of all junk, trash, flow lines and level. Solution of the state of all junk have been removed on the state of all junk have been removed from non-
OTHER: All pits have been remediated in comp Rat hole and cellar have been filled ar A steel marker at least 4" in diameter at OPERATOR NAME, LEASE N UNIT LETTER, SECTION, TO PERMANENTLY STAMPED (The location has been leveled as nearl her production equipment. Anchors, dead men, tie downs and rise If this is a one-well lease or last remai CD rules and the terms of the Operator's om lease and well location. All metal bolts and other materials hav be removed.) All other environmental concerns have Pipelines and flow lines have been aba trieved flow lines and pipelines. If this is a one-well lease or last remain	Diance with OCD rules a ad leveled. Cathodic pro- and at least 4' above grou AME, WELL NUMBE WNSHIP, AND RANC ON THE MARKER'S S y as possible to original a ers have been cut off at lease ning well on lease, the bas pit permit and closure pl e been removed. Portable e been addressed as per (andoned in accordance we ning well on lease: all elease rastructure.	CASING/CEMEN	Image: Second state of all junk, trash, flow lines and level. Solution of the state of all junk have been removed on the state of all junk have been removed from non-
DTHER: All pits have been remediated in comp Rat hole and cellar have been filled ar A steel marker at least 4" in diameter at OPERATOR NAME, LEASE N UNIT LETTER, SECTION, TO PERMANENTLY STAMPED (The location has been leveled as nearl her production equipment. Anchors, dead men, tie downs and rise If this is a one-well lease or last remai CD rules and the terms of the Operator's on lease and well location. All metal bolts and other materials hav be removed.) All other environmental concerns hav Pipelines and flow lines have been aba trieved flow lines and pipelines. If this is a one-well lease or last remai cation, except for utility's distribution inf hen all work has been sompleted, return	liance with OCD rules a ad leveled. Cathodic pro and at least 4' above grou AME, WELL NUMBE WNSHIP, AND RANC ON THE MARKER'S S y as possible to original ers have been cut off at lease ning well on lease, the ba pit permit and closure pl e been removed. Portable been addressed as per C undoned in accordance we ning well on lease: all elease rastructure.	CASING/CEMEN	NT JOB Image: Construction of the second
OTHER: All pits have been remediated in comp Rat hole and cellar have been filled ar A steel marker at least 4" in diameter at OPERATOR NAME, LEASE N UNIT LETTER, SECTION, TO PERMANENTLY STAMPED (The location has been leveled as nearl her production equipment. Anchors, dead men, tie downs and rise If this is a one-well lease or last remai CD rules and the terms of the Operator's om lease and well location. All metal bolts and other materials hav be removed.) All other environmental concerns have Pipelines and flow lines have been aba trieved flow lines and pipelines. If this is a one-well lease or last remain	liance with OCD rules a ad leveled. Cathodic pro and at least 4' above grou AME, WELL NUMBE WNSHIP, AND RANC ON THE MARKER'S S y as possible to original ers have been cut off at lease ning well on lease, the ba pit permit and closure pl e been removed. Portable been addressed as per C undoned in accordance we ning well on lease: all elease rastructure.	CASING/CEMEN	NT JOB Image: Construction of the second
DTHER: All pits have been remediated in comp Rat hole and cellar have been filled ar A steel marker at least 4" in diameter at OPERATOR NAME, LEASE N UNIT LETTER, SECTION, TO PERMANENTLY STAMPED (The location has been leveled as nearly her production equipment. Anchors, dead men, tie downs and rise If this is a one-well lease or last remai CD rules and the terms of the Operator's om lease and well location. All metal bolts and other materials hav be removed.) All other environmental concerns have Pipelines and flow lines have been aba trieved flow lines and pipelines. If this is a one-well lease or last remain cation, except for utility's distribution information hen all work has been sompleted, return GNATURE YPE OR PRINT HAME Delilah Flores	Iliance with OCD rules a ad leveled. Cathodic pro- and at least 4' above ground AME, WELL NUMBE WNSHIP, AND RANCE ON THE MARKER'S S y as possible to original for the sear cut off at lease pit permit and closure place the been removed. Portable the been addressed as per Condoned in accordance we ning well on lease: all elease rastructure. this form to the appropri- TITLI	CASING/CEMEN	NT JOB Image: Construction of the second
OTHER: All pits have been remediated in comp Rat hole and cellar have been filled ar A steel marker at least 4" in diameter at OPERATOR NAME, LEASE N UNIT LETTER, SECTION, TO PERMANENTLY STAMPED (The location has been leveled as nearly her production equipment. Anchors, dead men, tie downs and rise If this is a one-well lease or last remai CD rules and the terms of the Operator's om lease and well location. All metal bolts and other materials hav be removed.) All other environmental concerns have pipelines and flow lines have been abat trieved flow lines and pipelines. If this is a one-well lease or last remai cation, except for utility's distribution inf hen all work has been sompleted, return GNATURE	Iliance with OCD rules a ad leveled. Cathodic pro- and at least 4' above ground AME, WELL NUMBE WNSHIP, AND RANCE ON THE MARKER'S S y as possible to original for the sear cut off at lease pit permit and closure place the been removed. Portable the been addressed as per Condoned in accordance we ning well on lease: all elease rastructure. this form to the appropri- TITLI	CASING/CEMEN	NT JOB Image: Construction of the second
DTHER: All pits have been remediated in comp Rat hole and cellar have been filled ar A steel marker at least 4" in diameter at OPERATOR NAME, LEASE N UNIT LETTER, SECTION, TO PERMANENTLY STAMPED (The location has been leveled as nearly her production equipment. Anchors, dead men, tie downs and rise If this is a one-well lease or last remai CD rules and the terms of the Operator's om lease and well location. All metal bolts and other materials hav be removed.) All other environmental concerns have Pipelines and flow lines have been aba trieved flow lines and pipelines. If this is a one-well lease or last remain cation, except for utility's distribution information hen all work has been sompleted, return GNATURE YPE OR PRINT HAME Delilah Flores	I ance with OCD rules a ad leveled. Cathodic pro- and at least 4' above ground AME, WELL NUMBE WNSHIP, AND RANCE ON THE MARKER'S S y as possible to original and ers have been cut off at lean ing well on lease, the back pit permit and closure place the been removed. Portable the been addressed as per Condoned in accordance we ning well on lease: all elean rastructure. this form to the appropri- TITLL E-MAIL:	CASING/CEMEN	NT JOB Image: Construction of the property and closure plan. a properly abandoned. an concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR Sebeen cleared of all junk, trash, flow lines and bund level. s) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not hav C. All fluids have been removed from non- nd lines have been removed from lease and wel hedule an inspection. an DATE 8/8/2019