UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD-ARTES

FORM APPROVED

LC 065478 B

	Expires	: Marci	31,200
anna Cari	I Ma		

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side				7. If Unit or CA/Agreement, Name and/or No.			
Type of Well Soil Well Name of Operator	Gas Well Other	JL	IN 0 6 2006	8. Well Nan MA	ne and No. LCO A #2	***************************************	
	X ENERGY, INC.	. WULLINGTER		9. API We	ll No.		
3a. Address	1	3b. Phone No. (include	′ 1	30	-015-87165		
	D Box 3418, Midland, TX 79702 (432)686-0847		10. Field and Pool, or Exploratory Area				
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 143.6 FNL 1257.6FEL				d Lk, Qn, Brl	<u>b.</u> SA		
NE/4 NE/4 of Section 3, T 18 S, R 27 E, NMPM,			11. County or Parish, State				
Eddy County, New Mexico			Eddy, N.M.				
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTICE, RI	PORT, OR	OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Star Reclamation Recomplete Temporarily Abs	ŕ	□ Water Shut-Off □ Well Integrity ☑ Other <u>see remain</u>	arks.	
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond winder which the work will be preferred or provide the Bond No. on file with DI M/DIA. Required cultocapter reports shall be filed within 30 days.							

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Remarks:

Well is currently Shut-in.

Amtex is planning to commence operations on or about 9/1/06 to do one of the following:

- Return the well to production, or
- Permanently plug and abandon well, if returning the well to production is not feasible.

Please call 432-686-0847 if you have any questions.

	,						
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	!						
William J. Savage	Title	President					
Signature William J. Savage	Date	5/26/06					
ACCEPTED FORMIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by CHAN 2 2005		Title	Date				
Conditions of approval of this notice does not warrancertify that the applicant holds legal or equitable title to those rights in the subject less which would entitle the applicant to conduct operations thereon.	ase	Office					
Title 18 U.S.C. Section 700 and Title 43 U.S.C. Section 1212 make it a crime factory person knowingly and willfully to make to any department or agency of the United States any false, licitiful of fraudule in statements or representations as to associate within its jurisdiction.							
(Instructions on page 2)		Accepted For Record					

Subject To Returning Well To Continuous Production And Keeping Well On Continuous Production Or Plugging Well With An Approved Plugging Program!