

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO.30-015-05593

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.  
Lco59569B

7. Lease Name or Unit Agreement Name

North shugart Queen unit

8. Well Number 5

9. OGRID Number 188152

10. Pool name or Wildcat Shugart Queen  
Un.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

RECEIVED

2. Name of Operator

Tom R. Cone

JUN 05 2006

3. Address of Operator

1304 W. Broadway Place Hobbs N.M. 88240

OCD-ARTESIA

4. Well Location

Unit Letter F feet from the 2310 FNL line and 1650 feet from the FWL      line

Section 21

Township 18S

Range 31E

NMPM Eddy

County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type      Depth to Groundwater      Distance from nearest fresh water well      Distance from nearest surface water     

Pit Liner Thickness:      mil Below-Grade Tank: Volume      bbls; Construction Material     

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☐

CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

May 26 2006 we plain to move rig in and pull tubing and run sand line drill in, and drill out brig plug . Then run sand pump in well clean out bottom of well. Run tubing in and begin swabbing to test well. Then if well is cost efficient we plain to run pump and rods in well and move pumping unit in .

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Rick L Houston TITLE Fieldsuperintendent DATE May 25 2006

Type or print name Rick L. Houston

Telephone No.505 390 9611

E-mail address: Rhoul21198@valornet.com

**For State Use Only**

**FOR RECORDS ONLY**

JUN 05 2006

APPROVED BY:      TITLE      DATE     

Conditions of Approval (if any):