Submit 3 Copies To Appropriate District Office	State of N	ew Mexico		Form C-103
District I	Energy, Minerals ar	nd Natural Resources		May 27, 2004
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVA	ATION DIVISION	30-015-34461 5. Indicate Type of Lea	ice
District III	1220 South S	St. Francis Dr.	STATE	FEE 🗍
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe,	NM 87505	6. State Oil & Gas Lea	
1220 S. St. Francis Dr., Santa Fe, NM				
87505 SUNDRY NO	TICES AND REPORTS ON	WELLS	7. Lease Name or Unit	Agreement Name
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN	NOR PLUG BACK TO A		1.20.0011101110
DIFFERENT RESERVOIR. USE "APPLI PROPOSALS.)	CATION FOR PERMIT" (FORM C	2-101) FOR SUCH	PUMA	
1. Type of Well: Oil Well	Gas Well 🛛 Other	RECEIVED	8. Well Number	1
2. Name of Operator		•	9. OGRID Number	
	HISON OIL & GAS, INC.	MAY 3 0 2006		015363
	MIRA VISTA BLVD.	BUNDANTEO!	10. Pool name or Wild	I
	NO, TX. 75093-4698		EMPIRE MOR	ROW SOUTH
4. Well Location	((0, 0, 0, 1	NODELL	1000 6 6 4	E A COTE
Unit Letter B	: 660 feet from the		1980 feet from the	
Section 14	Township 17S	Range 28E NI ther DR, RKB, RT, GR, etc	MPM County	EDDY
	3592' GL	3609' KDB	<i>i.)</i>	
Pit or Below-grade Tank Application		3007 1232		
Pit typeDepth to Ground	waterDistance from neare	est fresh water well Dis	tance from nearest surface wate	er
Pit Liner Thickness: mil	Below-Grade Tank: Volum	e bbls; Co	astruction Material	
12 Check	Appropriate Box to Ind	icate Nature of Notice	Penart or Other Date	
12. CHECK	Appropriate Dox to file	icate mature of money	Report of Other Data	ı
NOTICE OF I	NTENTION TO:		SEQUENT REPOR	RT OF:
PERFORM REMEDIAL WORK [-	REMEDIAL WO		ERING CASING 🔲
TEMPORARILY ABANDON [CHANGE PLANS	☐ COMMENCE DE	RILLING OPNS. 🗌 🔝 P AN	IDA □
				
	MULTIPLE COMPL	CASING/CEMEN	 -	
PULL OR ALTER CASING [CASING/CEMEN		
PULL OR ALTER CASING OTHER: 13. Describe proposed or com	MULTIPLE COMPL apleted operations. (Clearly statements)	CASING/CEMENT OTHER:	NT JOB 🔀	Cluding estimated date
PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed	MULTIPLE COMPL	CASING/CEMENT OTHER:	NT JOB 🔀	Cluding estimated date
PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed or recompletion.	MULTIPLE COMPL apleted operations. (Clearly swork). SEE RULE 1103. For	CASING/CEMENT OTHER: state all pertinent details, a per Multiple Completions:	NT JOB 🔀	Cluding estimated date
PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed or recompletion. Drilled 8-1/2" hole to a depth	multiple complinations. (Clearly swork). SEE RULE 1103. For of 10285'. Ran 5-1/2" casing the complete	CASING/CEMENT OTHER: state all pertinent details, a per Multiple Completions: ng as follows:	NT JOB multiple states in the state of the	Cluding estimated date
PULL OR ALTER CASING OTHER: 13. Describe proposed or con of starting any proposed or recompletion. Drilled 8-1/2" hole to a depth	multiple complements of 10285'. Ran 5-1/2" casing Float Shoe	CASING/CEMEN OTHER: state all pertinent details, a per Multiple Completions:	nd give pertinent dates, ind Attach wellbore diagram of	Cluding estimated date
PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed or recompletion. Drilled 8-1/2" hole to a depth	multiple complinations. (Clearly swork). SEE RULE 1103. For of 10285'. Ran 5-1/2" casing the complete	CASING/CEMENT OTHER: state all pertinent details, and or Multiple Completions: Annual and a follows: T&C 3	NT JOB multiple states in the state of the	Cluding estimated date
PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed or recompletion. Drilled 8-1/2" hole to a depth 1 Jt 1 78 Jts	multiple compliance of 10285'. Ran 5-1/2" casing Float Shoe 5-1/2" 17 #/FT L-80 L Float Collar 5-1/2" 17 #/FT L-80 I	CASING/CEMENT OTHER: State all pertinent details, a per Multiple Completions: T&C 303	nd give pertinent dates, incattach wellbore diagram of the control	Cluding estimated date
PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed or recompletion. Drilled 8-1/2" hole to a depth 1 Jt 1 78 Jts 1	multiple compliance of 10285'. Ran 5-1/2" casing Float Shoe 5-1/2" 17 #/FT L-80 L Float Collar 5-1/2" 17 #/FT L-80 I Weatherford Stage Coll	CASING/CEMENT OTHER: State all pertinent details, a per Multiple Completions: Ang as follows: AT&C 303 ar	nd give pertinent dates, incattach wellbore diagram of the first state	Cluding estimated date
PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed or recompletion. Drilled 8-1/2" hole to a depth 1 Jt 1 78 Jts	multiple compliance of 10285'. Ran 5-1/2" casing Float Shoe 5-1/2" 17 #/FT L-80 L Float Collar 5-1/2" 17 #/FT L-80 I	CASING/CEMENT OTHER: State all pertinent details, a per Multiple Completions: T&C 303 T&C 303 T&C 7216	nd give pertinent dates, incattach wellbore diagram of the control	Cluding estimated date
PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed or recompletion. Drilled 8-1/2" hole to a depth 1 Jt 1 78 Jts 1	multiple compliance of 10285'. Ran 5-1/2" casing Float Shoe 5-1/2" 17 #/FT L-80 L Float Collar 5-1/2" 17 #/FT L-80 I Weatherford Stage Coll	CASING/CEMENT OTHER: State all pertinent details, a per Multiple Completions: Ang as follows: AT&C 303 ar	nd give pertinent dates, incattach wellbore diagram of the control	Cluding estimated date
PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed or recompletion. Drilled 8-1/2" hole to a depth 1 Jt 1 78 Jts 1	multiple compliance of 10285'. Ran 5-1/2" casing Float Shoe 5-1/2" 17 #/FT L-80 L Float Collar 5-1/2" 17 #/FT L-80 I Weatherford Stage Coll 5-1/2" 17 #/FT L-80 L	CASING/CEMENT OTHER: state all pertinent details, a per Multiple Completions: T&C 303 ar T&C 7216 1029	nd give pertinent dates, ind Attach wellbore diagram of 1' 6' 1' 4' 2' 5'	cluding estimated date f proposed completion
PULL OR ALTER CASING OTHER: 13. Describe proposed or come of starting any proposed or recompletion. Drilled 8-1/2" hole to a depth 1	multiple compliance of 10285'. Ran 5-1/2" casing Float Shoe 5-1/2" 17 #/FT L-80 L Float Collar 5-1/2" 17 #/FT L-80 L Weatherford Stage Coll 5-1/2" 17 #/FT L-80 L ced 1st stage with 1035 SXS state 220 SXS off DV tool. Ce	CASING/CEMEN OTHER: state all pertinent details, a per Multiple Completions: Angle as follows: AT&C 303 ar T&C 7216 1029 50/50/2 "H" + 5% NaCl + 1000 Tement 2nd stage w/ 1045 SX	nd give pertinent dates, ind Attach wellbore diagram of 1' 6' 1' 4' 2' 5' 0' 5% FL-25 + .5% FL-52.	Cluding estimated date f proposed completion Dropped bomb and set C1 + .4% FL-52
PULL OR ALTER CASING OTHER: 13. Describe proposed or come of starting any proposed or recompletion. Drilled 8-1/2" hole to a depth 1	multiple compliance of 10285'. Ran 5-1/2" casing Float Shoe 5-1/2" 17 #/FT L-80 L Float Collar 5-1/2" 17 #/FT L-80 L Weatherford Stage Coll 5-1/2" 17 #/FT L-80 L ced 1st stage with 1035 SXS state 220 SXS off DV tool. Ce	CASING/CEMEN OTHER: state all pertinent details, a per Multiple Completions: Angle as follows: AT&C 303 ar T&C 7216 1029 50/50/2 "H" + 5% NaCl + 1000 Tement 2nd stage w/ 1045 SX	nd give pertinent dates, ind Attach wellbore diagram of 1' 6' 1' 4' 2' 5' 0' 5% FL-25 + .5% FL-52.	Cluding estimated date f proposed completion Dropped bomb and set C1 + .4% FL-52
PULL OR ALTER CASING OTHER: 13. Describe proposed or come of starting any proposed or recompletion. Drilled 8-1/2" hole to a depth 1	multiple compliance of 10285'. Ran 5-1/2" casing Float Shoe 5-1/2" 17 #/FT L-80 L Float Collar 5-1/2" 17 #/FT L-80 L Weatherford Stage Coll 5-1/2" 17 #/FT L-80 L ced 1st stage with 1035 SXS state 220 SXS off DV tool. Ce	CASING/CEMEN OTHER: state all pertinent details, a per Multiple Completions: Angle as follows: AT&C 303 ar T&C 7216 1029 50/50/2 "H" + 5% NaCl + 1000 Tement 2nd stage w/ 1045 SX	nd give pertinent dates, ind Attach wellbore diagram of 1' 6' 1' 4' 2' 5' 0' 5% FL-25 + .5% FL-52.	Cluding estimated date f proposed completion Dropped bomb and set C1 + .4% FL-52
PULL OR ALTER CASING OTHER: 13. Describe proposed or come of starting any proposed or recompletion. Drilled 8-1/2" hole to a depth 1	multiple compliance of 10285'. Ran 5-1/2" casing Float Shoe 5-1/2" 17 #/FT L-80 L Float Collar 5-1/2" 17 #/FT L-80 L Weatherford Stage Coll 5-1/2" 17 #/FT L-80 L ced 1st stage with 1035 SXS state 220 SXS off DV tool. Ce	CASING/CEMEN OTHER: state all pertinent details, a per Multiple Completions: Angle as follows: AT&C 303 ar T&C 7216 1029 50/50/2 "H" + 5% NaCl + 1000 Tement 2nd stage w/ 1045 SX	nd give pertinent dates, ind Attach wellbore diagram of 1' 6' 1' 4' 2' 5' 0' 5% FL-25 + .5% FL-52.	Cluding estimated date f proposed completion Dropped bomb and set C1 + .4% FL-52
PULL OR ALTER CASING OTHER: 13. Describe proposed or come of starting any proposed or recompletion. Drilled 8-1/2" hole to a depth 1	multiple compliance of 10285'. Ran 5-1/2" casing Float Shoe 5-1/2" 17 #/FT L-80 L Float Collar 5-1/2" 17 #/FT L-80 L Weatherford Stage Coll 5-1/2" 17 #/FT L-80 L ced 1st stage with 1035 SXS state 220 SXS off DV tool. Ce	CASING/CEMEN OTHER: state all pertinent details, a per Multiple Completions: Angle as follows: AT&C 303 ar T&C 7216 1029 50/50/2 "H" + 5% NaCl + 1000 Tement 2nd stage w/ 1045 SX	nd give pertinent dates, ind Attach wellbore diagram of 1' 6' 1' 4' 2' 5' 0' 5% FL-25 + .5% FL-52.	Cluding estimated date f proposed completion Dropped bomb and set C1 + .4% FL-52
PULL OR ALTER CASING OTHER: 13. Describe proposed or come of starting any proposed or recompletion. Drilled 8-1/2" hole to a depth 1	multiple compliance of 10285'. Ran 5-1/2" casing Float Shoe 5-1/2" 17 #/FT L-80 L Float Collar 5-1/2" 17 #/FT L-80 L Weatherford Stage Coll 5-1/2" 17 #/FT L-80 L ced 1st stage with 1035 SXS state 220 SXS off DV tool. Ce	CASING/CEMEN OTHER: state all pertinent details, a per Multiple Completions: Angle as follows: AT&C 303 ar T&C 7216 1029 50/50/2 "H" + 5% NaCl + 1000 Tement 2nd stage w/ 1045 SX	nd give pertinent dates, ind Attach wellbore diagram of 1' 6' 1' 4' 2' 5' 0' 5% FL-25 + .5% FL-52.	Cluding estimated date f proposed completion Dropped bomb and set C1 + .4% FL-52
PULL OR ALTER CASING OTHER: 13. Describe proposed or come of starting any proposed or recompletion. Drilled 8-1/2" hole to a depth 1	multiple compliance of 10285'. Ran 5-1/2" cash Float Shoe 5-1/2" 17 #/FT L-80 L Float Collar 5-1/2" 17 #/FT L-80 I Weatherford Stage Coll 5-1/2" 17 #/FT L-80 L ed 1st stage with 1035 SXS state 220 SXS off DV tool. Cell ND BOP and set slip. Cut	CASING/CEMENT OTHER: state all pertinent details, a per Multiple Completions: Angle as follows: AT&C 303 ar T&C 7216 10296 50/50/2 "H" + 5% NaCl + 1000 ment 2nd stage w/ 1045 SX a casing and install product	nd give pertinent dates, ind Attach wellbore diagram of 1' 6' 1' 4' 2' 5' 0' 5% FL-25 + .5% FL-52. 1 S 50/50/10 "H" + 5% Nac ion head. Release rig @ 0	Dropped bomb and set C1 + .4% FL-52
PULL OR ALTER CASING OTHER: 13. Describe proposed or come of starting any proposed or recompletion. Drilled 8-1/2" hole to a depth 1	multiple complements of the properties of 10285'. Ran 5-1/2" cash Float Shoe 5-1/2" 17 #/FT L-80 L Float Collar 5-1/2" 17 #/FT L-80 L Weatherford Stage Coll 5-1/2" 17 #/FT L-80 L and 1st stage with 1035 SXS state 220 SXS off DV tool. Cell ND BOP and set slip. Cut	CASING/CEMENT OTHER: state all pertinent details, a per Multiple Completions: And as follows: AT&C 303 AT&C 303 AT 7216 10296 50/50/2 "H" + 5% NaCl + 1000 Tement 2nd stage w/ 1045 SX a casing and install product	nd give pertinent dates, ind Attach wellbore diagram of 1' 6' 1' 4' 2' 5' 0' 5% FL-25 + .5% FL-52. I S 50/50/10 "H" + 5% Nac ion head. Release rig @ 0	Dropped bomb and set C1 + .4% FL-52 0900 Hrs. 5/1/2006.
PULL OR ALTER CASING OTHER: 13. Describe proposed or come of starting any proposed or recompletion. Drilled 8-1/2" hole to a depth 1	multiple complements of the problem of the problements of the probleme	CASING/CEMENT OTHER: state all pertinent details, a per Multiple Completions: And	nd give pertinent dates, incattach wellbore diagram of the first of th	Dropped bomb and set C1 + .4% FL-52 0900 Hrs. 5/1/2006.
PULL OR ALTER CASING OTHER: 13. Describe proposed or come of starting any proposed or recompletion. Drilled 8-1/2" hole to a depth 1 1 Jt 1 78 Jts 1 180 Jts Set casing @ 10285'. Cement DV tool with 900 PSI. Circulate followed by 100 SXS "H" near	multiple complements of the problem of the problements of the probleme	CASING/CEMENT OTHER: state all pertinent details, a per Multiple Completions: And as follows: AT&C 303 AT&C 303 AT 7216 10296 50/50/2 "H" + 5% NaCl + 1000 Tement 2nd stage w/ 1045 SX a casing and install product	nd give pertinent dates, incattach wellbore diagram of the first of th	Dropped bomb and set C1 + .4% FL-52 0900 Hrs. 5/1/2006.
PULL OR ALTER CASING OTHER: 13. Describe proposed or come of starting any proposed or recompletion. Drilled 8-1/2" hole to a depth 1	multiple complements of the problem of the problem of 10285'. Ran 5-1/2" casing Float Shoe 5-1/2" 17 #/FT L-80 L Float Collar 5-1/2" 17 #/FT L-80 L Weatherford Stage Coll 5-1/2" 17 #/FT L-80 L of 1st stage with 1035 SXS State 220 SXS off DV tool. Cells ND BOP and set slip. Cut for above is true and complete for closed according to NMOCD grant for the problem of th	CASING/CEMENT OTHER: State all pertinent details, a per Multiple Completions: T&C 303 CT&C 303 CT&C 7216 1029 50/50/2 "H" + 5% NaCl + 1029 Tement 2nd stage w/ 1045 SX or casing and install product Tement 2nd stage w/ 1045 SX or casing and install product TITLE VP OPERAT	nd give pertinent dates, incattach wellbore diagram of the first of th	Dropped bomb and set C1 + .4% FL-52 0900 Hrs. 5/1/2006.
PULL OR ALTER CASING OTHER: 13. Describe proposed or come of starting any proposed or recompletion. Drilled 8-1/2" hole to a depth 1	multiple complements of the problem of the problem of 10285'. Ran 5-1/2" casing Float Shoe 5-1/2" 17 #/FT L-80 L Float Collar 5-1/2" 17 #/FT L-80 L Weatherford Stage Coll 5-1/2" 17 #/FT L-80 L of 1st stage with 1035 SXS State 220 SXS off DV tool. Cells ND BOP and set slip. Cut for above is true and complete for closed according to NMOCD grant for the problem of th	CASING/CEMENT OTHER: state all pertinent details, a per Multiple Completions: And	nd give pertinent dates, incattach wellbore diagram of the first of th	Cluding estimated date f proposed completion Dropped bomb and set C1 + .4% FL-52 0900 Hrs. 5/1/2006. tify that any pit or below-CD-approved plan DATE 5/22/2006 one No. 972-931-0700
OTHER: 13. Describe proposed or come of starting any proposed or recompletion. Drilled 8-1/2" hole to a depth 1 1 Jt 1 78 Jts 1 180 Jts Set casing @ 10285'. Cement DV tool with 900 PSI. Circular followed by 100 SXS "H" near starting and tank has been/will be constructed SIGNATURE Type or print name MICHAEL For State Use Only	multiple complements of the properties of 10285'. Ran 5-1/2" casing Float Shoe 5-1/2" 17 #/FT L-80 L Float Collar 5-1/2" 17 #/FT L-80 L Weatherford Stage Coll 5-1/2" 17 #/FT L-80 L and 1st stage with 1035 SXS 5 at 220 SXS off DV tool. Cell ND BOP and set slip. Cut for flosted according to NMOCD grant Stage according to NMOCD grant Stage with 1035 SXS 5 at 220 SXS off DV tool. Cell ND BOP and set slip. Cut for flosted according to NMOCD grant Stage with 1035 SXS 5 at 220 SXS off DV tool. Cell ND BOP and set slip. Cut for flosted according to NMOCD grant Stage with 1035 SXS 5 at 220 SXS off DV tool. Cell ND BOP and set slip. Cut for flosted according to NMOCD grant Stage with 1035 SXS 5 at 220 SXS off DV tool. Cell ND BOP and set slip. Cut for flosted according to NMOCD grant Stage with 1035 SXS 5 at 220 SXS off DV tool. Cell ND BOP and set slip. Cut for flosted according to NMOCD grant Stage with 1035 SXS 5 at 220 SXS off DV tool. Cell ND BOP and set slip. Cut flosted according to NMOCD grant Stage with 1035 SXS 5 at 220 SXS off DV tool. Cell ND BOP and set slip. Cut flosted according to NMOCD grant Stage with 1035 SXS 5 at 220 SXS off DV tool. Cell ND BOP and set slip. Cut flosted according to NMOCD grant Stage with 1035 SXS 5 at 220 SXS off DV tool. Cell ND BOP and set slip.	CASING/CEMENT OTHER: State all pertinent details, a per Multiple Completions: And as follows: And And Andrews: And Andrews: And Andrews: And Andrews: Andrews:	nd give pertinent dates, ind Attach wellbore diagram of 1' 6' 1' 4' 2' 6' 0' 5% FL-25 + .5% FL-52. ES 50/50/10 "H" + 5% Nac ion head. Release rig @ 0 Idge and belief. I further cer or an (attached) alternative Octoor IONS Indicate of the control of the cont	Cluding estimated date f proposed completion Dropped bomb and set C1 + .4% FL-52 1900 Hrs. 5/1/2006. tify that any pit or below-CD-approved plan DATE 5/22/2006 one No. 972-931-0700 10 5 2006
OTHER: 13. Describe proposed or comof starting any proposed or recompletion. Drilled 8-1/2" hole to a depth 1 Jt 1 78 Jts 1 180 Jts Set casing @ 10285'. Cement DV tool with 900 PSI. Circulate followed by 100 SXS "H" near grade tank has been/will be constructed. I hereby certify that the informating rade tank has been/will be constructed. SIGNATURE	multiple complements of the problem of the problem of 10285'. Ran 5-1/2" casing Float Shoe 5-1/2" 17 #/FT L-80 L Float Collar 5-1/2" 17 #/FT L-80 L Weatherford Stage Coll 5-1/2" 17 #/FT L-80 L of 1st stage with 1035 SXS State 220 SXS off DV tool. Cells ND BOP and set slip. Cut for above is true and complete for closed according to NMOCD grant for the problem of th	CASING/CEMENT OTHER: State all pertinent details, a per Multiple Completions: And as follows: And And Andrews: And Andrews: And Andrews: And Andrews: Andrews:	nd give pertinent dates, ind Attach wellbore diagram of 1' 6' 1' 4' 2' 6' 0' 5% FL-25 + .5% FL-52. ES 50/50/10 "H" + 5% Nac ion head. Release rig @ 0 Idge and belief. I further cer or an (attached) alternative Octoor IONS Indicate of the control of the cont	Cluding estimated date f proposed completion Dropped bomb and set C1 + .4% FL-52 0900 Hrs. 5/1/2006. tify that any pit or below-CD-approved plan DATE 5/22/2006 one No. 972-931-0700