Submit 3 Copies 10 Appropriate District Office District I	State of New Mexico Energy, Minerals and Natural Resources		Form C-103 May 27, 2004
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-30975
District III	1220 South St. Francis Dr.		5. Indicate Type of Lease  STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM			
87505 SUNDRY NOTE	CES AND REPORTS ON WELLS	8	E-647 7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		D STATE	
	Gas Well  Other	RECEIVED	8. Well Number 21
2. Name of Operator		MEURIVEE	9. OGRID Number
MARBOB ENERGY CORPORAT	ION	JUN 1 6 2006	14049
3. Address of Operator	40	MOSTEMINA	10. Pool name or Wildcat
PO BOX 227, ARTESIA, NM 88211-0227 ARTESIA; QUEEN-GRBG-SAN ANDRES			
4. Well Location			
Unit Letter I			330 feet from the EAST line
Section 25	Township 17S R		NMPM County EDDY
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3664' GL			
Pit or Below-grade Tank Application 🔲 o		<del></del>	
Pit typeDepth to Groundwa	terDistance from nearest fresh	water well Dist	ance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Co	nstruction Material
12 Check A	ppropriate Roy to Indicate N	Jature of Notice	Report or Other Data
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF IN		j .	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	<del>-</del>
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB []
OTHER:		OTHER: RECOM	PLETE/DOWNHOLE COMMINGLE
		pertinent details, and	I give pertinent dates, including estimated date tach wellbore diagram of proposed completion
RECOMPLETED TO THE SAN ANDRES AND DOWNHOLE COMMINGLED AS FOLLOWS:			
6/1/06 - SET CIBP @	3150'. PERF THE SAN A	NDRES @ 2870'-	3059' (20 SHOTS).
6/2/06 - ACDZ W/ 2000 GAL NEFE 15% HCL ACID. SWAB TEST.			
6/6/06 - DRILL OUT CIBP TO DOWNHOLE COMMINGLE.			
0,0,00 PRIME OUT OFFI TO DOMINIONE CONTINUED.			
(SEE ADMINISTRATIVE ORDER #DHC-3676)			
j .			
	·		
I hereby certaily that the information a	hove is true and complete to the b	est of my knowledge	and belief. I further certify that any nit or below-
SIGNATURE SIGNATURE	losed according to NMOCD guidelines	, a general permit 🗍	or an (attached) alternative OCD-approved plan
**************************************	losed according to NMOCD guidelines	, a general permit .  PRODUCTION A	or an (attached) alternative OCD-approved plan .
	toked according to NMOCD guidelines	, a general permit . O	or an (attached) alternative OCD-approved plan □.  NALYST DATE 6/15/06  N@MARBOB.COMfelephone No. (505) 748-33
For State Use Only	TITLE  BRIGGS ONLY	, a general permit . O	or an (attached) alternative OCD-approved plan □.  NALYST DATE 6/15/06  N@MARBOB.COMfelephone No. (505) 748-33
For State Use Only	losed according to NMOCD guidelines	, a general permit . O	or an (attached) alternative OCD-approved plan