

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-05346
5. Indicate Type of Lease STATE ☐ FEE ☐
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name Skelly Unit
1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☐ Injection ☒ RECEIVED JUN 27 2006		8. Well Number 45
2. Name of Operator Forest Oil Corporation		9. OGRID Number 8041
3. Address of Operator 3504 NW County Road		10. Pool name or Wildcat Grayburg Jackson 7RVS QN GB SA
4. Well Location Unit Letter <u>G</u> : <u>1980</u> feet from the <u>North</u> line and <u>1980</u> feet from the <u>East</u> line Section <u>22</u> Township <u>17S</u> Range <u>31E</u> NMPM <u>Eddy</u> County		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3858' DF		
Pit or Below-grade Tank Application ☐ or Closure ☐		
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____		
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	P AND A ☐
PULL OR ALTER CASING ☐	MULTIPLE COMPL ☐	CASING/CEMENT JOB ☐	
OTHER: Temporary Abandon ☒		OTHER: ☐	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

The annulus will be pressured to 500 PSI to check its integrity. If it is ok, a pulling unit will be rigged up. The packer will be released and pulled out of the hole, laying down tubing and packer. A CIBP will be set where packer was set. The Artesia OCD office will be notified before start of work and casing test. The casing will be pressured to 500 PSI and tested again with a 30 minute chart.

Estimated date of starting proposed work will be as soon as possible.

CIBP must be within 100' of top perforation

Notify OCD 24 hrs. prior to
any work done.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Mary Jo Turner TITLE Production Analyst DATE June 26, 2006

Type or print name Mary Jo Turner E-mail address: mturner@forestoil.com Telephone No. (505) 392-9797
For State Use Only

APPROVED BY: Gerry Guye TITLE Deputy Field Inspector DATE JUN 28 2006
Conditions of Approval (if any): District II - Artesia