Office	State of New Mexico		Form C-103
* <u>District I</u> Energy, Mine	Energy, Minerals and Natural Resources		March 4, 2004
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. 30-015-00258
1301 W. Grand Ave., Artesia, NM 88210 OIL CONS	, Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE X	
trict IV Santa Fe, NM 8/303		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		Nix Curtis JF	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		O W-11 N	
1. Type of Well:		8. Well Number	
Oil Well Gas Well Other P&A RECEIVED			
2. Name of Operator	N	1AY 1 8 2005	9. OGRID Number
Yates Petroleum Corporation		- · · · · ·	025575
3. Address of Operator 105 South Fourth Street, Artesia, NM 88210	#3 C	U-MATERIA	10. Pool name or Wildcat Penasco Draw San Andres Yeso
4. Well Location			reliasco Diaw Sali Alidies Teso
Unit Letter D : 990 feet from th	e North	line and 99	90 feet from the West line
			Total for the Total file
Section 32 Township	18S Rar	ige 26E	NMPM Eddy County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3413'GR			
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)			
Pit Location: ULSectTwpRngPit typeDepth to GroundwaterDistance from nearest fresh water well			
Distance from nearest surface water Below-grade Tank Location ULSectTwpRng;			
feet from theline andfeet from theline			
12. Check Appropriate Box 1 NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABAN		-	SEQUENT REPORT OF:
TEMPORARILY ABANDON		COMMENCE DRI	
PULL OR ALTER CASING MULTIPLE COMPLETION		CASING TEST AN	ABANDONMENT
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
5/3/05 – Began P&A procedures. 5/5/05 – POOH with tubing and rods. Set CIBP at 2635'. Circulated 10# mud. Spotted 25 sx cement at 2635'-2395'. Spotted 40 sx			
cement at 2304'-1920'.  5/6/05 - Tagged at 2003'. Reset plug. Spotted 20 sx cement with 2-1/2% CaCl at 2003'. WOC 3 hrs. Tagged at 1809'. Spotted 25 sx			
cement at 976'-736'. Spotted 17 sx cement at 159' to surface.			
5/9/05 - Tagged at 37'. Spotted 5 sx at 37' to surface. Cut off wellhead. Installed dry hole marker. WELL IS PLUGGED AND			
ABANDONED. FINAL REPORT.		Ž	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed of closed according to NMOCD guidelines, a general permit or an (attached) alternative OCD-approved plan.			
SIGNATURE:			
Type or print name Tina Huerta	E-mail address	<u></u>	
(This s Approved as to plugging of the well bore. Liability under bond is retained until surface restoration,		NMOCD NMOCD	AUG 9 2006
APPPI under bond is retained until surface restoration, environmental remediation and final inspection is completed.	ITTLE_	NMOCD	DATE