

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised June 10, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-10390
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. E-9262
7. Lease Name or Unit Agreement Name North Benson Queen Unit
8. Well Number 10
9. OGRID Number 5300
10. Pool name or Wildcat Queen - Grayburg

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other ☒ Injection Well

2. Name of Operator
United Oil & Minerals Limited Partnership

3. Address of Operator
1001 Westbank Dr., Austin, TX 78746

4. Well Location

Unit Letter **F** : **2310** feet from the **North** line and **1650** feet from the **West** line

Section **29** Township **18S** Range **30E** NMPM **Eddy** County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3455 KB

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	MULTIPLE COMPLETION ☐	CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

7-11-03 Started in hole to tag CIBP @ 2714', tag up on salt ring @ 651'.
7-14-03 Washed down to 2664', circ. hole w/mud, spot 25 sx @ 2664'.
7-15-03 Run stretch on csg. showed 500', perf @ 1305' & sqz 65 sx. Tagged cmt @ 1118'.
7-16-03 Cut csg @ 535', lay down 5-1/2" csg. Spot 65 sx 600-300'. WOC 3 hrs & tagged cmt @ 346'. Spot 100 sx plug to surface. POOH w/tbg. Spot 5 sx to cap well off.
Cut off wellhead, install dry hole marker & clean location. RDMO.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Curliss Patton TITLE Regulatory Coordinator DATE 7/30/2003

Type or print name Mary Curliss Patton E-mail address: mpatton@uominc.com Telephone No. (512) 328-8184
(This space for State use)

APPROVED BY _____ TITLE _____ DATE _____
Conditions of approval, if any: Accepted for record - NMOC