Submit 3 Copies To Appropriate District	State of New M	exico		Form C-103
Office District I	Energy, Minerals and Nat	ural Resources	TVELT A DIVIO	May 27, 2004
#625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO.	3435429 <sup>3031-1</sup> 2375
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION		5. Indicate Type of Le	1986 N
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE	SEE X Allo
District IV	Santa Fe, NM 8	7505	6. State Oil & Gas Lea	asono. Ocheca 200
1220 S. St. Francis Dr., Santa Fe, NM 87505	•			40000
	CES AND REPORTS ON WELL	S	7. Lease Name or Uni	t Agreement Name
(DO NOT USE THIS FORM FOR PROPOS			1	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		PREPARATION H	EEE CO CEL SI TI DI CINT	
			8. Well Number 1	0181713
2. Name of Operator			9. OGRID Number	1/0/0
MARBOB ENERGY CORPORATION  3. Address of Operator			10. Pool name or Wild	14049
PO BOX 227, ARTESIA, NM 88211-0227		10. I doi name of wife	ıcat	
4. Well Location	NM 88211-0227			
Y .	1980 feet from the SOU	TH line and	990 feet from the	e EAST line
Section 1	Township 198 R	· · · · · · · · · · · · · · · · · · ·		ounty EDDY
Section	11. Elevation (Show whether DI			anty EDD1
	3272'			
Pit or Below-grade Tank Application O	r Closure 🔲			
Pit typeDepth to Groundwa	iterDistance from nearest fresh	water well Di	stance from nearest surface w	ater
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; C	Construction Material	
12. Check A	Appropriate Box to Indicate N	Nature of Notice	, Report or Other Dat	a
NOTICE OF IN	TENTION TO	1 0115		DT 05
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TO				
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON	PLUG AND ABANDON 🔯 CHANGE PLANS		=======================================	ERING CASING   ND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN		NO A
T SEE STATE OF STATES		O/ IOI TO/ OEIVIE!	11 000	
OTHER:		OTHER:		
	leted operations. (Clearly state all			
of starting any proposed wo or recompletion.	ork). SEE RULE 1103. For Multip	ple Completions: A	ttach wellbore diagram of	f proposed completion
or recompletion.				
MARBOB ENERGY CORPO	ORATION PROPOSES TO PLU	G & ABANDON A	S FOLLOWS:	
1. SET CIBP @ ±10!				
			JIS & 5 1/2" CSC F	III. OF
2. SHOOT 4 HOLES @ ±240'. FILL 9 5/8" X 5 1/2" ANNULUS & 5 1/2" CSG FULL OF CMT (80 SX CLASS "C") FROM 240' TO SURFACE.				
3. CUT OFF WELLHEAD, INSTALL DRYHOLE MARKER & RECLAIM LOCATION.				
			Modify OCE	104 hm miles
			_ ~	24 hrs. prior
			to any v	vork done.
Thereby a buff, that the industrial	Share in the state of the state		11 1: 6	
I hereby certify that the information a		best of my knowleds	ge and belief. I further cert	ify that any nit or balance
11000	above is true and complete to the tables according to MOCD guidelines	. a general permit	or an (attached) alternative (	OCD-approved plan
SIGNATURE	closed according to NMOCD guidelines	□, a general permit □		OCD-approved plan 🗌.
<del>// // -</del>	posed according to MOCD guidelines  TITLE	, a general permit PRODUCTION		TE_8/1/06
	closed according to NMOCD guidelines	□, a general permit □ PRODUCTION	ANALYST DA	OCD-approved plan □. TE8/1/06
Type or print name DIANA J	closed according to NMOCD guidelines	□, a general permit □ PRODUCTION	ANALYST DA	OCD-approved plan 🗌.
	BRIGGS  BRIGGS  BRIGGS  BRIGGS  BRIGGS	PRODUCTION  ddressPRODUCTIO	ANALYST DA	OCD-approved plan □.  TE 8/1/06  one No.(505) 748-3303
Type or print name DIANA J	BRIGGS  BRIGGS  BRIGGS  BRIGGS  BRIGGS	□, a general permit □ PRODUCTION	ANALYST DA	OCD-approved plan [].