

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-015-34699
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VO-6154-16155
7. Lease Name or Unit Agreement Name: OXY Pogo State
8. Well Number 2
9. OGRID Number 192463
10. Pool name or Wildcat Undsq. Otis Morrow

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM 103) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other
2. Name of Operator OXY USA WTP Limited Partnership
3. Address of Operator P.O. Box 50250 Midland, TX 79710-0250
4. Well Location Unit Letter <u>F</u> : <u>1800</u> feet from the <u>north</u> line and <u>1350</u> feet from the <u>west</u> line Section <u>36</u> Township <u>22S</u> Range <u>27E</u> NMPM County <u>Eddy</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <u>3076'</u>
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/> Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐

OTHER: Drill 16' w/ Rat Hole Machine ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attachment

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE David Stewart TITLE Sr. Regulatory Analyst DATE 8/21/06

Type or print name David Stewart E-mail address: david\_stewart@oxy.com Telephone No. 432-685-5717

For State Use Only

APPROVED BY Jim W. Brown DATE 8/21/06

Conditions of Approval, if any:

## OXY Pogo State #2

**Date: 04/01/2006**

Supervisor 1: BOB LANGE  
DRILL TO 10' WITH RAT HOLE MACHINE  
WAIT ON DRILLING RIG

**Date: 04/02/2006**

WAIT ON DRILLING RIG  
DRILL TO 11' WITH RAT HOLE MACHINE  
WAIT ON DRILLING RIG

**Date: 04/08/2006**

WAIT ON DRILLING RIG  
MIRU BUTCH'S RAT HOLE MACHINE & DRILL TO 12'. RD  
WAIT ON DRILLING RIG

**Date: 05/26/2006**

Supervisor 1: BOB LANGE  
W/O RIG  
DRILL 1'  
W/O RIG

**Date: 06/13/2006**

Supervisor 1: BOB LANGE  
WAIT ON ROTARY TOOLS  
DRILL TO 14'  
WAIT ON TOTARY TOOLS

**Date: 07/01/2006**

Supervisor 1: BOB LANGE  
WAIT ON ROTARY TOOLS  
DRILL 1' WITH RAT HOLE MACHINE  
WAIT ON ROTARY TOOLS

**Date: 07/19/2006**

Supervisor 1: BOB LANGE  
WAIT ON DRILLING RIG  
MIRU BUTCH'S RAT HOLE MACHINE & DRILL 1'  
WAIT ON DRILLING RIG

TVD: 16.0

Cum Cost: 14,000.00

## Intent To P&A

1. M&P 30sx Surface