Submit 3 Copies To Appropriate District	State of New Mexico				Form C-103			
Office Energy, Minerals and Natural Resources District I					WELL AT	INO	May 2	7, 2004
1625 N. French Dr., Hobbs, NM 87240 District II	OIL CONCEDIVATION DIVISION				WELL API NO. 30-015-05714			
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.			l	5. Indicate Type of Lease			
District III 1000 Rio Brazos Rd., Aztec, NM 87410					STATE 🔀 FEE 🗆			
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505					6. State C	il & Gas Le	ase No.	
					E 6018			
SUNDRY NOTIC (DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	ES AND REPORTS SALS TO DRILL OR TO ATION FOR PERMIT" (F	ON WELD DEEPEN O ORMEE-101	129 23 24 25 R PLUG BACK I) FOR SUCH	52 7	STATE		it Agreement Na	ime:
1. Type of Well:		12	JOHN S	7829	8. Well N	umber		
Oil Well 🛛 Gas Well 🗌	Other	9	U. CHESCH	ည်		3		
2. Name of Operator		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	RECORRIG	3/	9. OGRID	Number		
RAY WESTALL		\ <u>\</u>	<u>60</u>			018862		
3. Address of Operator		(5)		15/		name or Wil	dcat	i
BOX 4, Loco Hills, NM 882 4. Well Location	55		68 F 3 2 4		SHUGART			
Unit Letter F ::	1650 feet from the	e NOR	TH line an	nd	1650	feet from the	he WEST	line
Section 2	Township	19S]	Range 31	E	NMPM	(County E	XDY
	11. Elevation (Show	v whether L						
Pit or Below-grade Tank Application								a variation of
Pit type STEEL Depth to Groundwater		nearest fresh	water well	Dis	tance from ne	arest surface	water	
Pit Liner Thickness: mil								
			·					
NOTICE OF INTE				SUB	-	NT REPO	RT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDO	ן יין אכ	REMEDIAL W	ORK			ALTERING CAS	ING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE	DRILLI	NG OPNS.		PLUG AND ABANDONMEN	T X
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST CEMENT JOB					
OTHER:			OTHER:					
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.								
10-10-06 Set 5 1/2" CIBP @2,600'.	@3,400'. Cap w/3	5'cant. w	v/bailer. Cii	rculat	e hole w/	mud. Spot	40 sx. cmt.	
,	'. Perf. 4 holes @ 200'. Pump 50 sx. (ent. down	1 5 1/2" to s	surfac	e out of			
10-12-06 Install Dryhole	Marker.	under bond is	to plugging of the retained until surf	face resto	ration,			
I hereby certify that the information al	oove is true and cor	environmenta completed.	al remediation and	final ins	pection is		tify that any pit or	
SIGNATURE DENNIAL	Mine	TITI	E	P&A	SUPV		ATE10-16	. —
			nail address:	<u> </u>				,00
Type or print name RANDALL MINEAU	'					Telepho	ne No.	
For State Use Only	· `			Gerry	Guye			
APPROVED BY / Slung of	my	TIT		Jly Fie	d Inspect	or Da'	_{TE} OCT 25	2006
Conditions of Approval, if any		111	Di	strict II	- Affesia	DA		
, , , , , , , , , , , , , , , , , , ,								