

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	GEOLOGIC MARKERS	
					MEAS. DEPTH	TOP
					TRUE VERT. DEPTH	
San Andres	1546'	2936'		Cravburg	1547'	
Glorieta	2936'	3017'		San Andres	1546'	
Yeso	3017'	3814'		Glorieta	2936'	
				Yeso	3017'	
				Total Depth	3814'	
DEPTH	ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC.. (continued from the front)					