FORM APPROVED
OM B No. 1004-0137
Expires: March 31, 2007

DEPARTMENT OF THE		<i>``</i> n\	Expires: March 31, 2007	
BUREAU OF LAND MAN	RE.	2008 8	5. Lease Serial No.	
SUNDRY NOTICES AND REP	1	ED 5	NMLC058362	
Do not use this form for proposals to abandoned well. Use Form 3160 - 3 (A	o drill or to re-é APD) for such pro	HIEFOR	6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE- Other instr	ructions on rever	se side	7. If Unit or CA/Agreement, Name and/or No.	
I. Type of Well Gas Well Other			NMNM111789X 8. Well Name and No.	
2. Name of Operator Marbob Energy Corporation			Dodd Federal Unit #11	
			9. API Well No. 30-015-02948	
3a. Address PO Box 227, Artesia, NM 88211-0227	3b. Phone No. (include area code) 505-748-3303		10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Grbg Jackson SR Q Grbg SA	
1980 FSL 1980 FEL, Sec. 11-T17S-R29E, Unit J				
			Eddy Co., NM	
12. CHECK APPROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTICE, RE	PORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYP	PE OF ACTION		
Acidize	Deepen	Production (Start	/Resume) Water Shut-Off	
Notice of Intent Alter Casing	Fracture Treat	Reclamation	Well Integrity	
Subsequent Report Casing Repair	New Construction	Recomplete	Other	
Final Abandonment Notice Convert to Injection	Plug and Abandon Plug Back	Temporarily Aba Water Disposal	ndon	
13. Describe Proposed or Completed Operation (clearly state all pertin		·		
Attach the Bond under which the work will be performed or provide following completion of the involved operations. If the operation it testing has been completed. Final Abandonment Notices shall be it determined that the site is ready for final inspection.)	esults in a multiple compl	letion or recompletion in	a new interval, a Form 3160-4 shall be filed once	
Plugged & abandoned as follows:				
10/18/06 - POOH w/ pkr & tbg. Set CIBP @ 2300'. Circ plugging mud. Spot 25 sx cmt on top of CIBP. Shoot 4 sqz holes @ 900'. Pump 45 sx cmt. 10/19/06 - Tag @ 727'. Shoot 4 sqz holes @ 510'. Pump 40 sx cmt plug. Tag @ 385'. Shoot 4 sqz holes @ 100'. Pump 40 sx cmt. 10/20/06 - Pump 40 sx cmt. Tag @ 75'. Top out w/ 15 sx cmt. Cut off wellhead & install dry hole marker.				
Accepted for record				
NMOCD (
14. I hereby certify that the foregoing is true and correct	-			
Name (Printed/Typed) Diana J. Briggs	Title Pro	oduction Analyst		
Signature Date 11/14/2006				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by James Q. Omes	T:	le SEAS	Date 11-28-04	
Conditions of approval, if any, are attached. Approval of this notice d certify that the applicant holds legal or equitable title to those rights in	oes not warrant or	fice (F)	11 CB - U)	
which would entitle the applicant to conduct operations thereon.		CFO		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to anymatter within its jurisdiction.