| Office | Form C-103 |
|--|---|
| District I Energy, Minerals and Natural Resources | May 27, 2004 WELL API NO. |
| 1625 N. Free Physics NM 88240 District II | 30-015-35047 |
| District III Di | 5. Indicate Type of Lease |
| 1220 South St. Francis Dr. 1000 Rio Brit. Rd. Jec., NM 87410 District IV Santa Fe, NM 87505 | STATE FEE |
| District IV 1220 S. St. Francis Dr., Santa Fe, NM | 6. State Oil & Gas Lease No. |
| 87505 (C.C.) 20.20.22.23 | VO-6515 |
| SUNDRY NOTICES AND REPORTS ON WELLS | 7. Lease Name or Unit Agreement Name |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEPEND R PLUG BACK TO A | |
| DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) RESERVOIR PROPOSALS.) | Draw BJL State |
| PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other PROPOSALS. 2. Name of Operator Yates Petroleum Corporation | 8. Well Number |
| 2. Name of Operator | 9. OGRID Number |
| Yates Petroleum Corporation | 025575 |
| 3. Address of Operator | 10. Pool name or Wildcat |
| 2. Name of Operator Yates Petroleum Corporation 3. Address of Operator 105 S. 4th Street, Artesia, NM 88210 4. Well Location | Corral Canyon; Bone Spring, South |
| | |
| Unit Letter K: 2310 feet from the South line and | 2310 feet from the West line |
| Section 36 Township 25S Range 29E | NMPM Eddy County |
| 11. Elevation (Show whether DR, RKB, RT, GR, e | (c.) |
| Pit or Below-grade Tank Application or Closure | |
| | Distance from nearest surface water |
| | Construction Material |
| 12. Check Appropriate Box to Indicate Nature of Notic | |
| | c, Report of Other Data |
| | BSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO | _ |
| | RILLING OPNS. PLUG AND ABANDON |
| PULL OR ALTER CASING MULTIPLE COMPL CASING/CEME | NT JOB |
| OTHER: OTHER: Comp | letion Operations |
| | |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, | and give pertinent dates, including estimated date |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: | and give pertinent dates, including estimated date |
| | and give pertinent dates, including estimated date |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. | and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/9/06 – TOC 2970' Est. Perforate Bone Spring 9044'-9068' (25) and 9130'-9138' (9). | Acidize Bone Spring 9130'-9138' with 300g 7- |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/9/06 – TOC 2970' Est. Perforate Bone Spring 9044'-9068' (25) and 9130'-9138' (9). 1/2% HCL acid. Acidize Bone Spring 9044'-9138' with 750g 7-1/2% HCL with 40 ball 11/15/06 – Frac Bone Spring with 37,928g Delta frac 200 and 37,683# 20/40 white and 4 | Acidize Bone Spring 9130'-9138' with 300g 7-sealers. 9,000# Expedite total of 86,683# of sand. |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/9/06 – TOC 2970' Est. Perforate Bone Spring 9044'-9068' (25) and 9130'-9138' (9). 1/2% HCL acid. Acidize Bone Spring 9044'-9138' with 750g 7-1/2% HCL with 40 ball 11/15/06 – Frac Bone Spring with 37,928g Delta frac 200 and 37,683# 20/40 white and 41/17/06 – Perforate Bone Spring 8036'-8044' (9), 8140'-8144' (5), 8156'-8160' (5), 81 | Acidize Bone Spring 9130'-9138' with 300g 7-sealers. 9,000# Expedite total of 86,683# of sand. 20'-8200' (11), 8215'-8218' (4) and 8223'-8226' |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/9/06 – TOC 2970' Est. Perforate Bone Spring 9044'-9068' (25) and 9130'-9138' (9). 1/2% HCL acid. Acidize Bone Spring 9044'-9138' with 750g 7-1/2% HCL with 40 ball 11/15/06 – Frac Bone Spring with 37,928g Delta frac 200 and 37,683# 20/40 white and 4 11/17/06 – Perforate Bone Spring 8036'-8044' (9), 8140'-8144' (5), 8156'-8160' (5), 816(4). Acidize Bone Spring 8140'-8226' with 1000g 7-1/2% Iron control and 50 balls. Ac | Acidize Bone Spring 9130'-9138' with 300g 7-sealers. 9,000# Expedite total of 86,683# of sand. 20'-8200' (11), 8215'-8218' (4) and 8223'-8226' |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/9/06 – TOC 2970' Est. Perforate Bone Spring 9044'-9068' (25) and 9130'-9138' (9). 1/2% HCL acid. Acidize Bone Spring 9044'-9138' with 750g 7-1/2% HCL with 40 ball 11/15/06 – Frac Bone Spring with 37,928g Delta frac 200 and 37,683# 20/40 white and 41/17/06 – Perforate Bone Spring 8036'-8044' (9), 8140'-8144' (5), 8156'-8160' (5), 816'. Acidize Bone Spring 8140'-8226' with 1000g 7-1/2% Iron control and 50 balls. Ac 1/2% IC acid and 20 balls. | Acidize Bone Spring 9130'-9138' with 300g 7-sealers. 9,000# Expedite total of 86,683# of sand. 90'-8200' (11), 8215'-8218' (4) and 8223'-8226' dize Bone Spring 8036'-8044' with 400g 7- |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/9/06 – TOC 2970' Est. Perforate Bone Spring 9044'-9068' (25) and 9130'-9138' (9). 1/2% HCL acid. Acidize Bone Spring 9044'-9138' with 750g 7-1/2% HCL with 40 ball 11/15/06 – Frac Bone Spring with 37,928g Delta frac 200 and 37,683# 20/40 white and 41/17/06 – Perforate Bone Spring 8036'-8044' (9), 8140'-8144' (5), 8156'-8160' (5), 81(4). Acidize Bone Spring 8140'-8226' with 1000g 7-1/2% Iron control and 50 balls. Ac 1/2% IC acid and 20 balls. 11/29/06 – Set 5-1/2" 17# cement retainer at 7955'. Squeezed perfs 8036'-8226' with 1500 performs a squeezed perfs 8036'-8226' with 1500 performs and 50 balls. | Acidize Bone Spring 9130'-9138' with 300g 7-sealers. 9,000# Expedite total of 86,683# of sand. 90'-8200' (11), 8215'-8218' (4) and 8223'-8226' dize Bone Spring 8036'-8044' with 400g 7- |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/9/06 – TOC 2970' Est. Perforate Bone Spring 9044'-9068' (25) and 9130'-9138' (9). 1/2% HCL acid. Acidize Bone Spring 9044'-9138' with 750g 7-1/2% HCL with 40 ball 11/15/06 – Frac Bone Spring with 37,928g Delta frac 200 and 37,683# 20/40 white and 41/17/06 – Perforate Bone Spring 8036'-8044' (9), 8140'-8144' (5), 8156'-8160' (5), 81' (4). Acidize Bone Spring 8140'-8226' with 1000g 7-1/2% Iron control and 50 balls. Ac 1/2% IC acid and 20 balls. 11/29/06 – Set 5-1/2" 17# cement retainer at 7955'. Squeezed perfs 8036'-8226' with 15 Squeezed off at 1450 psi (good squeeze). Circulated hole clean. | Acidize Bone Spring 9130'-9138' with 300g 7-sealers. 9,000# Expedite total of 86,683# of sand. 90'-8200' (11), 8215'-8218' (4) and 8223'-8226' dize Bone Spring 8036'-8044' with 400g 7- |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/9/06 – TOC 2970' Est. Perforate Bone Spring 9044'-9068' (25) and 9130'-9138' (9). 1/2% HCL acid. Acidize Bone Spring 9044'-9138' with 750g 7-1/2% HCL with 40 ball 11/15/06 – Frac Bone Spring with 37,928g Delta frac 200 and 37,683# 20/40 white and 41/17/06 – Perforate Bone Spring 8036'-8044' (9), 8140'-8144' (5), 8156'-8160' (5), 81(4). Acidize Bone Spring 8140'-8226' with 1000g 7-1/2% Iron control and 50 balls. Ac 1/2% IC acid and 20 balls. 11/29/06 – Set 5-1/2" 17# cement retainer at 7955'. Squeezed perfs 8036'-8226' with 1500 performs a squeezed perfs 8036'-8226' with 1500 performs and 50 balls. | Acidize Bone Spring 9130'-9138' with 300g 7-sealers. 9,000# Expedite total of 86,683# of sand. 90'-8200' (11), 8215'-8218' (4) and 8223'-8226' dize Bone Spring 8036'-8044' with 400g 7- |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/9/06 – TOC 2970' Est. Perforate Bone Spring 9044'-9068' (25) and 9130'-9138' (9). 1/2% HCL acid. Acidize Bone Spring 9044'-9138' with 750g 7-1/2% HCL with 40 ball 11/15/06 – Frac Bone Spring with 37,928g Delta frac 200 and 37,683# 20/40 white and 41/17/06 – Perforate Bone Spring 8036'-8044' (9), 8140'-8144' (5), 8156'-8160' (5), 81(4). Acidize Bone Spring 8140'-8226' with 1000g 7-1/2% Iron control and 50 balls. Ac 1/2% IC acid and 20 balls. 11/29/06 – Set 5-1/2" 17# cement retainer at 7955'. Squeezed perfs 8036'-8226' with 15 Squeezed off at 1450 psi (good squeeze). Circulated hole clean. 12/1/06 – Drilled out cement retainer. Circulated hole clean. | Acidize Bone Spring 9130'-9138' with 300g 7-sealers. 9,000# Expedite total of 86,683# of sand. 90'-8200' (11), 8215'-8218' (4) and 8223'-8226' dize Bone Spring 8036'-8044' with 400g 7- |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/9/06 – TOC 2970' Est. Perforate Bone Spring 9044'-9068' (25) and 9130'-9138' (9). 1/2% HCL acid. Acidize Bone Spring 9044'-9138' with 750g 7-1/2% HCL with 40 ball 11/15/06 – Frac Bone Spring with 37,928g Delta frac 200 and 37,683# 20/40 white and 41/17/06 – Perforate Bone Spring 8036'-8044' (9), 8140'-8144' (5), 8156'-8160' (5), 81(4). Acidize Bone Spring 8140'-8226' with 1000g 7-1/2% Iron control and 50 balls. Ac 1/2% IC acid and 20 balls. 11/29/06 – Set 5-1/2" 17# cement retainer at 7955'. Squeezed perfs 8036'-8226' with 15 Squeezed off at 1450 psi (good squeeze). Circulated hole clean. 12/1/06 – Drilled out cement retainer. Circulated hole clean. | Acidize Bone Spring 9130'-9138' with 300g 7-sealers. 9,000# Expedite total of 86,683# of sand. 90'-8200' (11), 8215'-8218' (4) and 8223'-8226' dize Bone Spring 8036'-8044' with 400g 7- |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/9/06 – TOC 2970' Est. Perforate Bone Spring 9044'-9068' (25) and 9130'-9138' (9). 1/2% HCL acid. Acidize Bone Spring 9044'-9138' with 750g 7-1/2% HCL with 40 ball 11/15/06 – Frac Bone Spring with 37,928g Delta frac 200 and 37,683# 20/40 white and 41/17/06 – Perforate Bone Spring 8036'-8044' (9), 8140'-8144' (5), 8156'-8160' (5), 81(4). Acidize Bone Spring 8140'-8226' with 1000g 7-1/2% Iron control and 50 balls. Ac 1/2% IC acid and 20 balls. 11/29/06 – Set 5-1/2" 17# cement retainer at 7955'. Squeezed perfs 8036'-8226' with 15 Squeezed off at 1450 psi (good squeeze). Circulated hole clean. 12/1/06 – Drilled out cement retainer. Circulated hole clean. | Acidize Bone Spring 9130'-9138' with 300g 7-sealers. 9,000# Expedite total of 86,683# of sand. 90'-8200' (11), 8215'-8218' (4) and 8223'-8226' dize Bone Spring 8036'-8044' with 400g 7- |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/9/06 – TOC 2970' Est. Perforate Bone Spring 9044'-9068' (25) and 9130'-9138' (9). 1/2% HCL acid. Acidize Bone Spring 9044'-9138' with 750g 7-1/2% HCL with 40 ball 11/15/06 – Frac Bone Spring with 37,928g Delta frac 200 and 37,683# 20/40 white and 41/17/06 – Perforate Bone Spring 8036'-8044' (9), 8140'-8144' (5), 8156'-8160' (5), 81(4). Acidize Bone Spring 8140'-8226' with 1000g 7-1/2% Iron control and 50 balls. Ac 1/2% IC acid and 20 balls. 11/29/06 – Set 5-1/2" 17# cement retainer at 7955'. Squeezed perfs 8036'-8226' with 15 Squeezed off at 1450 psi (good squeeze). Circulated hole clean. 12/1/06 – Drilled out cement retainer. Circulated hole clean. | Acidize Bone Spring 9130'-9138' with 300g 7-sealers. 9,000# Expedite total of 86,683# of sand. 90'-8200' (11), 8215'-8218' (4) and 8223'-8226' dize Bone Spring 8036'-8044' with 400g 7- |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/9/06 – TOC 2970' Est. Perforate Bone Spring 9044'-9068' (25) and 9130'-9138' (9). 1/2% HCL acid. Acidize Bone Spring 9044'-9138' with 750g 7-1/2% HCL with 40 ball 11/15/06 – Frac Bone Spring with 37,928g Delta frac 200 and 37,683# 20/40 white and 4 11/17/06 – Perforate Bone Spring 8036'-8044' (9), 8140'-8144' (5), 8156'-8160' (5), 81' (4). Acidize Bone Spring 8140'-8226' with 1000g 7-1/2% Iron control and 50 balls. Ac 1/2% IC acid and 20 balls. 11/29/06 – Set 5-1/2" 17# cement retainer at 7955'. Squeezed perfs 8036'-8226' with 15 Squeezed off at 1450 psi (good squeeze). Circulated hole clean. 12/1/06 – Drilled out cement retainer. Circulated hole clean. 12/4/06 – Test squeezed off perfs again to 1000 psi, held good. SN at 8947'. | Acidize Bone Spring 9130'-9138' with 300g 7-sealers. 9,000# Expedite total of 86,683# of sand. 20'-8200' (11), 8215'-8218' (4) and 8223'-8226' idize Bone Spring 8036'-8044' with 400g 7-0 sx "H" with .2% FL-62 and 200 sx "H" Neat. |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/9/06 – TOC 2970' Est. Perforate Bone Spring 9044'-9068' (25) and 9130'-9138' (9). 1/2% HCL acid. Acidize Bone Spring 9044'-9138' with 750g 7-1/2% HCL with 40 ball 11/15/06 – Frac Bone Spring with 37,928g Delta frac 200 and 37,683# 20/40 white and 41/17/06 – Perforate Bone Spring 8036'-8044' (9), 8140'-8144' (5), 8156'-8160' (5), 81(4). Acidize Bone Spring 8140'-8226' with 1000g 7-1/2% Iron control and 50 balls. Ac 1/2% IC acid and 20 balls. 11/29/06 – Set 5-1/2" 17# cement retainer at 7955'. Squeezed perfs 8036'-8226' with 15 Squeezed off at 1450 psi (good squeeze). Circulated hole clean. 12/1/06 – Drilled out cement retainer. Circulated hole clean. | Acidize Bone Spring 9130'-9138' with 300g 7-sealers. 9,000# Expedite total of 86,683# of sand. 20'-8200' (11), 8215'-8218' (4) and 8223'-8226' idize Bone Spring 8036'-8044' with 400g 7-0 sx "H" with .2% FL-62 and 200 sx "H" Neat. |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/9/06 – TOC 2970' Est. Perforate Bone Spring 9044'-9068' (25) and 9130'-9138' (9). 1/2% HCL acid. Acidize Bone Spring 9044'-9138' with 750g 7-1/2% HCL with 40 ball 11/15/06 – Frac Bone Spring with 37,928g Delta frac 200 and 37,683# 20/40 white and 4 11/17/06 – Perforate Bone Spring 8036'-8044' (9), 8140'-8144' (5), 8156'-8160' (5), 81' (4). Acidize Bone Spring 8140'-8226' with 1000g 7-1/2% Iron control and 50 balls. Ac 1/2% IC acid and 20 balls. 11/29/06 – Set 5-1/2" 17# cement retainer at 7955'. Squeezed perfs 8036'-8226' with 15 Squeezed off at 1450 psi (good squeeze). Circulated hole clean. 12/1/06 – Drilled out cement retainer. Circulated hole clean. 12/4/06 – Test squeezed off perfs again to 1000 psi, held good. SN at 8947'. | Acidize Bone Spring 9130'-9138' with 300g 7-sealers. 9,000# Expedite total of 86,683# of sand. 20'-8200' (11), 8215'-8218' (4) and 8223'-8226' dize Bone Spring 8036'-8044' with 400g 7-0 sx "H" with .2% FL-62 and 200 sx "H" Neat. |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/9/06 – TOC 2970' Est. Perforate Bone Spring 9044'-9068' (25) and 9130'-9138' (9). 1/2% HCL acid. Acidize Bone Spring 9044'-9138' with 750g 7-1/2% HCL with 40 ball 11/15/06 – Frac Bone Spring with 37,928g Delta frac 200 and 37,683# 20/40 white and 411/17/06 – Perforate Bone Spring 8036'-8044' (9), 8140'-8144' (5), 8156'-8160' (5), 81' (4). Acidize Bone Spring 8140'-8226' with 1000g 7-1/2% Iron control and 50 balls. Ac 1/2% IC acid and 20 balls. 11/29/06 – Set 5-1/2" 17# cement retainer at 7955'. Squeezed perfs 8036'-8226' with 15 Squeezed off at 1450 psi (good squeeze). Circulated hole clean. 12/1/06 – Drilled out cement retainer. Circulated hole clean. 12/4/06 – Test squeezed off perfs again to 1000 psi, held good. SN at 8947'. | Acidize Bone Spring 9130'-9138' with 300g 7-sealers. 9,000# Expedite total of 86,683# of sand. 20'-8200' (11), 8215'-8218' (4) and 8223'-8226' dize Bone Spring 8036'-8044' with 400g 7- 0 sx "H" with .2% FL-62 and 200 sx "H" Neat. |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/9/06 – TOC 2970' Est. Perforate Bone Spring 9044'-9068' (25) and 9130'-9138' (9). 1/2% HCL acid. Acidize Bone Spring 9044'-9138' with 750g 7-1/2% HCL with 40 ball 11/15/06 – Frac Bone Spring with 37,928g Delta frac 200 and 37,683# 20/40 white and 41/17/06 – Perforate Bone Spring 8036'-8044' (9), 8140'-8144' (5), 8156'-8160' (5), 81 (4). Acidize Bone Spring 8140'-8226' with 1000g 7-1/2% Iron control and 50 balls. Ac 1/2% IC acid and 20 balls. 11/29/06 – Set 5-1/2" 17# cement retainer at 7955'. Squeezed perfs 8036'-8226' with 15 Squeezed off at 1450 psi (good squeeze). Circulated hole clean. 12/1/06 – Drilled out cement retainer. Circulated hole clean. 12/4/06 – Test squeezed off perfs again to 1000 psi, held good. SN at 8947'. | Acidize Bone Spring 9130'-9138' with 300g 7-sealers. 9,000# Expedite total of 86,683# of sand. 90'-8200' (11), 8215'-8218' (4) and 8223'-8226' dize Bone Spring 8036'-8044' with 400g 7- 0 sx "H" with .2% FL-62 and 200 sx "H" Neat. |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/9/06 – TOC 2970' Est. Perforate Bone Spring 9044'-9068' (25) and 9130'-9138' (9). 1/2% HCL acid. Acidize Bone Spring 9044'-9138' with 750g 7-1/2% HCL with 40 ball 11/15/06 – Frac Bone Spring with 37,928g Delta frac 200 and 37,683# 20/40 white and 4 11/17/06 – Perforate Bone Spring 8036'-8044' (9), 8140'-8144' (5), 8156'-8160' (5), 81' (4). Acidize Bone Spring 8140'-8226' with 1000g 7-1/2% Iron control and 50 balls. Ac 1/2% IC acid and 20 balls. 11/29/06 – Set 5-1/2" 17# cement retainer at 7955'. Squeezed perfs 8036'-8226' with 15 Squeezed off at 1450 psi (good squeeze). Circulated hole clean. 12/1/06 – Drilled out cement retainer. Circulated hole clean. 12/4/06 – Test squeezed off perfs again to 1000 psi, held good. SN at 8947'. | Acidize Bone Spring 9130'-9138' with 300g 7-sealers. 9,000# Expedite total of 86,683# of sand. 20'-8200' (11), 8215'-8218' (4) and 8223'-8226' dize Bone Spring 8036'-8044' with 400g 7-0 sx "H" with .2% FL-62 and 200 sx "H" Neat. |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/9/06 – TOC 2970' Est. Perforate Bone Spring 9044'-9068' (25) and 9130'-9138' (9). 1/2% HCL acid. Acidize Bone Spring 9044'-9138' with 750g 7-1/2% HCL with 40 ball 11/15/06 – Frac Bone Spring with 37,928g Delta frac 200 and 37,683# 20/40 white and 4 11/17/06 – Perforate Bone Spring 8036'-8044' (9), 8140'-8144' (5), 8156'-8160' (5), 81 (4). Acidize Bone Spring 8140'-8226' with 1000g 7-1/2% Iron control and 50 balls. Ac 1/2% IC acid and 20 balls. 11/29/06 – Set 5-1/2" 17# cement retainer at 7955'. Squeezed perfs 8036'-8226' with 15 Squeezed off at 1450 psi (good squeeze). Circulated hole clean. 12/1/06 – Drilled out cement retainer. Circulated hole clean. 12/4/06 – Test squeezed off perfs again to 1000 psi, held good. SN at 8947'. I hereby certify that the information above is true and complete to the best of my knowledgrade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit SIGNATURE TITLE Regulatory Compliance St. Type or print name Tina Huerta E-mail address: tinah@ypcnm | Acidize Bone Spring 9130'-9138' with 300g 7-sealers. 9,000# Expedite total of 86,683# of sand. 20'-8200' (11), 8215'-8218' (4) and 8223'-8226' dize Bone Spring 8036'-8044' with 400g 7- 0 sx "H" with .2% FL-62 and 200 sx "H" Neat. dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan . pervisor DATE December 14, 2006 com Telephone No. 505-748-1471 |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/9/06 – TOC 2970' Est. Perforate Bone Spring 9044'-9068' (25) and 9130'-9138' (9). 1/2% HCL acid. Acidize Bone Spring 9044'-9138' with 750g 7-1/2% HCL with 40 ball 11/15/06 – Frac Bone Spring with 37,928g Delta frac 200 and 37,683# 20/40 white and 4 11/17/06 – Perforate Bone Spring 8036'-8044' (9), 8140'-8144' (5), 8156'-8160' (5), 81 (4). Acidize Bone Spring 8140'-8226' with 1000g 7-1/2% Iron control and 50 balls. Ac 1/2% IC acid and 20 balls. Ac 1/2% IC acid and 20 balls. 11/29/06 – Set 5-1/2" 17# cement retainer at 7955'. Squeezed perfs 8036'-8226' with 15 Squeezed off at 1450 psi (good squeeze). Circulated hole clean. 12/1/06 – Drilled out cement retainer. Circulated hole clean. 12/4/06 – Test squeezed off perfs again to 1000 psi, held good. SN at 8947'. I hereby certify that the information above is true and complete to the best of my knowled grade tank has been/will be constructed on closed according to NMOCD guidelines , a general permit SIGNATURE | Acidize Bone Spring 9130'-9138' with 300g 7-sealers. 9,000# Expedite total of 86,683# of sand. 90'-8200' (11), 8215'-8218' (4) and 8223'-8226' dize Bone Spring 8036'-8044' with 400g 7- 0 sx "H" with .2% FL-62 and 200 sx "H" Neat. dge and belief. I further certify that any pit or below— or an (attached) alternative OCD-approved plan pervisor DATE December 14, 2006 |