Submit 3 Copies To Appropriate District Office	•	State of New Mexico			Form C-103	
District I	Energy, Minerals and Natural Resources			WELL API NO.	Revised June 10, 2003	
1625 N. French Dr., Hobbs, NM 88240 District II				30-015-	32025	
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			5. Indicate Type of		
District III	1220 South St. Francis Dr.			STATE 🗵		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505			6. State Oil & Gas	Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM				32673		
87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name						
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				Dulce Amor		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH						
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other				8. Well Number		
Oil Well Gas Well	Other	A STA	A "	1		
2. Name of Operator	10000		P 2003 55	9. OGRID Number	<u> </u>	
Nadel and Gussman Permian,	L.L.C.	[St	- F 2000 6)	155615		
3. Address of Operator		ig RE	CEIVED 3	10. Pool name or V	Wildcat	
601 N. Marienfeld, Suite 508		$\sqrt{\omega}$ OCD	~/ l	Undesignate	ed Morrow	
4. Well Location		13	400/			
20 17						
Unit Letter2	:990feet from t	ne_North	S 42 Sime and	1980feet from	theEastline	
Section 4	Township	18S Ra	inge 26E	NMPM Eddy	County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)						
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK	PLUG AND ABAND	ON 🗌	REMEDIAL WOR		ALTERING CASING 🔲	
			COMMENCE DO			
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRII		PLUG AND ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE		CASING TEST AN			
	COMPLETION		CEMENT JOB			
OTHER:			OTHER:			
	mlated amountions (Clar	_		Laire partinant datas	including actimated data	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion						
or recompletion.						
8/26/03						
Spud well @7:30pm						
Drill 17 ½" hole to 436' TD, Survey ½ deg @ 245', circ, POOH to run surface casing.						
8/27/03						
RU casers, RIH w/10 jts (440') 48# 13 3/8" J-55 casing w/ notched collar, circ. on bottom.						
RU Schlumberger, cmt w/171 (100% excess) sx 35/65 pos (12.4#/gal) lead, tail w/180 sx C (14.8#/gal) w/2% CC, circ. 95						
sx cmt to pit, cut off csg, weld on A section, test same to 1000 psi, ok.						
. -						
_	•	ť				
Place	e Woc Ti.	B			•	
I hereby certify that the information			st of my knowledge	and belief		
la 2m						
SIGNATURE OM	5/1/	TITLE	_Drilling Superviso	rDA	TE <u>8/28/03</u>	
Manage and additional and a second a second and a second	4 D	T . 4 44		m-1 1 57	1 '	
	don Barker	E-mail addı	ress:	Telephone No.	432/682-4429	
(This space for State use)	0				SED A A A	
APPPROVED BY FOR RECORDS ONLINE DATE DATE						
Conditions of approval, if any:				-		