	it 3 Copies 10 Appropriate District	State	of New Me	exico			Form C-103
Office <u>Distri</u>	rt_I	Energy, Minera	ils and Natu	ıral Resources		77770	May 27, 2004
1625 î Distric	N. French Dr., Hobbs, NM 88240				WELL A		15-35456
	W. Grand Ave., Artesia, NM 88210	OIL CONSE			5 Indica	ate Type of	
Distric	et III Rio Brazos Rd., Aztec, NM 87410	and the second s	ith St. Frai			TATE	
Distric	et IV	Santa	Fe, NM 87	7508	6. State		Lease No.
1220 S 87505	S. St. Francis Dr., Santa Fe, NM			Month.	1 0-		
		CES AND REPORTS	ON WELLS	OCD 320	70. Lease	Name or	Unit Agreement Name
(DO N	SUNDRY NOTIC FOT USE THIS FORM FOR PROPOSE FRENT RESERVOIR. USE "APPLICATION."	ALS TO DRILL OR TO D	EEPEN OR PL	OU DUCK INCOM	A 1.		Ū
	RENT RESERVOIR. USE "APPLIC OSALS.)	ATION FOR PERMIT" (FO	JRM C-101) FC	OR SUCH "	9		T COOP UNIT
		Gas Well Other			8. Well	Number	152
2. Name of Operator						D Numbe	1
COG Operating LLC 3. Address of Operator						name or V	29137 Wildcat 97558
3. A	550 W. Texas Ave., Suite	e 1300	Midland,	TX 79701	I I		BB-GLORIETA-YESO
4 W	ell Location				33,		
"	Unit Letter D :	990' feet from the	- North	line and 33	O' feet fi	rom the	West line
	Section 21	Township		Range 29	***	MPM	County EDDY
	Section	11. Elevation (Show					County 2001
		<u> </u>	3604 ²			1	
Pit or E	selow-grade Tank Application 🔲 or	Closure 🛛					
Pit type	DRILLING Depth to Ground	dwater <u>110'</u> Distanc	e from nearest	fresh water well_	1000'_ Distance	from neares	st surface water 1000'
Pit Line	er Thickness: 12 mil	Below-Grade Tank: Volu	me	bbls; Constr	uction Material		
	12. Check A	ppropriate Box to	Indicate N	ature of Noti	ce. Report of	Other D	Data
					•		
DEDE	NOTICE OF INT	. .			UBSEQUE		
	FORM REMEDIAL WORK PORARILY ABANDON	PLUG AND ABANDO CHANGE PLANS	=	REMEDIAL W	/ORK DRILLING OPI		ALTERING CASING
	OR ALTER CASING	MULTIPLE COMPL		CASING/CEM		13.∐ F	P AND A
1 OLL	OIT ALTER CASING	WOLTH LL COMPL		CASING/CEIV	ILIVI JOB	ш	
OTHE				OTHER:			
	. Describe proposed or comple		rly state all p	ertinent details			
	. Describe proposed or comple of starting any proposed work		rly state all p	ertinent details			
	. Describe proposed or comple		rly state all p	ertinent details			
	. Describe proposed or comple of starting any proposed work or recompletion.		rly state all p For Multipl	ertinent details e Completions:	Attach wellbo	ore diagran	
13	Describe proposed or comple of starting any proposed work or recompletion. COC	k). SEE RULE 1103.	rly state all p For Multipl	ertinent details e Completions:	Attach wellbo	ore diagran	
	. Describe proposed or comple of starting any proposed work or recompletion.	k). SEE RULE 1103.	rly state all p For Multipl	ertinent details e Completions:	Attach wellbo	ore diagran	
13	Describe proposed or comple of starting any proposed work or recompletion. COC Remove fluids from pit.	k). SEE RULE 1103. G Operating LLC pro	rly state all p For Multipl oposes to c	pertinent details e Completions: lose the drillin	Attach wellbo	ore diagran	n of proposed completion
13	Describe proposed or complet of starting any proposed work or recompletion. COO Remove fluids from pit. A deep trench pit will be considered.	k). SEE RULE 1103. G Operating LLC pro	rly state all p For Multipl oposes to c see existing re	ertinent details e Completions: lose the drillin eserve pit and	Attach wellbog pit as follow	ore diagrans: s: 2 mil line	n of proposed completion
13 1. 2.	Describe proposed or complet of starting any proposed work or recompletion. COO Remove fluids from pit. A deep trench pit will be contents will be encaped.	k). SEE RULE 1103. G Operating LLC propositionstructed next to the osulated in this pit ar	rly state all p For Multipl oposes to c se existing rand the liner	ertinent details e Completions: lose the drillin eserve pit and will be folded	Attach wellbo g pit as follow I lined with a 1 over the mud	ore diagran s: 2 mil line and cuttir	n of proposed completion
13	Describe proposed or complet of starting any proposed work or recompletion. COO Remove fluids from pit. A deep trench pit will be contents will be encaped. Cover liner with 20 mil lines.	k). SEE RULE 1103. G Operating LLC propositive to the posulated in this pit are rewith excess of 3' or	rly state all p For Multipl oposes to c se existing rand the liner	ertinent details e Completions: lose the drillin eserve pit and will be folded	Attach wellbo g pit as follow I lined with a 1 over the mud	ore diagran s: 2 mil line and cuttir	n of proposed completion
13 1. 2.	Describe proposed or complet of starting any proposed work or recompletion. COO Remove fluids from pit. A deep trench pit will be contents will be encaped.	k). SEE RULE 1103. G Operating LLC propositive to the posulated in this pit are rewith excess of 3' or	rly state all p For Multipl oposes to c se existing rand the liner	ertinent details e Completions: lose the drillin eserve pit and will be folded as per option I	Attach wellbog pit as follow I lined with a 1 over the mud V.B.3.(b) of th	ore diagran s: 2 mil line and cuttir	n of proposed completion er. ngs.
1. 2. 3.	Describe proposed or complet of starting any proposed work or recompletion. COO Remove fluids from pit. A deep trench pit will be contracted to the contents will be encapted to the contents with 20 mil lines. Pit and Below-Grade Tank	constructed next to the osulated in this pit are with excess of 3' of K Guidelines.	rly state all p For Multipl oposes to c se existing rand the liner	ertinent details e Completions: lose the drillin eserve pit and will be folded as per option I	Attach wellbog pit as follow I lined with a 1 over the mud V.B.3.(b) of the	ore diagran s: 2 mil line and cuttir	n of proposed completion er. ngs.
13 1. 2.	Describe proposed or complet of starting any proposed work or recompletion. COO Remove fluids from pit. A deep trench pit will be contents will be encaped. Cover liner with 20 mil lines.	constructed next to the osulated in this pit are with excess of 3' of K Guidelines.	rly state all p For Multipl oposes to c se existing rand the liner	ertinent details e Completions: lose the drillin eserve pit and will be folded as per option I Notify OC pit closure	Attach wellboom g pit as follow I lined with a 1 over the mud V.B.3.(b) of the	ore diagrands: 2 mil line and cuttire ior to beg	n of proposed completion er. ngs.
1. 2. 3.	Describe proposed or complet of starting any proposed work or recompletion. COO Remove fluids from pit. A deep trench pit will be contracted to the contents will be encapted to the contents with 20 mil lines. Pit and Below-Grade Tank	constructed next to the post are with excess of 3' of K Guidelines.	rly state all p For Multipl oposes to cone existing rend the liner on all sides a	ertinent details e Completions: lose the drillin eserve pit and will be folded as per option I Notify OC pit closure Samp pit at	Attach wellboom Attach wellboo	ore diagram s: 2 mil line and cuttir ne ior to beg	n of proposed completion er. ngs.
1. 2. 3. 4.	Describe proposed or complete of starting any proposed work or recompletion. COO Remove fluids from pit. A deep trench pit will be contents will be encapted to contents will be encapted and Below-Grade Tank Cover with a minimum 3' or c	constructed next to the post are with excess of 3' of K Guidelines.	rly state all p For Multipl oposes to cone existing rend the liner on all sides a	ertinent details e Completions: lose the drillin eserve pit and will be folded as per option I Notify OC pit closure Samp pit at	Attach wellboom Attach wellboom Attach wellboom Britans follow I lined with a 1 over the mud V.B.3.(b) of the D 24 hours properties are to be obtained.	ore diagram s: 2 mil line and cuttir ne ior to beg	n of proposed completion er. ngs.
1. 2. 3.	Describe proposed or complete of starting any proposed work or recompletion. COO Remove fluids from pit. A deep trench pit will be contents will be encapted to contents will be encapted and Below-Grade Tank Cover with a minimum 3' or c	constructed next to the post are with excess of 3' of K Guidelines.	rly state all p For Multipl oposes to cone existing rend the liner on all sides a	ertinent details e Completions: lose the drillin eserve pit and will be folded as per option I Notify OC pit closure Samp pit at	Attach wellboom Attach wellboo	ore diagram s: 2 mil line and cuttir ne ior to beg	n of proposed completion er. ngs.
1. 2. 3. 4. 5.	Describe proposed or complet of starting any proposed work or recompletion. COO Remove fluids from pit. A deep trench pit will be constant will be encapted to any cover liner with 20 mil lines Pit and Below-Grade Tank Cover with a minimum 3' of Contour pit to prevent eros	constructed next to the postructed in this pit are with excess of 3' of a Guidelines. If native soil.	rly state all p For Multipl oposes to cone existing mend the liner on all sides a	ertinent details e Completions: lose the drillin eserve pit and will be folded as per option I Notify OC pit closure Samp pit an NMO	Attach wellboom Attach wellboom Attach wellboom Brit as follow I lined with a 1 over the mud V.B.3.(b) of the D 24 hours prepotes are to be obtained and analysis successful prior to back	ore diagram s: 2 mil line and cuttir le ior to beg ined from abmitted to -filling	n of proposed completion or. ngs.
1. 2. 3. 4. 5.	Describe proposed or complete of starting any proposed work or recompletion. COO Remove fluids from pit. A deep trench pit will be encapted to contents will be encapted and Below-Grade Tank Cover with a minimum 3' of Contour pit to prevent erosty certify that the information above.	constructed next to the post and the sulated in this pit are with excess of 3' of a Guidelines. If native soil.	rly state all p For Multipl oposes to co ne existing rand the liner on all sides a rainwater.	ertinent details e Completions: lose the drillin eserve pit and will be folded as per option I Notify OC pit closure Samp pit an NMO	g pit as follow I lined with a 1 over the mud V.B.3.(b) of the D 24 hours presented and analysis succeeding to back	ore diagram s: 2 mil line and cuttir le ior to beg ined from bibmitted to filling	or of proposed completion of proposed completion or. In a serior of proposed completion of
1. 2. 3. 4. 5.	Describe proposed or complet of starting any proposed work or recompletion. COO Remove fluids from pit. A deep trench pit will be constant will be encapted to any cover liner with 20 mil lines Pit and Below-Grade Tank Cover with a minimum 3' of Contour pit to prevent eros	constructed next to the post and the sulated in this pit are with excess of 3' of a Guidelines. If native soil.	rly state all p For Multipl oposes to co ne existing rand the liner on all sides a rainwater.	ertinent details e Completions: lose the drillin eserve pit and will be folded as per option I Notify OC pit closure Samp pit an NMO	g pit as follow I lined with a 1 over the mud V.B.3.(b) of the D 24 hours presented and analysis succeeding to back	ore diagram s: 2 mil line and cuttir le ior to beg ined from bibmitted to filling	or of proposed completion of proposed completion or. In a serior of proposed completion of
1. 2. 3. 4. 5. I hereby	Describe proposed or complete of starting any proposed work or recompletion. COO Remove fluids from pit. A deep trench pit will be constructed or contents will be encapted and Below-Grade Tank Cover with a minimum 3' of Contour pit to prevent erose of certify that the information about his has been/will be constructed or clean.	constructed next to the post and the sulated in this pit are with excess of 3' of a Guidelines. If native soil.	rly state all p For Multipl oposes to co ne existing rand the liner on all sides a rainwater.	ertinent details e Completions: lose the drillin eserve pit and will be folded as per option I Notify OC pit closure Samp pit an NMO	Attach wellboom Attach wellboom Below I lined with a 1 over the mud V.B.3.(b) of the D 24 hours proposed and analysis succeeding and analysis succeeding to back bedge and belief to or an (attached)	s: 2 mil line and cuttir te ior to beg ined from abmitted to filling	or of proposed completion of proposed completion or. In a serior of proposed completion of
13 1. 2. 3. 4. 5. I hereby grade tai	Describe proposed or complete of starting any proposed work or recompletion. COO Remove fluids from pit. A deep trench pit will be constructed or close the contents will be encaped to the contents with 20 mil line. Pit and Below-Grade Tank Cover with a minimum 3' of Contour pit to prevent erose of certify that the information about his has been/will be constructed or close to the	G Operating LLC proposed according to NMOCI	rly state all p For Multipl oposes to cone existing rand the liner on all sides a rainwater. etc to the become to	ertinent details e Completions: lose the drillin eserve pit and will be folded as per option I Notify OC pit closure Samp pit an NMO st of my knowle l, a general permit Regulatory A	Attach wellboom and the second and analysis support to backer analysis	s: 2 mil line and cuttir te ior to beg ined from abmitted to filling I further o	or of proposed completion or. ngs. certify that any pit or below- ve OCD-approved plan ATE 5-2-07
1. 2. 3. 4. 5. I hereby grade tan SIGNA	Describe proposed or complete of starting any proposed work or recompletion. COO Remove fluids from pit. A deep trench pit will be constructed or close the contents will be encaped to the contents with 20 mil line. Pit and Below-Grade Tank Cover with a minimum 3' of Contour pit to prevent erose or certify that the information about his has been/will be constructed or close the constructed or	constructed next to the post and the sulated in this pit are with excess of 3' of a Guidelines. If native soil.	rly state all p For Multipl oposes to cone existing rand the liner on all sides a rainwater. etc to the become to	ertinent details e Completions: lose the drillin eserve pit and will be folded as per option I Notify OC pit closure Samp pit an NMO st of my knowle l, a general permit Regulatory A	Attach wellboom and the property of the second and analysis support of the property of the pro	s: 2 mil line and cuttir te ior to beg ined from abmitted to filling I further o	or of proposed completion of proposed completion or . The completion of proposed completion or . The completion of proposed completion or . The completion of proposed completion or .
1. 2. 3. 4. 5. I hereby grade tan SIGNA	Describe proposed or complete of starting any proposed work or recompletion. COO Remove fluids from pit. A deep trench pit will be constructed or close the contents will be encaped to the contents with 20 mil line. Pit and Below-Grade Tank Cover with a minimum 3' of Contour pit to prevent erose of certify that the information about his has been/will be constructed or close to the	G Operating LLC proposed according to NMOCI	rly state all p For Multipl oposes to cone existing rand the liner on all sides a rainwater. etc to the become to	ertinent details e Completions: lose the drillin eserve pit and will be folded as per option I Notify OC pit closure Samp pit an NMO st of my knowle l, a general permit Regulatory A	Attach wellboom and the property of the second and analysis support of the property of the pro	s: 2 mil line and cuttir te ior to beg ined from abmitted to filling I further o	or of proposed completion or. ngs. certify that any pit or below- ve OCD-approved plan ATE 5-2-07
13 1. 2. 3. 4. 5. I hereby grade tan SIGNA Type on For Sta	Describe proposed or complete of starting any proposed work or recompletion. COO Remove fluids from pit. A deep trench pit will be constructed or close the contents will be encaped to the contents with 20 mil line. Pit and Below-Grade Tank Cover with a minimum 3' of Contour pit to prevent erose or certify that the information about his has been/will be constructed or close the constructed or	G Operating LLC proposed according to NMOCI	rly state all p For Multipl oposes to cone existing rand the liner on all sides a rainwater. etc to the become to	ertinent details e Completions: lose the drillin eserve pit and will be folded as per option I Notify OC pit closure Samp pit an NMO st of my knowle l, a general permit Regulatory A	Attach wellboom and the property of the second and analysis support of the property of the pro	ore diagram s: 2 mil line and cuttir le ior to beg ined from abmitted to filling Telephon	or of proposed completion or. ngs. certify that any pit or below- ve OCD-approved plan ATE 5-2-07