Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103
District I	Energy, Minerals and Natural Resources		May 27, 2004 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II	0.31		30-015-30284
1301 W. Grand Ave., Artesia, NM	OHISONSERVATION	DIVISION And And	5. Indicate Type of Lease
District III	030H7SONSERVATION 1220 South St. Fran	cis Dr. 2 2 2007	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 77 10	Santa Fe, NM 87	505 MAY 3 2 2007	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa 7 87505			
SUNDAY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PRODUCTION FOR PERMIT" (FORM C-101) FOR SUCH		Barclay Federal	
PROPOSALS)			8. Well Number
1. Type of Well: Oil Well Officer Other			19
2. Name of Operator Forest Oil Corporation			9. OGRID Number 8041
3. Address of Operator		10. Pool name or Wildcat	
707 17 th Street, Suite 3600, Denver, Colorado		Livingston Ridge South (Delaware)	
4. Well Location			
Unit Letter: B feet from the 700 line and North feet and 2100 from the East line			
Section 12	Township 23S Range		IMPM County Eddy
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3490'			
Pit or Below-grade Tank Application or Closure			
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water			
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK			
TEMPORARILY ABANDON		LING OPNS.□ PAND A □	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB			JOB 🔲
OTHER.		OTHER: Burns F	
OTHER:		OTHER: Pump F	kepair <u>⊠</u>
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
4-30-07 RU PU, lay down unit well head, POH rods & Pmp, run happy tool to 2500' POH happy tool. Run back in hole w/swab cups			
to 2500' to clean paraffin. POH swab cups.			
5-01-07 Pick up pmp & pick up K-bars, replace 2 1.5 K-Bars, RIh w/rods, hung well head, waited for Pmp truck. Load tbg w/36 bbls			
wtr. Press to 500#, lost 400# in 2 min. POH rods, pmp lay down K-Bars, 5-02-07 ND WH BOP, change rams on BOP from 2 3/8" to 2 7/8", RU tong & floor.			
5-03-07 POH tbg & tally tbg, rig up tbg tester, test TAC, had a crack on mandral, replace 5 ½" TAC & 2 7/8" seat nipple, & 2 7/8"			
collar, RBIH. Rig down tbg tester, set TAC ND BOP NU WH pick up new Pmp & replace 26-K shear tool. RBIH w/rods.			
Like 3 stands & PR to finish			•
5-04-07 Pick up subs & polish rod & PRL, hung well head, RU Crain Pmp trk load tbg w/28 bbls wtr. Press to 500# hold good. RD			
Pmp Truck. Clean Location	l .		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-			
grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.			
SIGNATURE -	TITLE ST	Regulatory Tech	DATE 5 17 07
SIGNATURE	THLE ST.	Regulatory rech	DATE 5-17-07
Type or print name <u>Cindy Bush</u>	E-mail address: cabush(forestoil.com	Telephone No. 303-812-1554
For State Use Only			
APPROVED BY: FOR RECORDS ONLY TITLE MAY 2 3 2007			
APPROVED BY: TITLE DATE DATE Conditions of Approval (if any):			

Conditions of Approval (if any):