Form 3160-5 (September 2001)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or re enter an

Month - Year MAY 2 5 2007 OCD - ARTESIA

FORM APPROVED OMB No. 1004-0135 Expires January 31, 2004

b. Lease Serial No.	
NM-28297	
6. If Indian, Allottee or Tribe Name	

abandoned well. Use Form 3160-3 (APD) for such proposals.  SUBMIT IN TRIPLICATE - Other instructions on reverse side				6. If Indian, Allottee or Tribe Name		
				7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well	[]					
Oil Well X Gas	s Well Other			8. Well Name and	No.	
2. Name of Operator				Everette OO	Federal #1	
Yates Petroleum Corporation				9. API Well No.		
3a. Address				30-005-60820		
105 S. 4th Str., Artesia, NM 88210 505-748-1471  ocation of Well (Footage, Sec., T., R., M., OR Survey Description)				10. Field and Pool, or Exploratory Area Pecos Slope; Abo		
4. Location of Well (Footage, Sec., F., K., M.,	, ON durvey Description)			11. County or Paris		
1980'FNL & 660'FWL of Section 25-T5S-R24E (UNIT E, SWNW)				Chaves County, New Mexico		
	RIATE BOX(ES) TO IN		OF NOTICE, R	<del></del>		
TYPE OF SUBMISSION			E OF ACTION			
	Acidize	Deepen	Production	(Start/Resume)	Water Shut-Off	
Notice of Intent	Alter Casing	Fracture Treat	Reclamatio	n	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	e	Other	
Subsequent Report	Change Plans	X Plug and Abandon	Temporaril	y Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disp	Water Disposal		
13. Describe Proposed of Completed Operation (cl	learly state all pertinent details, inclu	iding estimated starting date of a	ny proposed work and a	approximate duration the	reof	
Yates Petroleum Corporation p. 1. Rig up safety equipment as 2. Set a CIBP at 3866' with 35' 3. Spot a 25 sx Class "C" ceme 4. Perforate and spot a 40 sx C inside and outside the casing 5. Perforate and spot a 55 sx C inside and outside the casing 6. Perforate at 60' and circulate 7. Remove all surface equipment	plans to plug and aban needed. No casing re cement on top. This plant plug from 3566'-36 Class "C" cement plug g. WOC and tag plug Class "C" cement plug g. WOC and tag plug e a 45 sx Class "C" ce ent, weld dry hole mark	covery will be attem puts a plug over the 666'. This puts 100' from 1525'-1625'. To from 396'-496'. Thi ment plug from 60' uker and clean location	pted. Abo perforation plug across the control of the puts 100' of the surfactor as per regularity.	e top of the Ab plug across the  g across surfa  ce, inside and	e top of the Glorieta	
14. I hereby certify that the foregoing is true Name (Printed/Typed)	e and correct					
Tina H	uerta	Title Reg	ulatory Compl	iance Supervis	sor	
Signature (	Lista	Date <b>Ma</b> y	24, 2007			
	THIS SPACE FO	OR FEDERAL OR STATI	OFFICE USE			
Approved by		Title		Date	e	
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduct	uitable title to those rights in th		ce			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

WELL NAME: Everette OO Fed Com #1 FIELD: Pecos Slope Abo LOCATION: 1980' FNL & 660' FEL of Section 25-5S-24E Chaves Co., NM GL: 3,911.9' GR ZERO: KB:\_\_\_\_\_ CASING PROGRAM SPUD DATE: 1/8/81 \_\_COMPLETION DATE: \_\_2/19/81 **COMMENTS**: API # 30-005-60820 13-5/8" 48# 446' 4,280' 5-1/2" 14# 17 1/2" Hole **BEFORE** 13-5/8" @ 446' Tops: w/ 450 sx cmt (circ) San Andres 790' 1575' Glorieta Abo 3616 WC 4374' TOC @ 2,700' (temp survey) 7 7/8" Hole Accepted for record Abo perfs: 3,916'-3,936' (40) Abo perfs: 4,045'-4,051' (12) Not to Scale 3/1/07 5-1/2" @ 4,280' **MMFH** w/400 sx PBTD:4,280'

TD: 4,450'

