Form 3160-5 (August 1999)

1a. Type of Well

## UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APROVED OMB NO 1004-0135

EXPIRES. NOVEMBER 30, 2000 SUNDRY NOTICES AND REPORTS ON WELLS Lease Serial No LC-070678-A Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals 6 If Indian, Allottee or Tribe Name SUBMIT IN TRIPLICATE Unit or CA Agreement Name and No. Oil Well Gas Well Other \_ 8 Well Name and No 2 Name of Operator Hawk 8 O Federal 9 **DEVON ENERGY PRODUCTION COMPANY, LP** 9. API Well No 3 Address and Telephone No 30-015-29069 20 North Broadway, Ste 1500, Oklahoma City, OK 73102 405-552-8198 10. Field and Pool, or Exploratory Red Lake; QGB-San Andres-Glorieta-Yeso,NE 4 Location of Well (Report location clearly and in accordance with Federal requirements)\* 990 FSL 1885 FEL 12 County or Parish 13 State O 8 18S 27E NM Eddy CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OS SUBMISSION TYPE OF ACTION Production (Start/Resume) Water Shut-Off Deepen Acidize Notice of Intent Fracture Treat Reclamation Well Integrity Alter Casing ✓ Other Recompletion Subsequent Report Casing Repair New Construction Recomplete Change Plans Plug and Abandon Temporarily Abandon & Downhole Final Abandonment Notice ☐ Water Disposal Commingling J Plug Back Convert to Injection Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal deepen directionally or recomplete horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection) 09/28/06 MIRU PU. 10/01/06 RIH with bit Tagged BTM at 2068' TOOH Shut well in. 10/02/06 Drilled out FC & FS. Drilling in open hole. 10/08/06 Drilled 4 3/4" hole to 3413', TD. Circ hole and clean 10/11/06 MIRU RIH with tubing, packer, and perf subs 10/12/06 Acidize well with 4500 gallons 20% HCL, 1900 gallons 20% retarded acid, and 16,900 gallons flush. 10/15/06 Flow well back Swab well 10/16/06 Release packer and perf subs and POOH RIH with production tubing to 3139' Shut well in. 10/17/06 RIH with pump and rods. RDMO PU. 10/25/06 Hung well on and started pumping. 10/26/06 - 11/22/06 Problems keeping well pumping POOH with pump and rod. Swab well RIH with pump and rods. Put back on production The San Andres and Yeso zones in this well are downhole commingled per pre-approved order PC-1108 and order DHC-2458 Thereby certify that the foregoing is true and correct Name Norvella Adams

Title _	Sr. Staff Engineering Technician	Date	6/18/2007
Title		Date	

n on Reverse Side