State of New Mexico Energy Minerals and Natural Resources

For drilling and production facilities, submit to appropriate NMOCD District Office.
For downstream facilities, submit to Santa Fe

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

office

Form C-144 June 1 2004

Pit or 1	<u>Below-</u>	Grade	Tank	Regist	tration	or C	Closure

	or below-grade tank 🛛 Closure of a pit or below-			
Operator MCKAY OIL CORPORATION Telepi Address. PO Box 2014 Roswell, NM 88202-2014 Facility or well name: LL&E B Federal #5 API #30 COUNTY CHAVES Latitude Longitude	none: _505-6223-4735 e-mail address _jennifer@r	nckayoil.com AUG 0 3 22		
Address. PO Box 2014 Roswell, NM 88202-2014	K / 2001 - 111 - 0.10 - 0.10	OCD 2007		
Facility or well name: LL&E B Federal #5 API #3	763/3 U/L or Qtr/Qtr O Sec I	T 6S R 22E ARTESIA		
County CHAVES Latitude Longitude	NAD 1927 [] 1983 [] Surfa	ce Owner Federal 🛛 State 📋 Private 📋 Indian 📋		
Pit	Below-grade tank			
Type Drilling Production Disposal	Volumebbl Type of fluid ⁻			
Workover ☐ Emergency ☐	Construction material			
Lined 🛮 Unlined 🗌	Double-walled, with leak detection? Yes If not, explain why not			
Liner type Synthetic 🔀 Thickness 12 mil Clay 🗌				
Pit Volumebbl				
Depth to ground water (vertical distance from bottom of pit to seasonal	Less than 50 feet	(20 points)		
high water elevation of ground water)	50 feet or more, but less than 100 feet	(10 points)		
migh water elevation of ground water)	100 feet or more	(<u>0 points)</u>		
Wellback and an execution and the second sec	Yes	(20 points)		
Wellhead protection area (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)	No.	(0 points)		
water source, or less than 1000 feet from an other water sources.)	Loss than 200 feet	(20		
Distance to surface water (horizontal distance to all wetlands, playas,	Less than 200 feet	(20 points)		
irrigation canals, ditches, and perennial and ephemeral watercourses)	200 feet or more, but less than 1000 feet 1000 feet or more	(10 points)		
	1000 feet or more	(0 points)		
	Ranking Score (Total Points)	0		
If this is a pit closure: (1) attach a diagram of the facility showing the pit	s relationship to other equipment and tanks (2) Inc	dicate disposal location (check the onsite box if		
your are burying in place) onsite \(\square\) offsite \(\square\) If offsite, name of facility_				
remediation start date and end date (4) Groundwater encountered No				
Attach soil sample results and a diagram of sample locations and excavation				
Additional Comments A plan of reserve pit remediation is attached.				
I hereby certify that the information above is true and complete to the best been/will be constructed or closed according to NMOCD guidelines Date 8/2/2007	t of my knowledge and belief. I further certify th , a general permit , or an (attached) alternal	at the above-described pit or below-grade tank ha tive OCD-approved plan □.		
Printed Name/Title James L. Schultz, Agent	Signature Almy			
Your certification and NMOCD approval of this application/closure does		ents of the nit or tank contaminate ground water or		
otherwise endanger public health or the environment. Nor does it relieve regulations				
Approval	,	AIT A P ASS		
i uskinim	Signature Ginning III	AUG W 6 2007		
TIFY OCD 24 HOURS PRIOR to If burial trench is t		much		
nning closure and 24 HOURS PRIOR in pit area, sample taining samples. Samples are to be and analyses submined from pit area and analyses PRIOR to lining to		3' of clean top soil is		

NO begi to o , obta submitted to OCD prior to back-filling.



Reserve Pit Remediation Plan

LL&E B Federal #5 990'FSL & 1980'FEL Sec. 1, T6S, R22E

- 1. Collect soil samples from the walls of the reserve pit as shown on attached plat (from surface to depth reading 250 ppm chlorides).
- 2. Pile cuttings and original pit liner to one side of reserve pit.
- 3. Collect soil samples from inside the pit on the cleared side of reserve pit (trench area) at surface.
- 4. Dig trench in cleaned out side of the pit, big enough to put all of the cuttings in and leave enough room for 3' backfill material. (NOTE: Trench size depends on amount of cuttings, rock formations, surrounding terrain and mud solidity.)
- 5. Collect soil samples from inside trench area to a depth reading 250 ppm chloride.
- 6. Line trench with 20 MIL liner.
- 7. Fill the trench with cuttings and original pit liner.
- 8. Cap trench with 20 MIL liner.
- 9. Collect soil samples from points within the reserve pit (not including the trench area which were collected in Step 5) as shown on attached plat from surface to depth reading 250 ppm chlorides.
- 10. Back fill area (trench -3' and reserve pit -1') with topsoil.
- 11. Seed area per BLM specifications.



