\$/13/2003 Drilled out cement from 3230' to 3360'. Cement was firm but not hard (22,000# at 1.5 min./ft).

8/14/2003 Slide and time drill off of kick-off plug from 3360' to 3379'.

8/15/2003 Time drilled off plug from 3379' to 3384'.

8/24/2003 R/U Sholumberger and ran a PLat Form Express, logger TD was 8504', had a tight spot at 3400'. Follow with a FMI, would not go past spot at 3400'. R/D loggers. TOC L/D drill string to run 7" casing.

8/25/2003 R/U and ran 7" production casing. Van Barton with OCD was notified but, didnot wittness.
8/25/2003 R/U BJ Services and cemented 7" in two stages. Pumped 30 bbls of Turbo Flow III @ 11 ppg. 190 sacks of (15:61:11) Poz(Fly Ash): Class "C" + add at 13.4 ppg, 1.55 Second stage pumped 50 bbls of fresh water @ 8.40 ppg, 400 sacks of (60:40) Poz(Fly Ash): Class "C" + add at 13.80 ppg, 1.34 yield. ECP set, circulated 80 sacks off the stage to the pits. Stage tool closed and plug was down at 11:34, 08/24/2003 Plug bumped and hell. R/D BJ Services. N/D BOP, set slips on 7" casing, jet and cleaned pits. released at 06:00, 08/25/2003.