Form 3160-5 (April 2004)

1. Type of Well

2. Name of Operator

3a Address

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

Other

Gas Well

Pogo Producing Company

P.O. Box 10340, Midland, TX 79702

4 Location of Well (Footoge Sec. T. R. M. or Survey Description)

determined that the site is ready for final inspection.)

FORM APPROVED
OM B No. 1004-0137
Expires: March 31, 2007

7. If Unit or CA/Agreement, Name and/or No.

Lease Serial No.	
M-38463	

8. Well Name and No.

9. API Well No. 30-015-35300

6.	If Indian, Allottee or Tribe 1	Name
----	--------------------------------	------

Pure Gold B Federal #10

10. Field and Pool, or Exploratory Area

Sand Dunes Delaware West

760' FNL & 370' FEL, Section 20, T23S, R31E					11. County or Parish, State Eddy County, NM		
12. CHECK A	PPROPRIATE BOX(ES) T	O INDICATE NATUR	E OF NOTICE, RI	EPORT, OF	R OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent  Subsequent Report  Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Statement of Statement of Statem	,	Water Shut-Off Well Integrity  Other dirg operations		
13. Describe Proposed or Comple	ted Operation (clearly state all p	ertinent details, including esti	mated starting date of an	y proposed w	ork and approximate duration thereof		

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has

3b. Phone No (include area code)

432-685-8100

Intermediate Csg - Drld 11" hole to 4035'. TD reached @ 03:00 hrs 07/28/07. Ran 95 jts 8-5/8" 32# J-55 LT&C csg. Cmt'd w/ 1100 sks 35:65 POZ C followed by 200 sks CI C + 1% CaCl2. Plug down @ 03:30 hrs 07/28/07. Circ 220 sks to surface. WOC 24 hrs. Make cut-off. Install WH. NU BOP's & test to 1000#. Test csg to 1000# for 30 mins ok.

TD & Production Csg - Drld 7-7/8" hole to 8100'. TD reached @ 21:00 hrs 08/03/07. Logged well w/ Halliburton. Ran 193 jts 5-1/2" 15.5# & 17# J-55 LT&C csg. Cmt'd 1st stage w/ 500 sks CI C + add. Circ 119 sks to surface. Cmt'd 2nd stage w/ 800 sks CI C + add. Circ 175 sks to surface. Cmt'd 3rd stage w/ 250 sks 65:35 POZ C followed by 200 Cl C + 2% CaCl2. Circ 26 sks to surface. Test csg to 2500# ok. Ran CBL 08/11/07.

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Cathy Wright Title Sr. Eng. Tech Signature Date 08/27/07 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Date Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.