

United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Roswell Field Office 2909 West Second Street Roswell, New Mexico 88202

AUG 13 2007 OCD-ARTESIA

In Reply Refer To: 3162.4 (513) NM-29623

AUG 1 0 2007

Yates Petroleum Corporation Attn: Debbie Caffall 105 S 4th Street Artesia, NM 88210

30 005 63770

Dear Ms. Caffall:

The Bureau of Land Management is canceling your Application for Permit to Drill (APD) for the Filaree AEL Federal No. 6, located in Section 26, T. 8 S., R. 26 E., 1650' FSL & 1650' FEL, approved on September 7, 2005, along with the extension approved on August 22, 2006, due to receiving another application.

If you have any question, please contact Alexis C. Swoboda, Petroleum Engineer, at (505) 627-0228.

Sincerely, /S/ Angel Mayes

Angel Mayes Assistant Field Manager Lands and Minerals

cc: I&E

I & E (RFO) NMOCD (Artesia)

	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N French Dr., Hobbs, NM-88240	 -	WELL API NO.
District II 1301 W Grand Ave., Artesia, NM 88210 a	OIL CONSERVATION DIVISION	30-015-31133
District III	1220 South St. Francis Dr.	5. Indicate Type of Leasc
1000 Rio Brazos Rd , Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE
<u>District IV</u> 1220 S St Francis Dr , Santa Fe, NM	Saina Pe, INIVI 67303	6. State Oil & Gas Lease No.
87505		
SUNDRY NOTIC	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR USE "APPLIC. PROPOSALS)	ATION FOR PERMIT" (FORM C-101) FOR SUCH	Adobe Flat 18D State Com
1. Type of Well: Oil Well	Gas Well 🔯 Other	8. Well Number
	JUN 2 5 2007	1
2. Name of Operator	JOIN 5 2 5001	9. OGRID Number
Samson Resources Company	OCD-ARTESIA	20165
3. Address of Operator	<u> </u>	10. Pool name or Wildcat
200 N. Loraine St., Ste. 1010; Midla	and, TX 79701	Catclaw Draw (Strawn)
4. Well Location		
Unit Letter D:	660 feet from the <u>North</u> line and <u>6</u>	660 feet from the West line
Section 18	Township 21S Range 26F	NMPM Eddy County
	11 Flevation (Show whether DR RKR RT GR etc.	.)
	11. Elevation (Show whether DR, RKB, RT, GR, etc 3264' GR	THE PERSON NAMED AND POST OF
Pit or Below-grade Tank Application or	Closure	Supplied to 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
	Distance from nearest fresh water well Distance	oo fuom nonvort ourfo oo waten
Pit Liner Thickness: mil	Below-Grade Tank: Volume bbls; C	onstruction Material
12. Check A	ppropriate Box to Indicate Nature of Notice,	Report or Other Data
		•
NOTICE OF INT		SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK 🗌	PLUG AND ABANDON 🛛 REMEDIAL WO	RK 🔲 ALTERING CASING 🗌
TEMPORARILY ABANDON 🔲	CHANGE PLANS COMMENCE DR	RILLING OPNS. 🗌 P AND A 🔲
	MULTIPLE COMPLETE	
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEMEN	NT JOB 🔲
PULL OR ALTER CASING [_] OTHER:	MOLTIPLE COMPL CASING/CEMEN	NT JOB
OTHER:		
OTHER:	OTHER:	nd give pertinent dates, including estimated date
OTHER:	OTHER:eted operations. (Clearly state all pertinent details, an	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work.	OTHER:eted operations. (Clearly state all pertinent details, an	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion. Estimated start date: 7/	OTHER: eted operations. (Clearly state all pertinent details, and rest.). SEE RULE 1103. For Multiple Completions: A	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to	OTHER: eted operations. (Clearly state all pertinent details, and recompletions: A 23/07 o 1000#. Dump 35' cement.	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circle	OTHER: eted operations. (Clearly state all pertinent details, and the completions: A 23/07 0 1000#. Dump 35' cement. ulate hole w/9.5 ppg mud laden fluid	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circ POH. GIH w/2 3/8" tubing	OTHER: eted operations. (Clearly state all pertinent details, and the completions: A 23/07 0 1000#. Dump 35' cement. ulate hole w/9.5 ppg mud laden fluid	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circle POH. GIH w/2 3/8" tubing	OTHER:	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circle POH. GIH w/2 3/8" tubing Spot cement plugs: 8650' - 8550'- TAC	OTHER: eted operations. (Clearly state all pertinent details, and which is the completions: A see that the completions of the completion of	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circle POH. GIH w/2 3/8" tubing Spot cement plugs: 8650' - 8550'- 1866-1860' - 6050' - 5950'	OTHER: eted operations. (Clearly state all pertinent details, and its). SEE RULE 1103. For Multiple Completions: A 23/07 o 1000#. Dump 35' cement. ulate hole w/9.5 ppg mud laden fluid	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circle POH. GIH w/2 3/8" tubing Spot cement plugs: 8650' - 8550'- 1866-1860' - 6050' - 5950'	OTHER: eted operations. (Clearly state all pertinent details, and its). SEE RULE 1103. For Multiple Completions: A 23/07 o 1000#. Dump 35' cement. ulate hole w/9.5 ppg mud laden fluid	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circle POH. GIH w/2 3/8" tubing Spot cement plugs: 8650' - 8550'- 1866-1860' - 6050' - 5950'	OTHER:	Ind give pertinent dates, including estimated date ttach wellbore diagram of proposed completion of the completion of th
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circle POH. GIH w/2 3/8" tubing Spot cement plugs: 8650' - 8550'- TAC 6050' - 5950' 3830' - 3730' 2150' - 2050'- TAC 600' - 400' -	OTHER: eted operations. (Clearly state all pertinent details, and it). SEE RULE 1103. For Multiple Completions: A 23/07 o 1000#. Dump 35' cement. ulate hole w/9.5 ppg mud laden fluid .	Ind give pertinent dates, including estimated date ttach wellbore diagram of proposed completion is. If earthen pits are used in association with this work a pit permit is required prior
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circle POH. GIH w/2 3/8" tubing Spot cement plugs: 8650' - 8550'- TAC 6050' - 5950' 3830' - 3730' 2150' - 2050' - TAC 600' - 400' - TAC 600' - 50' - Surf	OTHER: eted operations. (Clearly state all pertinent details, and it). SEE RULE 1103. For Multiple Completions: A 23/07 o 1000#. Dump 35' cement. ulate hole w/9.5 ppg mud laden fluid .	Ind give pertinent dates, including estimated date ttach wellbore diagram of proposed completion of the completion of th
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circle POH. GIH w/2 3/8" tubing Spot cement plugs: 8650' - 8550'- 1AC 6050' - 5950' 3830' - 3730' 2150' - 2050'- 1AC 600' - 400' - 7 AC 600' - 501' 50' - Surf Cut off 8 5/8" casing	OTHER: eted operations. (Clearly state all pertinent details, and it). SEE RULE 1103. For Multiple Completions: A 23/07 o 1000#. Dump 35' cement. ulate hole w/9.5 ppg mud laden fluid .	Ind give pertinent dates, including estimated date ttach wellbore diagram of proposed completion If earthen pits are used in association with this work a pit permit is required prior to construction.
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circle POH. GIH w/2 3/8" tubing Spot cement plugs: 8650' - 8550'- TAC 6050' - 5950' 3830' - 3730' 2150' - 2050' - TAC 600' - 400' - TAC 600' - 50' - Surf	OTHER: eted operations. (Clearly state all pertinent details, and it). SEE RULE 1103. For Multiple Completions: A 23/07 o 1000#. Dump 35' cement. ulate hole w/9.5 ppg mud laden fluid .	Ind give pertinent dates, including estimated date ttach wellbore diagram of proposed completion If earthen pits are used in association with this work a pit permit is required prior to construction.
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circle POH. GIH w/2 3/8" tubing Spot cement plugs: 8650' - 8550'- 1AC 6050' - 5950' 3830' - 3730' 2150' - 2050'- 1AC 600' - 400' - 7 AC 600' - 501' 50' - Surf Cut off 8 5/8" casing	OTHER:eted operations. (Clearly state all pertinent details, and the completions.) SEE RULE 1103. For Multiple Completions: A 23/07 o 1000#. Dump 35' cement. The completion of the completions of the completion of the compl	Ind give pertinent dates, including estimated date ttach wellbore diagram of proposed completion of the completion of the construction. Notity OCD 24 hrs. prior
OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circ POH. GIH w/2 3/8" tubing Spot cement plugs: 8650' - 8550'- 1AC 6050' - 5950' 3830' - 3730' 2150' - 2050'- 1AC 600' - 400' - 7 20' 50' - Surf Cut off 8 5/8" casing Install dry-hole marker	OTHER:eted operations. (Clearly state all pertinent details, and the completions.) SEE RULE 1103. For Multiple Completions: A 23/07 o 1000#. Dump 35' cement. The completion of the completions of the completion of the compl	Ind give pertinent dates, including estimated date ttach wellbore diagram of proposed completion If earthen pits are used in association with this work a pit permit is required prior to construction.
OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circ POH. GIH w/2 3/8" tubing Spot cement plugs: 8650' - 8550'- 1AC 6050' - 5950' 3830' - 3730' 2150' - 2050'- 1AC 600' - 400' - 7 20' 50' - Surf Cut off 8 5/8" casing Install dry-hole marker	OTHER:eted operations. (Clearly state all pertinent details, and the completions.) SEE RULE 1103. For Multiple Completions: A 23/07 o 1000#. Dump 35' cement. The completion of the completions of the completion of the compl	Ind give pertinent dates, including estimated date ttach wellbore diagram of proposed completion of the completion of the construction. Notity OCD 24 hrs. prior
OTHER: 13. Describe proposed or completed of starting any proposed work or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circle POH. GIH w/2 3/8" tubing Spot cement plugs: 8650' - 8550' - 7AC 6050' - 5950' 3830' - 3730' 2150' - 2050' - 7AC 600' - 400' - 7AC 600' - 400' - 7AC 600' - 50' - Surf Cut off 8 5/8" casing Install dry-hole marker Proposed well sketch is as	eted operations. (Clearly state all pertinent details, and k). SEE RULE 1103. For Multiple Completions: A 23/07 0 1000#. Dump 35' cement. ulate hole w/9.5 ppg mud laden fluid	Ind give pertinent dates, including estimated date ttach wellbore diagram of proposed completion of the completion of the construction. Notity OCD 24 hrs. prior to construction.
OTHER: 13. Describe proposed or completed of starting any proposed work or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circle POH. GIH w/2 3/8" tubing Spot cement plugs: 8650' - 8550' - 7860'. 6050' - 5950'. 3830' - 3730'. 2150' - 2050' - 7860'. 600' - 400' - 7860'. 50' - Surf. Cut off 8 5/8" casing Install dry-hole marker. Proposed well sketch is at I hereby certify that the information at I hereby certify that the I hereby certify the I hereby certify that the I hereby certification the I hereby certification the	OTHER: eted operations. (Clearly state all pertinent details, and the completions: A 23/07 0 1000#. Dump 35' cement. ulate hole w/9.5 ppg mud laden fluid ttached bove is true and complete to the best of my knowledge	Ind give pertinent dates, including estimated date ttach wellbore diagram of proposed completion of the completion of the construction of the construction. Notify OCD 24 hrs. prior to construction. Notify OCD 24 hrs. prior to cony work done.
OTHER: 13. Describe proposed or completed of starting any proposed work or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circle POH. GIH w/2 3/8" tubing Spot cement plugs: 8650' - 8550' - 7860'. 6050' - 5950'. 3830' - 3730'. 2150' - 2050' - 7860'. 600' - 400' - 7860'. 50' - Surf. Cut off 8 5/8" casing Install dry-hole marker. Proposed well sketch is at I hereby certify that the information at I hereby certify that the I hereby certify the I hereby certify that the I hereby certification the I hereby certification the	eted operations. (Clearly state all pertinent details, and k). SEE RULE 1103. For Multiple Completions: A 23/07 0 1000#. Dump 35' cement. ulate hole w/9.5 ppg mud laden fluid	Ind give pertinent dates, including estimated date ttach wellbore diagram of proposed completion of the completion of the construction of the construction. Notify OCD 24 hrs. prior to construction. Notify OCD 24 hrs. prior to cony work done.
OTHER: 13. Describe proposed or completed of starting any proposed work or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circle POH. GIH w/2 3/8" tubing Spot cement plugs: 8650' - 8550'- 1866 6050' - 5950' 3830' - 3730' 2150' - 2050'- 1866 600' - 400' - 7866 600' - 400' - 7866 Cut off 8 5/8" casing Install dry-hole marker Proposed well sketch is as I hereby certify that the information all grade tank has been/will he constructed or classification.	OTHER: eted operations. (Clearly state all pertinent details, and the completions: A 23/07 0 1000#. Dump 35' cement. ulate hole w/9.5 ppg mud laden fluid ttached bove is true and complete to the best of my knowledge losed according to NMOCD guidelines [], a general permit []	Ind give pertinent dates, including estimated date ttach wellbore diagram of proposed completion of the completion of the completion of the construction. Notify OCD 24 hrs. prior to construction. Notify OCD 24 hrs. prior to construction. See and belief. I further certify that any pit or below-for an (attached) alternative OCD-approved plan.
OTHER: 13. Describe proposed or completed of starting any proposed work or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circle POH. GIH w/2 3/8" tubing Spot cement plugs: 8650' - 8550' - 7860'. 6050' - 5950'. 3830' - 3730'. 2150' - 2050' - 7860'. 600' - 400' - 7860'. 50' - Surf. Cut off 8 5/8" casing Install dry-hole marker. Proposed well sketch is at I hereby certify that the information at I hereby certify that the I hereby certify the I hereby certify that the I hereby certification the I hereby certification the	OTHER: eted operations. (Clearly state all pertinent details, and the completions: A 23/07 0 1000#. Dump 35' cement. ulate hole w/9.5 ppg mud laden fluid ttached bove is true and complete to the best of my knowledge	Ind give pertinent dates, including estimated date ttach wellbore diagram of proposed completion of the completion of the completion of the construction. Notify OCD 24 hrs. prior to construction. Notify OCD 24 hrs. prior to construction. See and belief. I further certify that any pit or below-for an (attached) alternative OCD-approved plan.
OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circle POH. GIH w/2 3/8" tubing Spot cement plugs: 8650' - 8550'- 1AC 8650'- 1AC 8650' - 5950' 3830' - 3730' 2150' - 2050'- 1AC 8600' - 400' - 7 10' 50' - Surf Cut off 8 5/8" casing Install dry-hole marker Proposed well sketch is as I hereby certify that the information all grade tank has been/will be constructed or co	oTHER: eted operations. (Clearly state all pertinent details, and its). SEE RULE 1103. For Multiple Completions: A 23/07 0 1000#. Dump 35' cement. ulate hole w/9.5 ppg mud laden fluid ttached bove is true and complete to the best of my knowledge losed according to NMOCD guidelines , a general permit . TITLE District Engineer	If earthen pits are used in association with this work a pit permit is required prior to construction. Notify OCD 24 hrs. prior To any work done. The and belief. I further certify that any pit or below-for an (attached) alternative OCD-approved plan.
OTHER: 13. Describe proposed or completed of starting any proposed work or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circle POH. GIH w/2 3/8" tubing Spot cement plugs: 8650' - 8550'- 1AC 8650'- 1AC 8650' - 5950' 3830' - 3730' 2150' - 2050'- 1AC 8600' - 400' - 7 10' 50' - Surf Cut off 8 5/8" casing Install dry-hole marker Proposed well sketch is as I hereby certify that the information all grade tank has been/will be constructed or con	oTHER: eted operations. (Clearly state all pertinent details, and its). SEE RULE 1103. For Multiple Completions: A 23/07 0 1000#. Dump 35' cement. ulate hole w/9.5 ppg mud laden fluid ttached bove is true and complete to the best of my knowledge losed according to NMOCD guidelines , a general permit . TITLE District Engineer	Ind give pertinent dates, including estimated date ttach wellbore diagram of proposed completion of the completion of the completion of the construction. Notify OCD 24 hrs. prior to construction. Notify OCD 24 hrs. prior to construction. See and belief. I further certify that any pit or below-for an (attached) alternative OCD-approved plan.
OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circle POH. GIH w/2 3/8" tubing Spot cement plugs: 8650' - 8550'- 1AC 8650'- 1AC 8650' - 5950' 3830' - 3730' 2150' - 2050'- 1AC 8600' - 400' - 7 10' 50' - Surf Cut off 8 5/8" casing Install dry-hole marker Proposed well sketch is as I hereby certify that the information all grade tank has been/will be constructed or co	OTHER: eted operations. (Clearly state all pertinent details, and its). SEE RULE 1103. For Multiple Completions: A 23/07 0 1000#. Dump 35' cement. ulate hole w/9.5 ppg mud laden fluid ttached bove is true and complete to the best of my knowledge losed according to NMOCD guidelines , a general permit . TITLE	Indigive pertinent dates, including estimated date ttach wellbore diagram of proposed completion If earthen pits are used in association with this work a pit permit is required prior to construction. Notity OCD 24 hrs. prior to construction. Notity OCD 24 hrs. prior to construction. If earthen pits are used in a pit permit is required prior to construction. Notity OCD 24 hrs. prior to construction. DATE 6/19/07 In accommod Telephone No. (432) 683-7063
OTHER: 13. Describe proposed or completed of starting any proposed work or recompletion. Estimated start date: 7/ Set CIBP @ 8850'. Test to Cut casing @ 8600'. Circle POH. GIH w/2 3/8" tubing Spot cement plugs: 8650' - 8550'- 1AC 8650'- 1AC 8650' - 5950' 3830' - 3730' 2150' - 2050'- 1AC 8600' - 400' - 7 10' 50' - Surf Cut off 8 5/8" casing Install dry-hole marker Proposed well sketch is as I hereby certify that the information all grade tank has been/will be constructed or con	oTHER: eted operations. (Clearly state all pertinent details, and its). SEE RULE 1103. For Multiple Completions: A 23/07 0 1000#. Dump 35' cement. ulate hole w/9.5 ppg mud laden fluid ttached bove is true and complete to the best of my knowledge losed according to NMOCD guidelines , a general permit . TITLE District Engineer	If earthen pits are used in association with this work a pit permit is required prior to construction. Notify OCD 24 hrs. prior To any work done. The and belief. I further certify that any pit or below-for an (attached) alternative OCD-approved plan.

P&A Proposed

