

UNITED STATES **OCD-ARTESIA**
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No 1004-0137
Expires March 31, 2007**SUNDRY NOTICES AND REPORTS ON WELLS****Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.****S**

Lease Serial No

LC-02419A

If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well

☐ Oil Well☐ Gas Well☐ Other**OCT 31 2007**

2. Name of Operator

Forest Oil Corporation**OCD-ARTESIA**

3a. Address

3504 NW County Road

3b. Phone No (include area code)

575 392-9797

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

510' FNL & 660' FEL**Sec. 22-T17S-R31E Unit P**

7. If Unit or CA/Agreement, Name and/or No.

Skelly Unit

8. Well Name and No.

58

9. API Well No

30-015-05355

10. Field and Pool, or Exploratory Area

Grayburg Jackson 7-Rivers QN-GB-SA

11. County or Parish, State

Eddy County, New Mexico**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☐ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☐ Other

13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

3/21/07 MIRU unit. ND WH. NU BOP. POH w/2-3/8" tbg. & Guiberson J-Lok pkr. RIH w/tbg. & CIBP.

3/22/07 Finish RIH w/tbg. Set CIBP @ 3232'. Tested to 500# for 30 min. Held ok. Circulated pkr. fluid.

POH & LD 2-3/8" tbg. ND BOP. NU WH. RD unit. Waiting on NMOCD to witness pressure chart.

4/02/07 Ran MIT for 30 min. to 520#. Held ok. Test performed by Nick Jimenez w/Gandy Corporation.

Witnessed by Gerry Guye w/NMOCD. Original chart retained by Gerry Guye. Copy of chart attached. Well is TA'D.

*NMOCD approved status attached.

APPROVED FOR 12 MONTH PERIOD
ENDING 4/2/08

APPROVED**OCT 22 2007****LES BABYAK
PETROLEUM ENGINEER**

14 I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Mary Jo TurnerTitle **Production Analyst****ACCEPTED FOR RECORD**

Signature

Mary Jo Turner

Date

04/13/2007**THIS SPACE FOR FEDERAL OR STATE OFFICE USE****NOV 01 2007**

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

**Gerry Guye, Deputy Field Inspector
NMOCD-District II ARTESIA**

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)