Form 3160-5 (August 1999)

(This space for Federal or State Office use)

Conditions of approval, if any OF RECORDS ONLY

Approved by

## **UNITED STATES** DEPARTMENT OF THE INTERIOR

- 07 2007

FORM APROVED OMB NO. 1004-0135

AUG 2 7 2007

Date

	J OF LAND MANAGEMENT	AUG Z I Zoo.	EXPIRES: NOVEMBER 30, 2000
SUNDRY NOTICES AND REPORTS ON WELLS  5. Lease Serial No.			
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an OCD-AKI-SIA			NMNM89052
abandoned well. Use Form 3160-3 (APD) for such proposals			6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE			
	EMIT IN THE ELOCATE		7. Unit or CA Agreement Name and No.
			7. Unit of CA Agreement Name and No.
1a. Type of Well 🔽 Oil Well 🔲 Ga	s Well 🔲 Other		
			8 Well Name and No.
2. Name of Operator			Apache 25 Federal 16
DEVON ENERGY PRODUCTION COMPANY, LP			9. API Well No.
3. Address and Telephone No.			30-015-34328
20 North Broadway, Oklahoma City, OK 73102 405-228-8699			10. Field and Pool, or Exploratory
4. Location of Well (Report location clearly and in accordance with Federal requirements)*			Los Medanos; Strawn
1980' FSL & 660' FWL SEC 25 22S R30E			12 County or Parish 13. State
1900 F 3E & 000 F WE 3E 0 23 220 NOVE			12 Oddiny of Farish To. State
			Eddy NM
CHECK A	APPROPRIATE BOX(s) TO INI	DICATE NATURE OF NOTICE REPO	ORT. OR OTHER DATA
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA  TYPE OS SUBMISSION   TYPE OF ACTION			
30 000001011			
☐ Notice of Intent	Acıdize		iction (Start/Resume) 🔛 Water Shut-Off
	☐ Alter Casing	☐ Fracture Treat ☐ Recla	mation $\ igsqcup \ $ Well Integrity
✓ Subsequent Report	Casing Repair	☐ New Construction ☐ Recor	mplete
	Change Plans	Plug and Abandon Temp	orarily Abandon
Final Abandonment Notice	Convert to Injection	☐ Plug Back ☐ Wate	r Disposal
13 Describe Proposed or Completed Operations (C			ing any proposed work and approximate duration thereof If the proposal
			nes Attach the Bond under which the work will be performed or provide
the Bond No on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations of the operation results in a multiple completion or recompletion in a new			
interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has			
determined that the site is ready for final inspection)			
3/31/07- 4/30/07			
MIRU Service unit. Rlse pkr @ 13,552'. CHC w/ 2% KCI. Set CIBP @ 13,590'. Test to 2000#, 5 mins. Perf Atoka Bank 12,999-			
13,308' @ 4 spf 36 holes. No blow. Set pkr @ 12,913'. Acidize w/ 2000 gals 15% HCL. Flush w/ 2% KCL. Swab. Set CIBP @			
12950' dump cmt. Set CIBP @ 12865', dump cmt. New PBTD @ 12,830'. Perf Strawn 12,610'-12,617' @ 4 spf: 28 holes. No			
blow. Swab dry, no blow. Acidize w/ 1200 gals 15% HCL w/ 40 BS. Flush w/ 2% KCL. RD BJ. Turn over to sales.			
blew. Stab dry, no blem. Adata w. 1200 gale 10 % 1102 w. 10 201 1 last w. 17 2 % 1.021. 1.0 201 1 date of			
•			
			Ì
			· ·
			i
			}
			İ
14. I hereby certify that the foregoing is t	rue and correct		
	Name	Judy A. Barnett	
Signed Visar (	Title	Regulatory Analyst	Data 9/22/2007
Signed	Title	Negulatory Arialyst	Date <u>8/23/2007</u>