

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007

S

JAN 15 2008
OCD-ARTESIA

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other2. Name of Operator
HANSON ENERGY3a. Address
P.O. BOX 1348 ARTESIA, NM 882113b. Phone No. (include area code)
575-746-2262

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

440 FNL 2310 FEL UNIT C SEC.13-17S-27E

5. Lease Serial No.

LC048491A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
SAUNDERS' A #119. API Well No.
30-015-2412310. Field and Pool, or Exploratory Area
RED LAKE, QN, GB, SA11. County or Parish, State
EDDY NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

RECORDS INDICATE 442' 13 5/8" CASING - CEMENT CIRCULATED
880' 8 5/8" CASING - CEMENT CIRCULATED
2291' 41/2" CASING - CEMENT FROM TD TO 310' CIBP SET AT 2000' 8/24/01

REQUEST APPROVAL TO PLUG WELL WITH READYMIX 6SK 3/8 PEAGRAVEL.

WILL POUR READYMIX SLOWLY FROM 2000' TO SURFACE. WILL REQUIRE APPROXIMATELY 12 YARDS CEMENT.

SET DRY HOLE MARKER.

CLEAN LOCATION.

Cut/Back off 4 1/2" casing 60/100', pull
Evacuate wellbore of any fluids prior to cement

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

KATHIE HANSON

Title PRODUCTION CLERK

Signature



Date

01/08/2008

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by James C. Lewis
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Title SEPS

Date

1-10-08

Office CFO

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212. make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

Accepted for record
NMOCD