
Form 3160-5 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT




FORM APPROVED OMB No 1004-0135


SUNDRY NOTICES AND REPORTS ON WELLS

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Expires January 31, 2004

	OTICES AND REPORTS ON his form for proposals to drill or re	'ABB A	2008	5 Lease Serial No NM-043625	
abandoned well. Use Form 3160-3 (APD) for such proposals.				6 If Indian, Allottee or Tribe	Vame
				7 If Unit or CA/Agreement, N	lame and/or No
SUBMIT IN TRIPLICATE - Other instructions on reverse side					
1 Type of Well	Tu T			NM-84604	<u> </u>
Oil Well Ga	s Well Other	RE-SUBMIT		8. Well Name and No	
2 Name of Operator				Saguaro AGS Feder	ral Com #8
Yates Petroleum Corporation				9 API Well No	
3a Address 3b Phone No (include area code)				30-015-26517	
105 S. 4th Str., Artesia, NM 88210 505-748-1471				10 Field and Pool, or Explora	,
4 Location of Well (Footage, Sec ,T.,R ,M., OR Survey Description)				Dagger Draw Upper	Penn, South
				11 County or Parish, State	
660'FSL & 1980'FEL of Section 14-T20S-R24E (UNIT O, SWSE)				Eddy County, New N	
12. CHECK APPROP	RLATE BOX(ES) TO INDIC	CATE NATURE OF N	NOTICE, RE	PORT, OR OTHER D	АТА
TYPE OF SUBMISSION	SUBMISSION TYPE OF ACTION				
	Г		D.ACCE	PTED FOR RECOR	SDr Occ
	Acidize	Deepen			
Notice of Intent	Alter Casing	Fracture Treat	Reclamation	[]Well	Integrity
	Casing Repair	New Construction	Recomplete	APR 3 0 2008Only	er
Subsequent Report	Change Plans	X Plug and Abandon	Tomporatily	Abandon	
		<u>-</u>	NMOCI	Abandon uye, Deputy Field Inspec	tor
Final Abandonment Notice	Convert to Injection	Plug Back	Water Dispos	D-District II ARTES	<u> </u>
Yates Petroleum Corporation properties Petroleum Corporation Petroleum	plans to plug and abandon ement needed. ex) across the Wolfcamp fr ex) across the DV tool from ex) across the Bone Spring ex) from 1038'-1138'. Tag ex) from 100' to surface. T	rom 5834'-5934'. n 5481'-5581'. g from 3244'-3344'. plug.		SEE ATTACHEI) FOR
NOTE: Yates Petroleum Corp	oration will use steel pits a	and no earth pits		CONDITIONS C	JE AFFILOVA
14 I hereby certify that the foregoing is true Name (Printed/Typed)	and correct				
Tina H	ψerta ,	Title Regulati	ory Complia	nce Supervisor	
11.			٢	4 DDD ()	/ED
Signature (Lina)	uerta	Date April 11,	, 2008	APPRO\	VED
	THIS SPACE FOR FI	EDERAL OR STATE OF	FICE USE		
Approved by	-	Title		ABB 26	2008
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduct	uitable title to those rights in the sub operations thereon	ject lease Office		JAMES A. A	AMOS
Title 18 U.S C Section 1001 and Title 43 U	S C Section 1212, make it a crime for	or any person knowingly and	willfully to make t	o any depar GlehRbrlagehS Q	nine United





BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.