Form 3160-5 (April2004)

UNITEDSTATES DEPARTMENT OF THE INTERIOR



OCD-	ARTESI AORMAPPROVED Expires: March 31, 2007	
	5. Lease Serial No.	
	NMLC 068545	

BUREAU OF LAND MANAGEMENT	5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS OF Do not use this form for proposals to drill or to abandoned well. Use Form 3160-3 (APD) for su	o re-enter an 6 If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on	7. If Unit or CA/Agreement, Name and/or No. NMNM71016X		
Ba. Address 3b Phone No.	8 Well Name and No. Poker Lake Unit #190 9 API Well No (include area code) 30-015-32142		
P.O. BOX 2760 MIDLAND TX 79702-2760 (432)6 4 Location of Well (Footage, Sec , T , R , M , or Survey Description) Sec 7, T24S, R30E, NWSE, 1980 FSL & 1980' FEL	10 Field and Pool, or Exploratory Area Nash Draw (Delaware, BS, Avalon Sd) 11. County or Parish, State Eddy County, New Mexico		
12. CHECK APPROPRIATE BOX(ES)TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA			
TYPE OF SUBMISSION TYPE OF ACTION			
X Acidize	rruction Recomplete X OtherAdd Delaware		
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) BEPCO, L. P. respectfully reports the addition of Delaware perfs to this wellbore as follows: 06/04/2008: MIRU CUDD Pumping Service. POOH w/ 2-7/8" tbg. & pump. 06/05/2008: MIRU Baker Hughes. RIH w/ 5-1/2" CIBP & set @ 6200' to temporarily zone abandon perfs from 7164-7360'. RU Basic Energy Services & perf Delaware @ 6014-24' & 6056-66' for a total of 20 holes. POOH w/guns & RD Baker. Basic RIH w/ 2-7/8" tubing & pump 1000 gals 7.5% NEFE HCL across perfs. POOH w/ tubing & RD Basic. 06/07/2008: Frac new Delaware perfs w/ 42107 gals BFRAC 30, 110141#'s 16/30 Ottawa Sand & 43429#'S 16/30 Super LC. Set 5-1/2" CIBP @ 5860'. Perf Delaware @ 5761-71' for a total of 20 holes. RD Baker. Switch to Cudd & frac newest perfs w/ 21683 gals BFRAC 30, 56195 #'s 16/30 Ottawa Sand & 16080#'s Super LC. RD Cudd. 06/10/2008: MIRU Chance Foam Air Unit. RIH w/ 4-3/4" blade bit, break circ w/ Foam Air & wash down to CIBP. Drill out 1st CIBP @ 5860' & chase down to CIBP @ 6200'. POOH w/bit & tubing. 06/11/2008: PU & RIH w/ 173 jts 2-7/8" tbg. & set SN @ 5500' & TAC @ 5339'. 06/12/2008: RIH w pump & rods. RDMOPU & return well to production. 14 I hereby certif			
Signature am Moore	Date 06/23/2008 ACCEPTED FOR RECORD		
THIS SPACE FOR FEDERAL	OR STATE OFFICE USE		
Approved by Conditions of approval, if any, are attached Approval of this notice does not warr certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon Title 18 U S C Section 1001 and Title 43 U S C Section 1212, make it a crime for as States any false, fictitious or fraudulent statements or representations as to any	ease Office Py person knowingly and willfully to make to any department or agency of the United		