

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTOil Cons.
N.M. DIV-Dist. 2
1301 W. Grand Avenue
Artesia, NM 88210FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000**SUNDRY NOTICES AND REPORTS ON WELLS**
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

OCT 28 2003

SUBMIT IN TRIPLICATE - Other instructions on reverse side

OCD-ARTESIA

1. Type of Well
☐ Oil Well ☐ Gas Well ☒ Other Plug & Abandon2. Name of Operator
Vintage Drilling, LLC3a. Address
P.O. Box 158
Loco Hills, NM 882553b. Phone No. (include area code)
505-746-16894. Location of Well (Footage, Sec., T., R., M., or Survey Description)
990' FSL & 660' FEL of Section 15-T16S-R29E
Unit P, SESE

5. Lease Serial No.

NM-05323

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

High Lonesome Penrose Ut. #4

9. API Well No.

30-015-02731

10. Field and Pool, or Exploratory Area

High Lonesome Queen

11. County or Parish, State

Eddy Co., NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

9-18-2003 - Started moving in pulling unit and plugging equipment.

9-19-2003 - Spotted equipment. Rigged up pulling unit.

9-20-2003 - RIH with tubing and spotted 50 sacks "C" Neat cement at 1958' and flushed to blance. POOH with 14 stands. Shut well in for night.


9-21-23-2003 - RIH with tubing and tagged top of cement at 1775'. Circulated hole with plugging mud. POOH with tubing. Rigged up wireline. RIH and perforated 5-1/2" casing at 875'. POOH and rigged down wireline. RIH with packer and tubing to 500'. Spotted 40 sacks "C" Neat and flushed to 750'. 0 psi. POOH with packer. Shut well in for night. WOC.

9-24-2003 - Rigged up wireline. RIH to 900' - no ffill. POOH & rigged down wireline. RIH with tubing to 1000'. Circulated hole with plugging mud. Pulled up to 500' and set packer. Spotted 40 sacks "C" Neat and flushed to 750'. 0 psi. WOC 1 hour. POOH with packer. Dug out cellar. Rigged up wireline. RIH and perforated 5-1/2" casing at 486'. POOH and rigged down wireline. Shut well in for night.

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Rusty Klein

Signature



CONTINUED ON NEXT PAGE:

Title Agent for BCM & Associates

Date Oct. 12, 2003

APPROVED

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

OCT 24 2003
DateLES BABYAK
PETROLEUM ENGINEER

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.


VINTAGE DRILLING, LLC.
High Lonesome Penrose Unit #4
Section 15-T16S-R29E
Eddy County, New Mexico

SUNDRY NOTICE CONTINUED:

9-25-2003 - RIH with tubing to 875' - no fill. Spotted 30 sacks "C" with 2% CaCl₂ and flushed to balance. POOH. WOC 3 hours. RIH and tagged top of cement at 605'. POOH. RIH and set packer at 31'. Opened 8-5/8" X 5-1/2" annulus to pit. Established circulation. Spotted 125 sacks "C" and flushed to 370'. ISIP 0 psi. Shut well in for night. WOC.

9-26-2003 - RIH with tubing to 600' - no fill. POOH. Rigged up pump to surface pipe. Reversed bottoms up. RIH with packer to 31' and set - would not circulate. Spotted 75 sacks "C" down 5-1/2" and 75 sacks "C" down 8-5/8" X 5-1/2" annulus. Shut well in for night. WOC.

9-26-2003 - Cement at surface. Cut off wellhead. Tagged top of cement in 8-5/8" X 5-1/2" annulus at 40'. Cut 5-1/2" packer out of wellhead. Filled annulus with 40 sacks "C" to surface. Rigged down pulling unit and plugging equipment. Installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed 9-26-2003.



Rusty Klein
Agent
October 12, 2003