Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELL

SEP -8 2008

FORM APROVED OMB NO 1004-0135 EXPIRES: NOVEMBER 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS	OCD-ARTESIA	5. Lease Serial No.
Do not use this form for proposals to drill or to re-enter an abandoned well—Use Form 3160-3 (APD) for such proposals	• •	・ NMNM0557370 ช. It Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE		
		7 Unit or CA Agreement Name and No.
1a. Type of Well 🗸 Oil Well 🔲 Gas Well 🔲 Other		
		8 Well Name and No.
2. Name of Operator	Eagle 35E Federal 11	
DEVON ENERGY PRODUCTION COMPANY, LP		9 API Well No.
3. Address and Telephone No		30-015-33242
20 North Broadway, Oklahoma City, OK 73102	405-552-8198	10 Field and Pool, or Exploratory

2. Name of Operator			Eagle 35E Federal 11		
DEVON ENERGY PRODUCTION COMPANY, LP			9 API Well No.		
3. Address and Telephone No			30-015-33242		
20 North Broadway, Oklahoma City, OK 73102 405-552-8198			10 Field and Pool, or Exploratory		
4 Location of Well (Report location clearly and in accordance with Federal requirements)*			Redlake: QB-SA-Glorieta-Yeso		
1800 FNL 1100 FWL E 35 17S 27E		i i	12. County or Parish 13. State		
			Eddy	NM	
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
TYPE OS SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize		ıction (Start/Resume)	Water Shut-Off	
✓ Subsequent Report	☐ Alter Casing☐ Casing Repair	=	mation nolete	Well Integrity Other Downhole	
	Change Plans		orarily Abandon	Other Downhole Commingling	
Final Abandonment Notice	Convert to Injection		r Disposal	Comminging	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal deepen directionally or recomplete horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)					
9/17/06 MIRU PU. POOH with rods and pump ND wellhead and NU BOP. POOH with tubing. 9/18/06 RIH with bailer and bail sand from 2750'-2895'. POOH with bailer. 9/19/06 RIH with retrieving tool and latched onto RBP. Released RBP and POOH with RBP RIH with tubing. ND BOP and NU wellhead. RIH with rods and pump. Hang well on production.					
			100====		
			I ACCEPTED	FOR RECORD	
			MOULI ILL	ן עווטטאא וויט וי	
			SEP	4 2208	
			7	m	
			BUREAU OF L	AND MANAGEMENT	
			(RARLSBA	D FIELD OFFICE	
14. Thereby certity that the foregoing is true and correct					
Signed	Name _	Norvella Adams Sr. Staff Engineering Technicia	Date	6/27/2008	
(This space for Federal or State Office use)					
Approved by	Title		Date		
Conditions of approval, if any:	The the				

THE TO SIC Section 1001, makes it a crime for any person knowingly and willingly dimake any department or agency or the crimed states any takes, includous or traductions to any person knowingly and willingly dimake any department or agency or the crimed states any takes, includous or traduction is taken any person knowingly and willingly and willingly different to the contract of the contract of

*See Instruction on Reverse Side

Accepted for record NMOCD