SEP 17 2008

Submit 3 Copies To Appropriate District Office	State of New Mexico	OCD-ARTESIA	Form C-103 May 27, 2004	
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Res	WELL API NO.	Way 27, 2004	
District II	OIL CONCEDIATION DIVI	20.015.21707		
1301 W. Grand Ave , Artesia, NM 88210	OIL CONSERVATION DIVIS	1.5 Indicate Type of Lea	se	
<u>District III</u> 1000 Rio Brazos Rd , Aztec, NM 87410	1220 South St. Francis Dr	SIAIL	FEE	
<u>District IV</u> 1220 S St Francis Dr , Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Leas	se No.	
87505	ES AND REPORTS ON WELLS	7. Lease Name or Unit	A graamant Nama	
(DO NOT USE THIS FORM FOR PROPOSA	LES AND REPORTS ON WELLS ALS TO DRILL OR TO DEEPEN OR PLUG BACK ATION FOR PERMIT" (FORM C-101) FOR SUCH	C TO A	Agreement Name	
PROPOSALS)		Higgins Trust Inc Com 8. Well Number		
1. Type of Well: Oil Well Gas Well Other				
2. Name of Operator	I.D.	9. OGRID Number		
Devon Energy Production Company, L.P. 3. Address of Operator		6137 10. Pool name or Wildo	nat .	
20 North Broadway, Oklahoma City, OK 73102-8260 405-552-8198			Jai	
4. Well Location	- OK 75102-0200 - 405 552 0170	neu Cake		
		1 000 Cat Cat Day	1:	
	990feet from theNorth line and		line	
Section 13	Township 18S Range 26I		nty Eddy	
The second secon	11. Elevation (Show whether DR, RKB, F	RT, GR, etc.)		
Pit or Below-grade Tank Application ☐ or	3287' GR	4.		
		Digtorgo from poorest gurfoso wat	tom	
	erDistance from nearest fresh water well		ler	
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Construction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INT		SUBSÉQUENT REPOR		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING				
TEMPORARILY ABANDON	IANGE PLANS COMMENCE DRILLING OPNS. P AND A			
PULL OR ALTER CASING	MULTIPLE COMPL CASIN	NG/CEMENT JOB □		
OTHER:	☐ OTHE	R Completion Report	\bowtie	
13. Describe proposed or comple	eted operations. (Clearly state all pertinen	t details, and give pertinent dates, inc		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompletion.				
6/00/09 MIDII winding TIII with Cl	(DD and get at 6020). Test assing and DO	D to 2000 pai hald als Parforata Va	oso from 2562 2325'	
6/09/08 MIRU wireline. TIH with CIBP and set at 6030'. Test casing and BOP to 3000 psi – held ok. Perforate Yeso from 2562-3325': 45 0.40 holes. TIH with packer and tubing. Set packer at 2490'.				
	ons 15% HCl acid. Bled well down. Rele	ase packer. TOOH with tubing and p	acker. ND BOP and	
NU Frac valve.		p 3 1		
6/12/08 Frac with 128,525 gallons 10	# Brine + 20,500 # 100% Lite Prop 125, 1	14/30 sand + 25,500 # 100% Siber Pro	op, 16/30 sand.	
6/13/08 TIH with tubing, pump, and rods. Hung well on production.				
I hereby certify that the information al	bove is true and complete to the best of m	y knowledge and belief. I further certii	fy that any pit or below-	
grade tank has been/will be constructed or cl	osed according to NMOCD guidelines [], a gene	ral permit 🗌 or an (attached) alternative O	CD-approved plan .	
SIGNATURE /		The Trul	10	
SIGNATURE	ITILE_Sr. Staff	Eng. TechDATE_8/20/0	10	
Type or print name Norvella Adams	E-mail address: norvella.adams@dvn	.com Telephone No. 405-552-819	98	
For State Use Only	L-man addiess. noi vena.adams@dvii	100m 100-332-01	. ·	
~			ı	
APPROVED BY:	TITLE	Accepted for record	E	
Conditions of Approval (if any):		NMOCD		