Form 3160-5 (August 1999)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR

**BUREAU OF LAND MANAGEMENT** 

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

		Expires:	Novem	per	<u>3</u>
5,	Lease	Scrial No.			
	NMI .	C02939!	5A		

6 If Indian Allottee or Tribe Name

abandoned well. Use for	0, 2 120.23, 1210.35 01 11100.10110	
SUBMIT IN TRIPLICATE -	7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well Gas Well Other		8. Well Name and No. TURNER A 50
2. Name of Operator MERIT ENERGY COMPANY	Contact: BEVERLY HATFIELD E-Mail: beverly.hatfield@meritenergy.com	9. API Well No. 30-015-28772-00-S1
3a. Address 13727 NOEL RD., STE 500 DALLAS, TX 752406	3b. Phone No. (include area code) Ph: 972.628.1630 Ext: 630 Fx: 972.960.1252	10. Field and Pool, or Exploratory GRBG JACKSON SR Q GRBG SA
4. Location of Well (Footage, Sec., T., R., M., or S.	11. County or Parish, and State	
Sec 19 T17S R31E SENE 2390FNL 1210	OFEL .	EDDY COUNTY, NM

## 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☑ Notice of Intent ☐ Subsequent Report ☐ Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete ☐ Temporarily Abandon ☐ Water Disposal	☐ Water Shut-Off ☐ Well Integrity ☑ Other Workover Operations

## PERF & ACIDIZE SEVEN RIVERS PERFS.

1. COMPLY W/COMPANY & GOVERNMENTAL SAFETY REGULATIONS.

2.RU PU. ND WH. NU BOP. TOH RODS PMP & TBG. TIH W/4-5/8" BIT ON 2-7/8" WS. CLEAN OUT TO +/-2950'. TOH W/BIT. PERF SEVEN RIVERS 1922-1926', 1905-1907', 1888-1892', 1834-1836', 1808-1810', 1796-1798', 1770-1772' & 1780-1784' 1770-1772', & 1693-1695'(26'NET) W/4 SPF, RD WL.

3. TIH W/5-1/2" W/RBP W/15.5# STIMULATION PKR ON 2-7/8" WS SET RBP @ 1975. SET PKR @ 1650'. ACIDIZE SR W/HCL PER CUDD. TIH W/3-1/2" MHMA W/PURGE VALVE, SN, 1 2-7/8" IPC JT, & 2-7/8" TBG W/TBG ANCHOR. SET SN BELOW BOTTOM PERF. RUN GAS ANCHOR, PMP, SUCKER RODS W/T GRADE COUPLINGS. 4. RETURN WELL TO PRODUCTION.

			<del></del>			
14. I hereby certify that the	e foregoing is true and correct. Electronic Submission #24630 verifie For MERIT ENERGY COMI Committed to AFMSS for processing by AR	ANY, s	ent to the Carlsbad			
Name (Printed/Typed)	BEVERLY HATFIELD	Title	AUTHORIZED SIGNATURE			
Signature	(Electronic Submission)	Date	10/29/2003			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved By ALEXIS	C.SWOBODA OCA	Title	PETROLEUM ENGINEER	Date 10/30/2003		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	Carlsbad			
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212 make it a crime for provingly and willfully to make to any department or second of the United						

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

<sup>13.</sup> Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones.

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)