

Submit 3 Copies To Appropriate District

Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised May 08, 2003

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		<b>WELL API NO.</b> 30-015-33007
<b>1. Type of Well:</b> Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		<b>5. Indicate Type of Lease</b> STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
<b>2. Name of Operator</b> MURCHISON OIL & GAS, INC.		<b>6. State Oil &amp; Gas Lease No.</b>
<b>3. Address of Operator</b> 1100 MIRA VISTA BLVD. PLANO, TX. 75093-4698		<b>7. Lease Name or Unit Agreement Name</b> STRONG FEDERAL COM
<b>4. Well Location</b> Unit Letter <u>A</u> : <u>1250</u> feet from the <u>NORTH</u> line and <u>1250</u> feet from the <u>EAST</u> line Section <u>34</u> Township <u>24S</u> Range <u>26E</u> NMPM County <u>EDDY</u>		<b>8. Well Number</b> 3
<b>11. Elevation</b> (Show whether DR, RKB, RT, GR, etc.)		<b>9. OGRID Number</b> 015363
<b>10. Pool name or Wildcat</b> WHITE CITY PENN		

<b>12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data</b>	
<b>NOTICE OF INTENTION TO:</b> PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	<b>SUBSEQUENT REPORT OF:</b> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/> OTHER: <input type="checkbox"/>

**13. Describe proposed or completed operations.** (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Notify NMOCD of running & cementing 7-5/8" casing @ 9:30 AM MST 10/23/03.

Drill 8-3/4" hole to a depth of 8588'. Pick up and run 7-5/8" casing as follows:

	Guide Shoe	2'
1 Jt	7-5/8" P-110 33.04 #/FT SJ-2	40'
	Fioat Collar	2'
39 Jts	7-5/8" P-110 33.04 #/FT SJ-2	1650'
163 Jts	7-5/8" P-110 29.04 #/FT SJ-2	6931'
		8625'

Set casing @ 8588'. Cement with 675 SX 50:50:10 Class H + 5% Salt + .20% R-21 followed with 200 SX Class H + FL-25. Bump plug, plug held. Set casing slips. Nipple up BOP and test to 10,000 PSI, held OK. Trip in hole w/ BHA and 3-1/2" DP. Resume drilling 6-1/2" hole. WOC total of 33 hours.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Michael S. Daugherty TITLE VICE PRESIDENT OPERATIONS DATE 11/4/03

Type or print name MICHAEL S. DAUGHERTY Telephone No. (972) 931-0700

(This space for State use)

APPROVED BY Jim W. Gunn TITLE District Supervisor DATE NOV 12 2003

Conditions of approval, if any: