Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-ARIESIA
FORM APROVED
OMB NO. 1004-0135

EXPIRES: NOVEMBER 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS NUV - 1 2008	5. Lease Serial No.		
* Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals OCD-ARTESIA	NM-77046		
SUBMIT IN TRIPLICATE	o. I malan, Amortos de Massertante		
	7. Unit or CA Agreement Name and No.		
1a. Type of Well OII Well Gas Well Other	8 Well Name and No.		
2. Name of Operator	North Pure Gold 9 Federal 4		
DEVON ENERGY PRODUCTION COMPANY, LP	9. API Well No.		
3. Address and Telephone No.	30-015-27443		
20 North Broadway, Oklahoma City, OK 73102 405-235-3611	10. Field and Pool, or Exploratory		
4 Location of Well (Report location clearly and in accordance with Federal requirements)*	Los Medanos; Delaware		
1980' FNL 660' FWL SEC 9 T23S R31E	12. County or Parish 13. State		
	Eddy NM		
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOR	r, OR OTHER DATA		

				8 Well Name and No.		
2. Name of Operator			North Pure Gold 9 Federal 4			
DEVON ENERGY PRODUC	TON COMPANY, LP			9. API Well No.		
3. Address and Telephone No.			30-015-27443			
20 North Broadway, Oklahoma City, OK 73102 405-235-3611			10. Field and Pool, or Exploratory			
4 Location of Well (Report location clearly and in accordance with Federal requirements)*		Los Medanos; Delaware				
1980' FNL 660' FWL SEC 9	T23S R31E			12. County or Par	rish 13. State	
				Eddy	NM NM	
CHECK	APPROPRIATE BOX(s) TO INI	DICATE NATURE OF NO	TICE, REPORT	, OR OTHER DATA	Α	
TYPE OS SUBMISSION		TYP	E OF ACTION			
Notice of Intent	Acidize	Deepen		n (Start/Resume)	☐ Water Shut-Off	
✓ Subsequent Report	☐ Alter Casing	Fracture Treat New Construction	Reclamaț		☐ Well Integrity	
	Casing Repair Change Plans	Plug and Abandon		rily Abandon	Other Add Pay Brushy Car	avon.
Final Abandonment Notice	Convert to Injection	☐ Plug Back	☐ Water Di	•	Grushy Gar	iyon .
13 Describe Proposed or Completed Operations (deepen directionally or recomplete honzontally, give s the Bond No on file with BLM/BIA Required subsequinterval, a Form 3160-4 shall be filed once testing has determined that the site is ready for final inspection)	ubsurface location and measured and tru ent reports shall be filed within 30 days fo	e vertical depths of all pertinent mollowing completion of the involved	arkers and zones do operations of the	Attach the Bond under whoperation results in a mul	nich the work will be performed or Itiple completion or recompletion i	r provide iπ a new
10/03/08 - 10/10/08 1. MIRU PU. POOH w/rods & p	ump					į
 NU BOP. MIRU WL. NU WL BOP and test. RIH w/gauge ring. Tag @ 8051'. RIH w/4" csg gun. Perforate the following Brushy Canyon intervals, 7710-20' (10 ft, 10 shots) 7726-32' (6 ft, 6 shots) 7748-7824' (76 ft, 76 shots) RIH w/ RBP& set @ 7880' and set pkr @ 7846'. Test to 1500#, good. RU BJ Services to test csg & acidize w/ 9500 g 7 1/2% acid w/ 140 BS. FL w/ 2% KCL. RD BJ. RIse pkr and RBP. POOH. 						
9. RDMO.			AC	CEPTED F	FOR RECORD	
	ACCEPTED FOR REC	ORD		NOV	2 2008	
	NOV 3 - 2008			J-Com		
143	erry Guye, Deputy Field Ins MOCD-District II ART	pector 'ESIA			ID MANAGEMENT FIELD OFFICE	
14. I hereby certify that the foregoing is t	rue and correct			<u></u>		
Signed Dely GB	Name Title	Judy A. Bar Regulatory Ar		Date	10/13/2008	
(This space for Federal or State Office us	e)					
Approved by Conditions of approval, if any:	Title		· · · · · · · · · · · · · · · · · · ·	Date		

*See Instruction on Reverse Side