

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.	30-015-30027
5. Indicate Type of Lease	FEDERAL STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name Parkway Delaware Unit
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other Injection Well		8. Well Number 703
2. Name of Operator St. Mary Land & Exploration Co.	DEC - 8 2008	9. OGRID Number 154903
3. Address of Operator 3300 N. A Street, Bldg. 7, Ste. 200 Midland, TX 79705	OCD-ARTESIA	10. Pool name or Wildcat Parkway; Delaware
4. Well Location Unit Letter I : 2610 feet from the South line and 430 feet from the East line Section 35 Township 19S Range 29E NMPM County Eddy		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3346' RKB		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10/27/08 Notified BLM & OCD of MI, Trip Equip. to location.

10/28/08 RIH w/tbg to spot 25 sxs cmt, pump down SDFD.

10/29/08 Spot 25sxs cmt & 3% CaChl @ 1892', WOC 4 hrs, Tag TOC @ 1849', PUH w/tbg spot 25 sxs class C neat @ 1849' POH w/tbg. SDFN. WOC overnight.

10/30/08 RIH w/tbg, no Tag. RU to pump mix & spot 25 sxs class C cmt 3% CaChl, Witnessed BLM Rep. Terry Wilson, WOC, RIH w/tbg Tag @ 1845', contact BLM Terry Wilson, pump 25 sxs class C cmt., 3% CaChl POH w/tbg, WOC overnight. SDFN.

10/31/08 RIH w/tbg Tag @ 1845', POH w/tbg, contacted BLM Jim Amos, ok'd; RIH w/7" pkr on 2 3/8" tbg & set pkr @ 1450'. RU to pump load backside & mix & sqz 75 sxs class C cmt, 3% CaChl, WOC 4 hrs, Release & POH w/tbg & 7" pkr, remove pkr 7"; RIH w/tbg, Tag TOC @ 1579', POH w/tbg & SI for weekend.

11/3/08 RU WL & RIH w/7" CIBP, set @ 1550', POH RD WL, RIH w/tbg mix & spot 130 sxs class C cmt. 2% CaChl. PUH w/tbg laid down 27 jts, WOC 4 hrs, RIH w/tbg, Tag TOC @ 794'. RU to pump & mix spot 105 sxs cmt. class C. neat. SDFN.

11/4/08 Open well RIH w/tbg. TAG TOC @ 179', POH w/tbg, contact BLM Jim Amos, Ok'd to spot 35 sxs cmt for surface plug. ND BOP & wellhead, RIH w/tbg, 5 jts & spot 35 sxs cmt for surface plug. RDMO.

Cut off wellhead and install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Donna Huddleston TITLE Production Tech DATE 12/04/2008

Type or print name Donna Huddleston E-mail address: dhuddleston@stmaryland.com PHONE: (432)688-1789

For State Use Only

APPROVED BY: Accepted for record TITLE NMOCD DATE 12/8/08
Conditions of Approval (if any):