/	,	
Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office	Energy, Minerals and Natural Resources	June 19, 2008
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	anergy, winicials and Natural Resources	WELL API NO.
District II	OIL CONCEDUATION DIVIGION	30-005-63343
1301 W Grand Ave., Artesia, NW 66210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE S FEE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr, Santa Fe, NM	•	V-5576
87505	ND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	O DRILL OR TO DEEPEN OR PLUG BACK TO A	S K State
DIFFERENT RESERVOIR. USE "APPLICATION		8. Well Number
PROPOSALS)		8. Well Number
1. Type of Well: Oil Well Gas W	/ell Other	
2. Name of Operator	DEC _ 8 2008	9. OGRID Number
Armstrong Energy Corporation 3. Address of Operator	OCD-ARTESIA	001092 10. Pool name or Wildcat
P.O. Box 1973, Roswell, NM 88202-		Foor Ranch
	-1973	Foot Ranch
4. Well Location		
Unit Letter_ C: 660	feet from the <u>NORTH</u> line and <u>1980</u>	feet from theWEST line
Section 11	Township 10 SOUTH Range 26 EAS	ST NMPM CHAVES County
11. I	Elevation (Show whether DR, RKB, RT, GR, etc.	.)
	3871' GR	
12. Check Appro	priate Box to Indicate Nature of Notice,	Report or Other Data
1=V Onton 1-pp10		Troport of Other Data
NOTICE OF INTEN	TION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK 🗍 💢 PLU	G AND ABANDON 🛛 📗 REMEDIAL WOR	RK
TEMPORARILY ABANDON 🔲 CHA	NGE PLANS 🔲 COMMENCE DR	ILLING OPNS. D P AND A
PULL OR ALTER CASING MUL	.TIPLE COMPL CASING/CEMEN	IT JOB
DOWNHOLE COMMINGLE		-
OTH	IER:	OTHER:
of starting any proposed work). S or recompletion. Propose to plug and abandon by: (1) (1) (1) (2) (3) (2) (4) (5) (4) (5) (5) (7) (6) (7) (7) (7) (7) (7) (7) (7) (7) (7) (7	perations. (Clearly state all pertinent details, an EE RULE 1103. For Multiple Completions: A Cutoff and pull 5.5" casing @ 4000', (2) Load lent, (4) Spot plug @ 2312'-2412' w/50sx Class (6) Spot plug 200'-300' w/40sx Class (7); (7) Spot plug 200'	ttach wellbore diagram of proposed completion hole w/ 9.2 PPG mud, (3) Spot a stub plug ss "C", (5) Spot plug @ 974'-1074' w/50sx Set 10sx Class "C" surface plug, (8) Install Dry
TIOIC MARKET.		* 0'-60'
Clean location, rip pad and re-seed.	* TACa	
, , , ,	•	·
		1
	Notify OCD 24 hrs. p	rior .
	To down work dans	Approval Granted providing work
	To any work done.	is complete by $\frac{3}{9}/0$
Spud Date:	Rig Release Date:	
I hereby certify that the information above	is true and complete to the best of my knowledg	ge and helief
		o and coner.
(S) MA	H.	
SIGNATURE /////	TITLE Vice President – Opera	ations DATE 12/02/08
Type or print nameBruce A. Stubbs	E-mail address: bastubbs@z	rianet.com PHONE: (505) 625-2222
For State Use Only	•	
MSH. In	, 	1-1-1-1
APPROVED BY:	TITLE CO	DATE 12/9/U8

