Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103 June 19, 2008
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO.
1301 W. Grand Ave., Artesia, NM 88210 District III	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	30-015-25006 5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		Federal-NMLC060572A
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name Trigg Federal SWD
1. Type of Well: Oil Well Gas Well Other SWD Well		8. Well Number 1
2. Name of Operator Dakota Resources, Inc.	DEC - 8 2008	9. OGRID Number 5691
3. Address of Operator 4914 N. Midkiff Midland, TX 79705		10. Pool name or Wildcat Fenton Delaware NE
4. Well Location		Tonion Belaware 142
Unit Letter L : 1980 feet from the South line and 660 feet from the		
West line Section 7 Township 21S Range 28E NMPM County Eddy		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3168' RKB		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐		
TEMPORARILY ABANDON		
DOWNHOLE COMMINGLE		
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
or recompletion. Repair tubing part at packer.		
11/17/08 MIRU Mesa Rig #218. ND WH, NU BOP. POOH W/ 92 jts. 2 7/8" DUO-Line tbg and 2 7/8" X 2 3/8" Swedge, w/ 2 3/8"		
Collar. RU Hydrostatic testers, PU Nickel plated 5 1/2" AD-1 Watson Packer, 2 7/8" SN (plated) and test tbg in hole to 2500 PSI		
below slips. ND BOP. Strip off WH, replace 5 ½" collar, install WH, packoff WH. RU I & W. Circulate 55 BBL packer fluid. ND WH. Set packer w/ 15K tension. NU WH. Text Packer and Casing to 500 PSI. Hold 15 Min. Well tests good. RU		
Kodiak. Release pressure on the to truck. Remove 2 7/8" sub, install orbit value. NU WH. Lease well ready for injection. RDPU.		
Rig released 11/19/08		
MIT test performed on 12/02/2008. Pressure up to 400#, held for 30 min. Test witnessed by Richard Inge of the OCD.		
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE Robert Long TITLE Foreman DATE 12/4/08		
Type or print name _Rodney Long E-mail address: _rodneyl@dakotares.com PHONE: _432-697-3420 For State Use Only		
APPROVED BY: LUJAN MAS TITLE COMPLIANCE OFFICER DATE 12/16/08 Conditions of Approval (if any):		