at 3 Copies To Appropriate District State of New Mexico Form C-103 Office May 27, 2004 Energy, Minerals and Natural Resources District I WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 District II 30-005-63070 OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease District III 1220 South St. Francis Dr. STATE 🖂 **FEE** 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM 87505 V-2982 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Quincy AMQ State 1. Type of Well: Oil Well Gas Well Other 8. Well Number #13 2. Name of Operator 9. OGRID Number JAN 05 2009 Hanson Operating Company, Inc. 009974 OCD-ARTESIA 3. Address of Operator 10. Pool name or Wildcat P. O. Box 1515, Roswell, NM 88202-1515 Acme San Andres Southeast 4. Well Location feet from the South line and feet from the West line Unit Letter Ν 990 12 Township 8 South Range 27 East Chaves **NMPM** County Section 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3938' GR Pit or Below-grade Tank Application or Closure Depth to Groundwater >100' Distance from nearest fresh water well >2 miles Distance from nearest surface water >10 miles Pit Liner Thickness: Below-Grade Tank: Volume bbls; Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: REMEDIAL WORK ALTERING CASING PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. P AND A \boxtimes TEMPORARILY ABANDON **CHANGE PLANS** PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Plug and abandon well as follows: 11/6/2008: MIRU. Set CIBP at 2050'. Circulate hole with 10# brine with 12.5# per barrel salt water gel. Spot 25 sack plug on 11/7/2008: CIBP. Perforate 4 squeeze holes at 450'. Pump 110 sack cement plug and circulate to surface. Well plugged and abandoned. Witnessed by Phil Hawkins. Clean and remediate location, and set Dry Hole Marker by January 31, 2009. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be equistructed or closed according to NMOCD guidelines 🗵, a general permit 🗌 or an (attached) alternative OCD-approved plan 🔲. TITLE **Production Analyst** DATE 12/31/2008 SIGNATURE Telephone No. 505-622-7330 E-mail address: hanson@dfn.com Type or print name Accepted for record For State Use Only Approved for plugging of well bore oniv. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well-PluggingDATE TITLE APPROVED BY: which may be found at OCD Web Page under Conditions of Approval (if any): Forms, www.cmnrd.state.nm.us/oed.