	FEB - 2 2009
State of New Mexico	Form C-103
Office District I Energy, Minerals and Natural Resource	May 27, 2004
1625 N French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave. Artesia, NM 88210 OIL CONSERVATION DIVISION	J 30-015-30597
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd, Aztec, NM 87410	STATE FEE
District IV 1220 S St Francis Dr , Santa Fe, NM	6. State Oil & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	2410149 1 0 0 0 1 0 1
PROPOSALS.)	8. Well Number
1. Type of Well: Oil Well Gas Well Other	25
2. Name of Operator	9. OGRID Number
Forest Oil Corporation	8041
3. Address of Operator	10. Pool name or Wildcat
707 17 th Street, Suite 3600, Denver, Colorado	S. Livingston Ridge Delaware
4. Well Location	
Unit Letter: D feet from the 660 line and North f	eet and 660 from the West line
Section 12 Township 23S Range 31E	NMPM County Eddy
11. Elevation (Show whether DR, RKB, RT, G.	R, etc.)
Pit or Below-grade Tank Application or Closure	
Pit typeDepth to GroundwaterDistance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volume bb	ls; Construction Material
12. Check Appropriate Box to Indicate Nature of No.	otice. Report or Other Data
	_
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL	_
	E DRILLING OPNS. P AND A
	EMENT JOB
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CE	EMENT JOB
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CE	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: OTHER:	EMENT JOB □ Rod Repair⊠
PULL OR ALTER CASING	EMENT JOB ☐ Rod Repair ☐ ils, and give pertinent dates, including estimated date
PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: OTHER:	EMENT JOB ☐ Rod Repair ☐ ils, and give pertinent dates, including estimated date
PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion.	EMENT JOB ☐ Rod Repair ☐ ils, and give pertinent dates, including estimated date
PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 8-7-08 – MI RUPU POH w/1" body break	Rod Repair ils, and give pertinent dates, including estimated date as: Attach wellbore diagram of proposed completion
PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 8-7-08 – MI RUPU POH w/1" body break 8-8-08 – RIH w/fishing took caught fish, unseated pmp, POH w/rods and pmp. Had to	Rod Repair ils, and give pertinent dates, including estimated date as: Attach wellbore diagram of proposed completion rouble POH due to inverted cups.
PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 8-7-08 – MI RUPU POH w/1" body break 8-8-08 – RIH w/fishing took caught fish, unseated pmp, POH w/rods and pmp. Had t 8-11-08 – WO cups f/pmp. RIH w/2 ½" x 2" x 26' pmp w./1' LS, 2-4 (1") subs, 26K	Rod Repair lils, and give pertinent dates, including estimated date as: Attach wellbore diagram of proposed completion rouble POH due to inverted cups. shear tool, 1-4' (1") sub, 10-1 1/5 sinkerbards, 111-
PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 8-7-08 – MI RUPU POH w/1" body break 8-8-08 – RIH w/fishing took caught fish, unseated pmp, POH w/rods and pmp. Had t 8-11-08 – WO cups f/pmp. RIH w/2 ½" x 2" x 26' pmp w./1' LS, 2-4 (1") subs, 26K 1" steel ros, 121-1 ¼ FG rods, 2-3' (1 ¼ FG) subs, 1 ½ x 26 pr w/16' liner. Hung we	Rod Repair lils, and give pertinent dates, including estimated date as: Attach wellbore diagram of proposed completion rouble POH due to inverted cups. shear tool, 1-4' (1") sub, 10-1 1/5 sinkerbards, 111-
PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 8-7-08 – MI RUPU POH w/1" body break 8-8-08 – RIH w/fishing took caught fish, unseated pmp, POH w/rods and pmp. Had t 8-11-08 – WO cups f/pmp. RIH w/2 ½" x 2" x 26' pmp w./1' LS, 2-4 (1") subs, 26K 1" steel ros, 121-1 ¼ FG rods, 2-3' (1 ¼ FG) subs, 1 ½ x 26 pr w/16' liner. Hung we w/pmp.	Rod Repair ils, and give pertinent dates, including estimated date as: Attach wellbore diagram of proposed completion rouble POH due to inverted cups. shear tool, 1-4' (1") sub, 10-1 1/5 sinkerbards, 111-11 on. RU pmp truck. Loaded tbg and press to 500 psi
PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 8-7-08 – MI RUPU POH w/1" body break 8-8-08 – RIH w/fishing took caught fish, unseated pmp, POH w/rods and pmp. Had t 8-11-08 – WO cups f/pmp. RIH w/2 ½" x 2" x 26' pmp w./1' LS, 2-4 (1") subs, 26K 1" steel ros, 121-1 ¼ FG rods, 2-3' (1 ¼ FG) subs, 1 ½ x 26 pr w/16' liner. Hung we w/pmp.	Rod Repair lils, and give pertinent dates, including estimated date as: Attach wellbore diagram of proposed completion rouble POH due to inverted cups. shear tool, 1-4' (1") sub, 10-1 1/5 sinkerbards, 111-
PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 8-7-08 – MI RUPU POH w/1" body break 8-8-08 – RIH w/fishing took caught fish, unseated pmp, POH w/rods and pmp. Had t 8-11-08 – WO cups f/pmp. RIH w/2 ½" x 2" x 26' pmp w./1' LS, 2-4 (1") subs, 26K 1" steel ros, 121-1 ¼ FG rods, 2-3' (1 ¼ FG) subs, 1 ½ x 26 pr w/16' liner. Hung we w/pmp.	Rod Repair ils, and give pertinent dates, including estimated date as: Attach wellbore diagram of proposed completion rouble POH due to inverted cups. shear tool, 1-4' (1") sub, 10-1 1/5 sinkerbards, 111-11 on. RU pmp truck. Loaded tbg and press to 500 psi
PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 8-7-08 – MI RUPU POH w/1" body break 8-8-08 – RIH w/fishing took caught fish, unseated pmp, POH w/rods and pmp. Had t 8-11-08 – WO cups f/pmp. RIH w/2 ½" x 2" x 26' pmp w./1' LS, 2-4 (1") subs, 26K 1" steel ros, 121-1 ¼ FG rods, 2-3' (1 ¼ FG) subs, 1 ½ x 26 pr w/16' liner. Hung we w/pmp.	Rod Repair lils, and give pertinent dates, including estimated date as: Attach wellbore diagram of proposed completion rouble POH due to inverted cups. shear tool, 1-4' (1") sub, 10-1 1/5 sinkerbards, 111-cll on. RU pmp truck. Loaded tbg and press to 500 psi
PULL OR ALTER CASING	Rod Repair ils, and give pertinent dates, including estimated date as: Attach wellbore diagram of proposed completion rouble POH due to inverted cups. shear tool, 1-4' (1") sub, 10-1 1/5 sinkerbards, 111- ill on. RU pmp truck. Loaded tbg and press to 500 psi EPTED FOR RECORD
PULL OR ALTER CASING	Rod Repair ils, and give pertinent dates, including estimated date as: Attach wellbore diagram of proposed completion rouble POH due to inverted cups. shear tool, 1-4' (1") sub, 10-1 1/5 sinkerbards, 111- ill on. RU pmp truck. Loaded tbg and press to 500 psi EPTED FOR RECORD
PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 8-7-08 – MI RUPU POH w/1" body break 8-8-08 – RIH w/fishing took caught fish, unseated pmp, POH w/rods and pmp. Had t 8-11-08 – WO cups f/pmp. RIH w/2 ½" x 2" x 26' pmp w./1' LS, 2-4 (1") subs, 26K 1" steel ros, 121-1 ¼ FG rods, 2-3' (1 ¼ FG) subs, 1 ½ x 26 pr w/16' liner. Hung we w/pmp. ACC	Rod Repair ils, and give pertinent dates, including estimated date as: Attach wellbore diagram of proposed completion rouble POH due to inverted cups. shear tool, 1-4' (1") sub, 10-1 1/5 sinkerbards, 111-bil on. RU pmp truck. Loaded tbg and press to 500 psi EPTED FOR RECORD FEB 0.2.2009 Guye, Deputy Field Inspector CD-District II ARTESIA
PULL OR ALTER CASING	Rod Repair ils, and give pertinent dates, including estimated date as: Attach wellbore diagram of proposed completion rouble POH due to inverted cups. shear tool, 1-4' (1") sub, 10-1 1/5 sinkerbards, 111-bil on. RU pmp truck. Loaded tbg and press to 500 psi CEPTED FOR RECORD FEB 0.2.2009 Guye, Deputy Field Inspector CD-District II ARTESIA wledge and belief. I further certify that any pit or below-
PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 8-7-08 – MI RUPU POH w/1" body break 8-8-08 – RIH w/fishing took caught fish, unseated pmp, POH w/rods and pmp. Had t 8-11-08 – WO cups f/pmp. RIH w/2 ½" x 2" x 26' pmp w./1' LS, 2-4 (1") subs, 26K 1" steel ros, 121-1 ¼ FG rods, 2-3' (1 ¼ FG) subs, 1 ½ x 26 pr w/16' liner. Hung we w/pmp. ACC	Rod Repair ils, and give pertinent dates, including estimated date as: Attach wellbore diagram of proposed completion rouble POH due to inverted cups. shear tool, 1-4' (1") sub, 10-1 1/5 sinkerbards, 111-bil on. RU pmp truck. Loaded tbg and press to 500 psi CEPTED FOR RECORD FEB 0.2.2009 Guye, Deputy Field Inspector CD-District II ARTESIA wledge and belief. I further certify that any pit or below-
OTHER: Is a Casing/Cf of the constructed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 8-7-08 − MI RUPU POH w/1" body break 8-8-08 − RIH w/fishing took caught fish, unseated pmp, POH w/rods and pmp. Had the self-took of the country o	Rod Repair ils, and give pertinent dates, including estimated date as: Attach wellbore diagram of proposed completion rouble POH due to inverted cups. shear tool, 1-4' (1") sub, 10-1 1/5 sinkerbards, 111-bil on. RU pmp truck. Loaded tbg and press to 500 psi CEPTED FOR RECORD FEB 0.2.2009 Guye, Deputy Field Inspector CD-District II ARTESIA wledge and belief. I further certify that any pit or belowmit or an (attached) alternative OCD-approved plan .
PULL OR ALTER CASING	Rod Repair ils, and give pertinent dates, including estimated date as: Attach wellbore diagram of proposed completion rouble POH due to inverted cups. shear tool, 1-4' (1") sub, 10-1 1/5 sinkerbards, 111-bil on. RU pmp truck. Loaded tbg and press to 500 psi CEPTED FOR RECORD FEB 0.2.2009 Guye, Deputy Field Inspector CD-District II ARTESIA wledge and belief. I further certify that any pit or belowmit or an (attached) alternative OCD-approved plan .

TITLE

DATE

Type or print name
For State Use Only

APPROVED BY:____Conditions of Approval (if any):