Approved by

Conditions of approved it any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease

which would entitle the applicant to conduct operations thereon.

Form 3160-5 FORM APPROVED UNITED STATES OMB No. 1004-0135 Expires November 30, 2000 (August 1999) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT 5 Lease Scrial No. LC-060524 **SUNDRY NOTICES AND REPORTS ON WELLS** Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side 1. Type of Well ☐ Oil Well ☐ Gas Well ☒ Other WATER INJECTION 8. Well Name and No. FEDERAL JJ 2 CBS OPERATING CORP. API Well No. 3a. Address P O BOX 2236 30-015-20314 3b. Phone No. (include area code) MIDLAND TX 79702 432/685-0878 10. Field and Pool, or Exploratory Area SQUARE LAKE GB SA 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State 1980' FSL & 660' FWL UL L SEC. 3 T17S R30E EDDY, NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION ☐ Acidize Deepen ☐ Production (Start/Resume) Water Shut-Off Notice of Intent Alter Casing ☐ Well Integrity Fracture Treat Reclamation Casing Repair New Construction Recomplete Other Subsequent Report Plug and Abandon Change Plans Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back ☐ Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 1. MI & RU. Install BOP. Dig & line pit. Move in work string. 2. Tag CIBP @ 2761'. Spot 25 sx @ 2761-2531'. 3. Circulate 9.5# mud. 4. Perforate @ 1315', 5. Squeeze 35 sx @ 1315-1215' & tag. 6. Perforate @ 488'. 7. Squeeze 40 sx @ 488-388' & tag. 8. Spot 10 sx at surface. Cut off wellhead, anchors & cover pit. 9. Install dry hole marker. 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) M. A. SIRGO, Title **ENGINEER** Date NOVEMBER 25, 2003 THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Title

Date



M A SIRGO

Malling Address: P. O. Diawer 130 Aileshi: New Mexico 88211-0130 Office Location: 132829 #1 Envirigion Flyry Laco Hills, Hev. Mexico BB255 00 (505) 577-2411 Fax. (505) 677-2414

