

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.	30-015-32422
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	NM 648
7. Lease Name or Unit Agreement Name:	STATE 25
8. Well No.	1
9. Pool name or Wildcat	WILDCAT

<p><b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>	
<p>1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other</p>	
<p>2. Name of Operator PAR MINERALS CORPORATION</p>	
<p>3. Address of Operator 509 MARKET ST STE 300, SHREVEPORT, LOUISIANA 71101</p>	
<p>4. Well Location Unit Letter <u>F</u>: <u>2310</u> feet from the <u>NORTH</u> line and <u>1980</u> feet from the <u>WEST</u> line Section <u>25</u> Township <u>18S</u> Range <u>27E</u> NMPM County <u>EDDY</u></p>	
<p>10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3559 GR</p>	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Plug and Abandon: Set and cmt. plugs @ 10,300, 100' plug  
9,900, 100' plug  
7,500, 100' plug  
5,900, 100' plug  
4,000, 100' plug  
2,430, 100' plug tag @ 2320'  
660, 400' plug tag @ 255'  
Surface plug 0 - 60'

Well P&A on Nov. 02, 2002

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roger Hooper TITLE REGULATORY DATE 11/19/02

Type or print name ROGER HOOPER

(This space for State use)

Telephone No. 318-221-6156

APPROVED BY

Conditions of approval, if any:

TITLE

APPROVED DEC  
DATE

4 2003