MAR 3 0 2009

OCD-ARTESIA FORM APPROVED

Form 3160- 5 (August 2007)

2/2/09 - RIH w/ 178 jts 2 7/8" J55 tbg.

UNITED STATES DEPARTMENT OF THE INTERIOR

OMB No. 1004, 0137

(Migusi, 2007)	DEI ARTMENT OF	THE INTERIOR			OMD 10 1004- 0137	
	BUREAU OF LANI	MANAGEMENT		}	Expires July 31, 2010	
SUNDRY NOTICES AND REPORTS ON WELLS			'ELLS	5 I case Senal No NMNM67979		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6 If Indian, Al	lottee, or Tribe Name	
				7 1511	A. A. w No	
	TRIPLICATE - Other In:	structions on page 2		/ If Unit of C/	A Agreement Name and/or No	
Type of Well Gas Well Other				8 Well Name	and No	
2 Name of Operator				Irish Whiskey Federal #3H		
Marbob Energy Corporation				9 API Well No		
3a Address 3b Phone No (mclude area code)					20.016.26710	
PO B	(575) 7	(575) 748-3303		30-015-35710		
Artesia, NM 88211-0227				10 Field and Pool, or Exploratory Area Herradura Bend; Delaware, East		
4 Location of Well (Footage, Sec., T., R., M., or, Survey Description)					ra Bend; Delaware, El	ast
430 FSL 1650 FWL, Sec. 26-T22S-R28E, Unit N						
	DDL LEED DOVLOVED IN ID	ICAMPANAMUNTO ON	NOMICE BER		Eddy County, NM	
12. CHECK APPRO	PRIATE BOX(S) TO IND	ICATE NATURE OF	NOTICE, REPO	ORT, OR OTHE	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize	Deepen	Production	(Start/ Resume)	Water Shut-off	
	Altering Casing	Fracture Treat	Reclamation	n	Well Integrity	
X Subsequent Report	Casing Repair	New Construction	X Recomplete	:	Other	
	Change Plans	Plug and Abandon	Temporanly	y Abandon		
Final Abandonment Notice	Convert to Injection	X Plug Back	Water Disp			
Attach the Bond under which the tollowing completion of the invo	ectionally or recomplete horizont e work will performed or provide alved operations. If the operation al Abandonment Notice shall be	ally, give subsurface locations the Bond No on file with results in a multiple comp	ons and measured a the BLM/ BIA R detion or recompletion	nd true vertical de equired subsequent on in a new interva	pths or pertinent markers and reports shall be filed within I al, a Form 3160-4 shall be file	l sands 30 days ed once
Recompleted in the Del	aware zone as follows:					
1/20/09 - POOH w/ rod	s & tbg.					
1/21/09 - Set CBP @ 82	250'. Load & test to 353	7# - OK.				
	vare (2) @ 7353' - 7950'					
	gal NE Fe 15% Hcl acid	•				
	50'. Test to 3500#, OK		(3) @ 6350' -	6950' (16 sho	ts).	
_	gal NE Fe 15% HCl aci		. , _ = = =	(•	

14 I hereby certify that the foregoing is true and correct Name (Proted Typed) Title Diana J. Briggs Signature Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE MAR 2 8 2009 Approved by Conditions of approval, it any are attached. Approval of this notice does not warrant or Certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212 make it a crime for any person knowingly and willfully to the RADY OF THE AND TITLE States any talse, hetitious or fraudulent statements or representations as to any matter within its jurisdiction CARI SRAD FIELD DEFICE (Instructions on page 2)

2/3/09 - RIH w/ rods & pump. Test pump to 300# - good. Return well to production. Producing interval is 6350'-6950'.