Submit 3 Copies To Appropriate District Office District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 South First, Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM	State of Ne Emergy, Minerals and OIL CONSERVA 1220 South S Santa Fe, N	d Natural Resource TION DIVISION t. Francis Dr.	WELL API NO 30-005-635 5. Indicate Ty STATE	pe of Lease
(DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.) 1. Type of Well: Oil Well Gas Well X 2. Name of Operator Yates Petroleum Corpor 3. Address of Operator	Other	OR PLUG BACK TO A	7. Lease Name Window AV 7. Well No. #1 8. Pool name	e or Unit Agreement Name: VT State or Wildcat unated Wolfcamp
4. Well Location		· OCh	# / / / / / / / / / / / / / / / / / / /	
Unit Letter <u>E: 198</u>	0 feet from the North	h line and 66	feet from the	West line
	10. Elevation (Show when	3839' GR	FR, etc.)	IVES County
	ppropriate Box to Indic			
NOTICE OF IN			SUBSEQUENT F	REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON [REMEDIAL	WORK	CASING X
TEMPORARILY ABANDON	CHANGE PLANS [COMMENCE	E DRILLING OPNS. [PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION [CASING TE		
OTHER:	[OTHER: Pe	erforate, acidize	X
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 4/3/01 – Run CBL. PBTD at 6380', and TOC at 4140'. 4/5/01 – Perforate Ordovician 6068-6088', 80 holes, .42" holes. Acidize perfs 6068-6088' with 300 gals 15% IC HCL. 4/9/01 – Acidized perfs 6068-6088' with 2000 gals 20% FE HCL. 4/11/01 – Set cement retainer at 6060'. 4/12/01 – Cement squeezed perfs 6068-6088' with 50 sxs Class C neat + 50 sxs C + .2% FL52. Squeezed to 2100#. 4/13/01 – Perforate Penn sands 5985-6000', 90 holes and 6030-6046', 96 holes, .42". Acidized with 3000 gals 7.5% NEFE acid. 4/18/01 – Set CIBP at 5900'. Perforate Wolfcamp 5560-5570' with 22 holes, .42". 4/19/01 – Acidize perfs 5560-5570' with 1000 gals 15% NEFE acid. 4/23/01 – Rig down and move out. Waiting on further orders.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE Signature	2eTITLE	Engineering 1	[echnician DATE	January 18, 2002
Type or print name Susan Herpin Telephone No. 505-748-1471				
(This space for State use) APPPROVED BY Conditions of approval, if				MAN 31 2002

1 Sent 3/1/02 FOR RECORD ONLY