

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

JUN 26 2009

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



WELL API NO. 30-015-21807
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-5313
7. Lease Name or Unit Agreement Name: Empire Abo Unit 'L'
8. Well Number 132
9. OGRID Number 00778
10. Pool name or Wildcat Empire Abo

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3536' GR
2. Name of Operator BP America Production Company	
3. Address of Operator P.O. Box 1089 Eunice NM 88231	
4. Well Location Unit Letter <u>M</u> : <u>275</u> feet from the <u>S</u> line and <u>1243</u> feet from the <u>W</u> line Section <u>2</u> Township <u>18S</u> Range <u>27E</u> NMPM County <u>Eddy</u>	
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/> Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6/16/09: MIRU. PUMP 50 BBL FRESH WATER KILL WELL. RELEASE PACKER POH.  
6/17/09: POH W/ PACKER LD 179 JOINTS OF 2 3/8 EUE 4.7# TBG BOTTOM JOINT HAD A HOLE IN IT.  
PICK UP 2 3/8 WORK STRING RIH W/ CIBP SET CIBP @ 5843' LOAD CSG TEST TO 500 PSI GOOD TEST.  
SPOT 25 SKS OF CLASS C ON CIBP @ 5843'-5613' EST TOP CMT. POH TO 4318'.  
6/18/09: CIRC 9.5 40 VIS PLUG MUD 130 BBL TO SURFACE. POH TO 4314 PUMP 25 SKS OF CLASS C  
CMT. DISPLACE 15 BBL EST TOP CMT @ 4074. POH TO 3412 PUMP 25 SKS OF CLASS C CMT DISPLACE  
11.5 BBL EST TOP CMT @ 3172. POH TO SURF LD SETTING TOOL PU SLOT SUB AND BULL PLUG RIH TO 1432.  
Continued on page 2.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Barry C. Price TITLE Area Operations Team Lead DATE 6/23/09  
E-mail address: barry.price@bp.com  
Type or print name Barry C. Price Telephone No. 575-394-1648

For State Use Only

APPROVED BY [Signature] TITLE \_\_\_\_\_  
Conditions of Approval, if any:

Approved for plugging of well bore only.  
Liability under bond is retained pending receipt  
of C-103 (Subsequent Report of Well Plugging)  
which may be found at OCD Web Page under  
Forms. [www.emnrd.state.nm.us/oed](http://www.emnrd.state.nm.us/oed).

DATE 6/26/09

Form C-103  
Empire Abo Unit L-132  
30-015-21807  
Continued from Page 1

6/19/09: RIH TAG TOP OF GLORIETTA @ 3174 ' POH TO 1500' LD TUBING PUMP  
SURFACE PLUG USING 150 SKS OF CLASS C CMT TO SURFACE WITNESSED BY  
PHIL HAWKINS NMOC. POH TO SURFACE LD TUBING PUMP TOP OFF PLUG AT  
SURFACE

6/22/09: DIG OUT AROUND WELLHEAD. CUT OFF ALL ANCHORS AND WELL HEAD,  
WELD IN PLATE, 1" NIPPLE & VALVE, DRY HOLE MARKER, BACKFILL AND LEVEL  
LOCATION.