

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTJUN 23 2009
OCD-ARTESIA
FORM APPROVED
B No. 1004-0137
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

1 Type of Well
☐ Oil Well ☒ Gas Well ☐ Other2. Name of Operator
BOPCO, L.P.

3a Address

P.O. Box 2760 Midland TX 79702

3b. Phone No. (include area code)

(432)683-2277

4. Location of Well (Footage, Sec, T., R., M., or Survey Description)

UL L, 2380' FSL, 660' FWL, SEC. 11, T21S, R28E

5. Lease Serial No

NMLC063516

6 If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8 Well Name and No.

Big Eddy Unit #166

9 API Well No

30-015-36019

10 Field and Pool, or Exploratory Area

Wildcat (Delaware)

11 County or Parish, State

Eddy


NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input checked="" type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input checked="" type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other Permanently
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	zone abandon
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	Atoka formation

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

BOPCO, LP respectfully requests permission to permanently abandon the Atoka formation @ 11,418'-11,529' by POOH with retrievable packer assembly and tubing and setting a CIBP @ 11,408' and 35' Class H cement on top. The Delaware will be perforated from 5,996'-6,250' OA and fracture stimulated after inflow performance is established.

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

*Contact this office prior to Plug Back @ 575-361-2822

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Valerie Truax

Title Regulatory Admin Assistant

Signature

Date 06/10/2009

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

WZ

BOPCO, L.P.
NMLC063516: Big Eddy Unit 166
2380' FSL & 660' FWL, Sec. 11, T21S-R28E
Eddy County, New Mexico

RE: Plug Back from Atoka to Delaware

1. No record of plugging the Upper Morrow from 12055'-12213'. Set CIBP plus 35' Class H cement across the top of the Morrow formation @ 11756'.
2. Set CIBP plus 35' Class H cement as specified in Sundry Notice.
3. Suggest plugging the well back to the Delaware, or you will have to go back when plugging the well out. Plugs would be as follows:
 - Spot a 190' (25 sack minimum Class H) plug across the top of Wolfcamp (9798') from 9893'-9703'.
 - Spot a 160' (25 sack minimum) plug across the top of Bone Spring (6271') from 6351'-6191'.

If you have any questions, please contact James A. Amos @ 575-234-5909.