

District I  
1025 N French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

JUL 14 2009

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company – Marbob Energy Corporation 14049	Contact Rand French
Address – P.O. Box 227, Artesia, NM 88211-0227	Telephone No. 575-748-3303
Facility Name – Panagra Com #1	Facility Type – Oil well/Tank Battery

Surface Owner - Private - city of Carlsbad	Mineral Owner – Federal	Lease No.
--	-------------------------	-----------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	11	23S	26E	990	North	1980	East	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release - Fire caused by lightning	Volume of Release: estimated 18 barrels	Volume Recovered: 0
Source of Release: Tank Battery	Date and Hour of Occurrence – night or 7/7/09	Date and Hour of Discovery: 0630 Hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - Artesia District Office	
By Whom? Rand French	Date and Hour 7/7/09 0830 hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

Describe Cause of Problem and Remedial Action Taken.\* Monday evening or Tuesday morning lightning struck the tank battery and fiberglass water tank on the above mentioned well. Fluid levels were checked the day before with an estimated 18-20 barrels of water and 9-10 barrels of oil at the time of fire. All of the oil stayed in the steel tank and burned up. With the significant rainfall it is difficult to determine how much (if any) water ran off the location.. Clean up of the tank batteries began on 7/7/09.

Describe Area Affected and Cleanup Action Taken.\*

Most if not all of the fluids stayed on location. Other than removal of tank batteries and some soil excavation little clean up has been done. Soil samples will be completed and once data is reviewed an agreed upon clean up will be conducted.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rand French</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: RAND FRENCH	Signed By <i>Mike Bratcher</i> Approved by District Supervisor:	
Title: Biologist	Approval Date: JUL 14 2009	Expiration Date:
E-mail Address: wildlife@marbob.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/13/09 Phone: 748-3303		

\* Attach Additional Sheets If Necessary

pMLB 07195-54924

REMEDATION per OCD Rules and  
Guidelines. **SUBMIT REMEDIATION**  
PROPOSAL BY: 8/5/09

2RP-322